

**PM Inspection Schedule**

School	Portable Number	Portables on Site	Round 97 Inspection Date	ARCADIS Inspector	Proposed Round 98 Inspection Date	Comments from Round 97 Inspection
Anne J. MacArthur P.S.	HB 026	10	11-Apr-16	J. Jones	04-Jul-16	<i>N.S.M.O.M.O.</i>
	HB 071		11-Apr-16	J. Jones	04-Jul-16	<i>Exterior caulking degraded at windows and door.</i>
	HBL 202		11-Apr-16	J. Jones	04-Jul-16	<i>N.S.M.O.M.O.</i>
	HBL 203		11-Apr-16	J. Jones	04-Jul-16	<i>N.S.M.O.M.O.</i>
	HBL 204		11-Apr-16	J. Jones	04-Jul-16	<i>N.S.M.O.M.O.</i>
	HBL 205		11-Apr-16	J. Jones	04-Jul-16	<i>N.S.M.O.M.O.</i>
	HBL 214		11-Apr-16	J. Jones	04-Jul-16	<i>N.S.M.O.M.O.</i>
	HBL 215		11-Apr-16	J. Jones	04-Jul-16	<i>N.S.M.O.M.O.</i>
	HBL 232		11-Apr-16	J. Jones	04-Jul-16	<i>N.S.M.O.M.O.</i>
	HBL 233		11-Apr-16	J. Jones	04-Jul-16	<i>N.S.M.O.M.O.</i>
Boyne P.S.	HBL 251	6	22-Apr-16	J. Jones	11-Jul-16	<i>N.S.M.O.M.O.</i>
	HB 015		22-Apr-16	J. Jones	11-Jul-16	<i>N.S.M.O.M.O.</i>
	HB 152		22-Apr-16	J. Jones	11-Jul-16	<i>N.S.M.O.M.O.</i>
	HBL 253		22-Apr-16	J. Jones	11-Jul-16	<i>N.S.M.O.M.O.</i>
	HBL 252		22-Apr-16	J. Jones	11-Jul-16	<i>N.S.M.O.M.O.</i>
	HBL 254		22-Apr-16	J. Jones	11-Jul-16	<i>N.S.M.O.M.O.</i>
Brookville P.S.	HBL 201	1	16-May-16	C. Jagarnauth	10-Aug-16	<i>N.S.M.O.M.O.</i>
Bruce Trail P.S.	HB 046	13	12-May-16	C. Jagarnauth	7-Jul-16	<i>N.S.M.O.M.O.</i>
	HB 062		12-May-16	C. Jagarnauth	7-Jul-16	<i>N.S.M.O.M.O.</i>
	HB 075		12-May-16	C. Jagarnauth	7-Jul-16	<i>Exterior caulking degraded at both windows. Vinyl floor tiles (~4) damaged throughout.</i>
	HB 103		12-May-16	C. Jagarnauth	7-Jul-16	<i>N.S.M.O.M.O.</i>
	HB 110		12-May-16	C. Jagarnauth	7-Jul-16	<i>N.S.M.O.M.O.</i>
	HB 114		12-May-16	C. Jagarnauth	7-Jul-16	<i>N.S.M.O.M.O.</i>
	HB 115		12-May-16	C. Jagarnauth	7-Jul-16	<i>N.S.M.O.M.O.</i>
	HB 149		12-May-16	C. Jagarnauth	7-Jul-16	<i>Downspout damaged at rear elevation.</i>
	HBL 105		12-May-16	C. Jagarnauth	7-Jul-16	<i>N.S.M.O.M.O.</i>
	HBL 228		12-May-16	C. Jagarnauth	7-Jul-16	<i>N.S.M.O.M.O.</i>
	HBL 229		12-May-16	C. Jagarnauth	7-Jul-16	<i>N.S.M.O.M.O.</i>
	HBL 230		12-May-16	C. Jagarnauth	7-Jul-16	<i>N.S.M.O.M.O.</i>
	HBL 231		12-May-16	C. Jagarnauth	7-Jul-16	<i>N.S.M.O.M.O.</i>
Chris Hadfield P.S.	RM A1	12	16-May-16	C. Jagarnauth	10-Aug-16	<i>N.S.M.O.M.O.</i>
	RM A2		16-May-16	C. Jagarnauth	10-Aug-16	<i>N.S.M.O.M.O.</i>
	RM A3		16-May-16	C. Jagarnauth	10-Aug-16	<i>N.S.M.O.M.O.</i>
	RM A4		16-May-16	C. Jagarnauth	10-Aug-16	<i>N.S.M.O.M.O.</i>
	RM A5		16-May-16	C. Jagarnauth	10-Aug-16	<i>N.S.M.O.M.O.</i>
	RM A6		16-May-16	C. Jagarnauth	10-Aug-16	<i>N.S.M.O.M.O.</i>
	RM A7		16-May-16	C. Jagarnauth	10-Aug-16	<i>N.S.M.O.M.O.</i>
	RM A8		16-May-16	C. Jagarnauth	10-Aug-16	<i>N.S.M.O.M.O.</i>
	RM A9		16-May-16	C. Jagarnauth	10-Aug-16	<i>N.S.M.O.M.O.</i>
	RM A10		16-May-16	C. Jagarnauth	10-Aug-16	<i>N.S.M.O.M.O.</i>
	RM A11		16-May-16	C. Jagarnauth	10-Aug-16	<i>N.S.M.O.M.O.</i>
	HBL 106		16-May-16	C. Jagarnauth	10-Aug-16	<i>Screw holes at left and rear elevation.</i>
Craig Kielburger S.S.	HBL 084	18	03-May-16	C. Jagarnauth	17-Aug-16	<i>N.S.M.O.M.O.</i>
	HBL 005		03-May-16	C. Jagarnauth	17-Aug-16	<i>N.S.M.O.M.O.</i>
	HB 100		03-May-16	C. Jagarnauth	17-Aug-16	<i>N.S.M.O.M.O.</i>
	HB 135		03-May-16	C. Jagarnauth	17-Aug-16	<i>N.S.M.O.M.O.</i>
	HB 056		03-May-16	C. Jagarnauth	17-Aug-16	<i>N.S.M.O.M.O.</i>

	HB 203		03-May-16	C. Jagarnauth	17-Aug-16	<i>Holes (1/4') observed underneath air-conditioner unit.</i>
	HB 045		03-May-16	C. Jagarnauth	17-Aug-16	<i>N.S.M.O.M.O.</i>
	HB 038		03-May-16	C. Jagarnauth	17-Aug-16	<i>Edge flashing damaged at front elevation leaving sharp edge.</i>
	HBL 80		03-May-16	C. Jagarnauth	17-Aug-16	<i>N.S.M.O.M.O.</i>
	HB 090		03-May-16	C. Jagarnauth	17-Aug-16	<i>N.S.M.O.M.O.</i>
	HB 091		03-May-16	C. Jagarnauth	17-Aug-16	<i>N.S.M.O.M.O.</i>
	HB 057		03-May-16	C. Jagarnauth	17-Aug-16	<i>Screw holes observed at front cladding.</i>
	HB 143		03-May-16	C. Jagarnauth	17-Aug-16	<i>N.S.M.O.M.O.</i>
	HB 133		03-May-16	C. Jagarnauth	17-Aug-16	<i>N.S.M.O.M.O.</i>
	HB 134		03-May-16	C. Jagarnauth	17-Aug-16	<i>N.S.M.O.M.O.</i>
	HB 073		03-May-16	C. Jagarnauth	17-Aug-16	<i>N.S.M.O.M.O.</i>
	HB 125		03-May-16	C. Jagarnauth	17-Aug-16	<i>N.S.M.O.M.O.</i>
	HB 113		03-May-16	C. Jagarnauth	17-Aug-16	<i>N.S.M.O.M.O.</i>
Escarpment View P.S.	HBL 103	11	25-Apr-16	J. Jones	12-Jul-16	<i>N.S.M.O.M.O.</i>
	HB 005		25-Apr-16	J. Jones	12-Jul-16	<i>Exterior caulking degraded at door.</i>
	HB 089		25-Apr-16	J. Jones	12-Jul-16	<i>N.S.M.O.M.O.</i>
	HB 144		25-Apr-16	J. Jones	12-Jul-16	<i>N.S.M.O.M.O.</i>
	HBL 081		25-Apr-16	J. Jones	12-Jul-16	<i>N.S.M.O.M.O.</i>
	HBL 082		25-Apr-16	J. Jones	12-Jul-16	<i>N.S.M.O.M.O.</i>
	HBL 088		25-Apr-16	J. Jones	12-Jul-16	<i>N.S.M.O.M.O.</i>
	HBL 090		25-Apr-16	J. Jones	12-Jul-16	<i>N.S.M.O.M.O.</i>
	HBL 091		25-Apr-16	J. Jones	12-Jul-16	<i>Broken downspout at front elevation.</i>
	HBL 104		25-Apr-16	J. Jones	12-Jul-16	<i>N.S.M.O.M.O.</i>
	HBL 089		25-Apr-16	J. Jones	12-Jul-16	<i>N.S.M.O.M.O.</i>
E.W. Foster P.S.	HB 086	5	11-May-16	C. Jagarnauth	18-Aug-16	<i>Screw holes observed in metal cladding at right elevation.</i>
	HB 129		11-May-16	C. Jagarnauth	18-Aug-16	<i>N.S.M.O.M.O.</i>
	HB 160		11-May-16	C. Jagarnauth	18-Aug-16	<i>N.S.M.O.M.O.</i>
	HB 180		11-May-16	C. Jagarnauth	18-Aug-16	<i>N.S.M.O.M.O.</i>
	HB 189		11-May-16	C. Jagarnauth	18-Aug-16	<i>Exterior caulking missing at downspout.</i>
Gardiner P.S.	HBL 207	2	26-Apr-16	R. Farnsworth	6-Jul-16	<i>Conduit damaged right side of portable.</i>
	HBL 212		26-Apr-16	R. Farnsworth	6-Jul-16	<i>N.S.M.O.M.O.</i>
Glen Williams P.S.	HB 178	2	26-Apr-16	R. Farnsworth	6-Jul-16	<i>N.S.M.O.M.O.</i>
	HB184		26-Apr-16	R. Farnsworth	6-Jul-16	<i>Stained ceiling tile observed . No moisture or mould observed in ceiling space above.</i>
Hawthorne Village P.S.	HB 013	22	27-Apr-16	D.Kellyman	20-Jul-16	<i>N.S.M.O.M.O.</i>
	HB 034		27-Apr-16	D.Kellyman	20-Jul-16	<i>N.S.M.O.M.O.</i>
	HB 035		27-Apr-16	D.Kellyman	20-Jul-16	<i>Exterior caulking degraded at window.</i>
	HB 036		27-Apr-16	D.Kellyman	20-Jul-16	<i>N.S.M.O.M.O.</i>
	HB 136		27-Apr-16	D.Kellyman	20-Jul-16	<i>Roof edge flashing missing at left elevation. Skirting damaged at left elevation.</i>
	HB 155		27-Apr-16	D.Kellyman	20-Jul-16	<i>N.S.M.O.M.O.</i>
	HB 162		27-Apr-16	D.Kellyman	20-Jul-16	<i>N.S.M.O.M.O.</i>
	RM 101		28-Apr-16	D.Kellyman	20-Jul-16	<i>N.S.M.O.M.O.</i>
	RM 102		28-Apr-16	D.Kellyman	20-Jul-16	<i>N.S.M.O.M.O.</i>
	RM 103		28-Apr-16	D.Kellyman	20-Jul-16	<i>N.S.M.O.M.O.</i>
	RM 104		28-Apr-16	D.Kellyman	20-Jul-16	<i>N.S.M.O.M.O.</i>
	RM 105		28-Apr-16	D.Kellyman	20-Jul-16	<i>N.S.M.O.M.O.</i>
	RM 301		28-Apr-16	D.Kellyman	20-Jul-16	<i>N.S.M.O.M.O.</i>
	RM 302		28-Apr-16	D.Kellyman	20-Jul-16	<i>N.S.M.O.M.O.</i>
	RM 303		28-Apr-16	D.Kellyman	20-Jul-16	<i>N.S.M.O.M.O.</i>
	RM 304		28-Apr-16	D.Kellyman	20-Jul-16	<i>N.S.M.O.M.O.</i>
	RM 305		28-Apr-16	D.Kellyman	20-Jul-16	<i>N.S.M.O.M.O.</i>

	RM 306		28-Apr-16	D.Kellyman	20-Jul-16	N.S.M.O.M.O.
	RM 307		28-Apr-16	D.Kellyman	20-Jul-16	N.S.M.O.M.O.
	RM 308		28-Apr-16	D.Kellyman	20-Jul-16	N.S.M.O.M.O.
	RM 309		28-Apr-16	D.Kellyman	20-Jul-16	N.S.M.O.M.O.
	RM 310		28-Apr-16	D.Kellyman	20-Jul-16	N.S.M.O.M.O.
Irma Coulson P.S.	HB 009	13	11-May-16	C. Jagarnauth	18-Aug-16	N.S.M.O.M.O.
	HB 081		11-May-16	C. Jagarnauth	18-Aug-16	N.S.M.O.M.O.
	HB 142		11-May-16	C. Jagarnauth	18-Aug-16	N.S.M.O.M.O.
	HB 146		11-May-16	C. Jagarnauth	18-Aug-16	N.S.M.O.M.O.
	HB 150		11-May-16	C. Jagarnauth	18-Aug-16	N.S.M.O.M.O.
	HBL 242		11-May-16	C. Jagarnauth	18-Aug-16	Exterior caulking degraded at window. Screw holes observed in metal cladding at left elevation.
	HBL 243		11-May-16	C. Jagarnauth	18-Aug-16	Screw holes observed in corner flashing at left elevation. Downspout detached at left elevation.
	HBL 244		11-May-16	C. Jagarnauth	18-Aug-16	N.S.M.O.M.O.
	HBL 245		11-May-16	C. Jagarnauth	18-Aug-16	N.S.M.O.M.O.
	HBL 246		11-May-16	C. Jagarnauth	18-Aug-16	Screw holes observed in metal cladding at right elevation.
	HB 204		11-May-16	C. Jagarnauth	18-Aug-16	Exterior caulking missing at windows, door, and air-exchanger vent.
	HBL 111		11-May-16	C. Jagarnauth	18-Aug-16	N.S.M.O.M.O.
	HB 196		11-May-16	C. Jagarnauth	18-Aug-16	Exterior caulking degraded at air-exchanger vent.
Milton District H.S.	HB 001	3	25-Apr-16	J. Jones	12-Jul-16	N.S.M.O.M.O.
	HB 093		25-Apr-16	J. Jones	12-Jul-16	Wood fascia damaged below eavestrough at front elevation. Hole (2") in cladding near roof at rear elevation.
	HB 154		25-Apr-16	J. Jones	12-Jul-16	N.S.M.O.M.O.
P.L. Robertson P.S.	HB 004	7	11-May-16	C. Jagarnauth	26-Jul-16	Caulking degraded at front windows.
	HB 016		11-May-16	C. Jagarnauth	26-Jul-16	Caulking degraded at door and windows.
	HB 021		11-May-16	C. Jagarnauth	26-Jul-16	N.S.M.O.M.O.
	HB 022		11-May-16	C. Jagarnauth	26-Jul-16	N.S.M.O.M.O.
	HB 027		11-May-16	C. Jagarnauth	26-Jul-16	N.S.M.O.M.O.
	HB 030		11-May-16	C. Jagarnauth	26-Jul-16	N.S.M.O.M.O.
	HB 039		11-May-16	C. Jagarnauth	26-Jul-16	N.S.M.O.M.O.
Park P.S.	HB 048	1	26-Apr-16	R. Farnsworth	6-Jul-16	N.S.M.O.M.O.
Robert Baldwin P.S.	HB 174	4	12-May-16	C. Jagarnauth	7-Jul-16	Window caulking degraded at front windows.
	HBL 079		12-May-16	C. Jagarnauth	7-Jul-16	N.S.M.O.M.O.
	HB 122		12-May-16	C. Jagarnauth	7-Jul-16	Caulking degraded at front door.
	HBL 248		12-May-16	C. Jagarnauth	7-Jul-16	N.S.M.O.M.O.
Robert Little P.S.	HB 208	2	26-Apr-16	R. Farnsworth	6-Jul-16	N.S.M.O.M.O.
	HBL 10		26-Apr-16	R. Farnsworth	6-Jul-16	N.S.M.O.M.O.

Sam Sherratt P.S.	HB 082	10	16-Feb-16	C. Jagarnauth	17-Aug-16	N.S.M.O.M.O.		
	HB 083		16-Feb-16	C. Jagarnauth	17-Aug-16	N.S.M.O.M.O.		
	HBL 087		16-Feb-16	C. Jagarnauth	17-Aug-16	N.S.M.O.M.O.		
	HBL 099		16-Feb-16	C. Jagarnauth	17-Aug-16	N.S.M.O.M.O.		
	HBL 223		16-Feb-16	C. Jagarnauth	17-Aug-16	N.S.M.O.M.O.		
	HBL 227		16-Feb-16	C. Jagarnauth	17-Aug-16	N.S.M.O.M.O.		
	HB 041		16-Feb-16	C. Jagarnauth	17-Aug-16	Exterior caulking missing at rear elevation conduit.		
	HB 195		16-Feb-16	C. Jagarnauth	17-Aug-16	Screw holes observed in metal cladding at front elevation.		
	HB 066		16-Feb-16	C. Jagarnauth	17-Aug-16	Section of metal cladding missing around conduit bracket.		
HB 127	16-Feb-16	C. Jagarnauth	17-Aug-16	Screw holes observed in rear right corner flashing and center flashing at left elevation.				
Silver Creek P.S.	HB 029	2	26-Apr-16	R. Farnsworth	6-Jul-16	N.S.M.O.M.O.		
	HB 033		26-Apr-16	R. Farnsworth	6-Jul-16	N.S.M.O.M.O.		
Tiger Jeet Singh P.S.	HB 063	11	22-Apr-16	J. Jones	11-Jul-16	N.S.M.O.M.O.		
	HB 095		22-Apr-16	J. Jones	11-Jul-16	N.S.M.O.M.O.		
	HB 109		22-Apr-16	J. Jones	11-Jul-16	N.S.M.O.M.O.		
	HB 116		22-Apr-16	J. Jones	11-Jul-16	N.S.M.O.M.O.		
	HB 126		22-Apr-16	J. Jones	11-Jul-16	N.S.M.O.M.O.		
	HB 187		22-Apr-16	J. Jones	11-Jul-16	N.S.M.O.M.O.		
	HBL 098		22-Apr-16	J. Jones	11-Jul-16	N.S.M.O.M.O.		
	HBL 013		22-Apr-16	J. Jones	11-Jul-16	N.S.M.O.M.O.		
	HBL 014		22-Apr-16	J. Jones	11-Jul-16	N.S.M.O.M.O.		
	HBL 015		22-Apr-16	J. Jones	11-Jul-16	N.S.M.O.M.O.		
	HBL 213		22-Apr-16	J. Jones	11-Jul-16	N.S.M.O.M.O.		
	W.I. Dick P.S.		HB 002	3	11-Apr-16	J. Jones	4-Jul-16	Hole (1") observed at rear metal cladding.
			HB 007		11-Apr-16	J. Jones	4-Jul-16	N.S.M.O.M.O.
HB 183		11-Apr-16	J. Jones		4-Jul-16	N.S.M.O.M.O.		
<b>Total Number of Portables</b>		<b>158</b>						

Notes:			
Scheduled inspection date subject to change due to availability of manpower and the facility.			
N.S.M.O.M.O. =	No Suspect Mould Or Moisture Observed		

PM Inspection Schedule						
School	Portable Number	Portables on Site	Round 97 Inspection Date	ARCADIS Inspector	Proposed Round 98 Inspection Date	Comments from Round 97 Inspection
Abbey Park H.S.	HB 164	3	15-May-16	S. Parliament	28-Jul-16	N.S.M.O.M.O.
	HB 108		15-May-16	S. Parliament	28-Jul-16	N.S.M.O.M.O.
	HB 163		15-May-16	S. Parliament	28-Jul-16	N.S.M.O.M.O.
E.J. James P.S.	HB 061	6	30-Apr-16	S. Parliament	15-Aug-16	N.S.M.O.M.O.
	HB 079		30-Apr-16	S. Parliament	15-Aug-16	N.S.M.O.M.O.
	HB 111		30-Apr-16	S. Parliament	15-Aug-16	Evidence of previous water penetration and dirt/debris observed on vapour barrier in ceiling space at C-2. No moisture or mould observed in ceiling space above.
	HB 121		30-Apr-16	S. Parliament	15-Aug-16	Stained ceiling tile observed. No moisture or mould observed in ceiling space above. Floor tiles (~6) damaged causing tripping hazard.
	HBL 009		30-Apr-16	S. Parliament	15-Aug-16	N.S.M.O.M.O.
	HBL 85		30-Apr-16	S. Parliament	15-Aug-16	N.S.M.O.M.O.
Iroquois Ridge H.S.	HB 070	3	10-May-16	C. Jagarnauth	11-Aug-16	Wooden skirting damaged at front elevation.
	HB 209		10-May-16	C. Jagarnauth	11-Aug-16	N.S.M.O.M.O.
	HB 202		10-May-16	C. Jagarnauth	11-Aug-16	Hole (2") and screw holes observed in metal cladding at right elevation. Exterior caulking missing at left elevation gable-louvre. Exterior caulking degraded at right elevation conduits. Siding open/missing at right elevation
James W. Hill P.S.	HB 080	3	10-May-16	C. Jagarnauth	11-Aug-16	N.S.M.O.M.O.
	HB 099		10-May-16	C. Jagarnauth	11-Aug-16	N.S.M.O.M.O.
	HB 176		10-May-16	C. Jagarnauth	11-Aug-16	Hole (1") observed in drywall. Wood fascia damaged at left elevation. Large quantities of dirt/debris observed on vapour barrier in ceiling space at C-2.
Joshua Creek P.S.	HB 085	3	10-May-16	C. Jagarnauth	11-Aug-16	Exterior caulking missing at left elevation conduit.
	HB 011		10-Mar-16	C. Jagarnauth	11-Aug-16	N.S.M.O.M.O.
	HB 077		10-Mar-16	C. Jagarnauth	11-Aug-16	Exterior caulking missing at left elevation conduit.
Munn's P.S.	HB 106	2	12-May-16	C. Jagarnauth	8-Aug-16	N.S.M.O.M.O.
	HB 177		12-May-16	C. Jagarnauth	8-Aug-16	Exterior caulking missing at left elevation conduit.
Oakville Trafalgar H.S.	RM 190	7	30-Apr-16	S. Parliament	15-Aug-16	N.S.M.O.M.O.
	RM 191		30-Apr-16	S. Parliament	15-Aug-16	N.S.M.O.M.O.
	RM 192		30-Apr-16	S. Parliament	15-Aug-16	Exterior caulking degraded at top of second window.
	RM 193		30-Apr-16	S. Parliament	15-Aug-16	N.S.M.O.M.O.
	RM 194		30-Apr-16	S. Parliament	15-Aug-16	N.S.M.O.M.O.
	RM 198		30-Apr-16	S. Parliament	15-Aug-16	N.S.M.O.M.O.
	RM 199		30-Apr-16	S. Parliament	15-Aug-16	N.S.M.O.M.O.
Pilgrim Wood P.S.	HBL 110	2	12-May-16	C. Jagarnauth	8-Aug-16	N.S.M.O.M.O.
	HBL 224		12-May-16	C. Jagarnauth	8-Aug-16	Screw holes observed in corner flashing and metal cladding at rear and right elevation.
Post's Corners P.S.	HB 065	1	10-May-16	C. Jagarnauth	11-Aug-16	Downspout missing at rear elevation.
Sheridan P.S.	HBL 226	1	10-May-16	C. Jagarnauth	11-Aug-16	N.S.M.O.M.O.
<b>Total Number of Portables</b>		<b>31</b>				

Notes:	
Scheduled inspection date subject to change due to availability of manpower and the facility.	
<b>N.S.M.O.M.O. =</b>	No Suspect Mould Or Moisture Observed

**PM Inspection Schedule**

School	Portable Number	Portables on Site	Round 97 Inspection Date	ARCADIS Inspector	Proposed Round 98 Inspection Date	Comments from Round 97 Inspection
Alexander's P.S.	HB 008	6	03-May-16	J. Jones	9-Aug-16	N.S.M.O.M.O.
	HB 024		03-May-16	J. Jones	9-Aug-16	N.S.M.O.M.O.
	HB 028		03-May-16	J. Jones	9-Aug-16	N.S.M.O.M.O.
	HB 032		03-May-16	J. Jones	9-Aug-16	N.S.M.O.M.O.
	HB 051		03-May-16	J. Jones	9-Aug-16	N.S.M.O.M.O.
	HBL 241		03-May-16	J. Jones	9-Aug-16	N.S.M.O.M.O.
Charles R. Beaudoin P.S.	HBL 100	4	25-Apr-16	D. Kellyman	13-Jul-16	N.S.M.O.M.O.
	HBL 101		25-Apr-16	D. Kellyman	13-Jul-16	N.S.M.O.M.O.
	HBL 102		25-Apr-16	D. Kellyman	13-Jul-16	N.S.M.O.M.O.
	HBL 247		25-Apr-16	D. Kellyman	13-Jul-16	N.S.M.O.M.O.
Dr. Frank Hayden	HB 059	6	17-May-16	C. Jagarnauth	26-Jul-16	<i>Exterior caulking degraded at front door. Stained ceiling tiles (2) observed (new). No moisture or mould observed in ceiling space above.</i>
	HB 120		17-May-16	C. Jagarnauth	26-Jul-16	N.S.M.O.M.O.
	HB 137		17-May-16	C. Jagarnauth	26-Jul-16	N.S.M.O.M.O.
	HB 172		17-May-16	C. Jagarnauth	26-Jul-16	N.S.M.O.M.O.
	HB 207		17-May-16	C. Jagarnauth	26-Jul-16	<i>Screw holes observed in metal cladding at right elevation. Vapour barrier damaged in ceiling space at C-3.</i>
	HB 092		17-May-16	C. Jagarnauth	26-Jul-16	<i>Hole (3") observed at right elevation for air-conditioner wiring. Exterior caulking missing at front door.</i>
J.W. Singleton Education Centre	HB 003	4	29-Apr-16	J. Jones	22-Aug-16	N.S.M.O.M.O.
	HB 117		29-Apr-16	J. Jones	22-Aug-16	N.S.M.O.M.O.
	HB 118		29-Apr-16	J. Jones	22-Aug-16	N.S.M.O.M.O.
	HB 119		29-Apr-16	J. Jones	22-Aug-16	N.S.M.O.M.O.
	HB 064		29-Apr-16	J. Jones	22-Aug-16	N.S.M.O.M.O.
John T. Tuck P.S.	HB 064	8	25-Apr-16	D. Kellyman	13-Jul-16	N.S.M.O.M.O.
	HB 156		25-Apr-16	D. Kellyman	13-Jul-16	N.S.M.O.M.O.
	HB 157		25-Apr-16	D. Kellyman	13-Jul-16	<i>Exterior caulking degraded at air conditioning unit.</i>
	HB 173		25-Apr-16	D. Kellyman	13-Jul-16	<i>Exterior caulking degraded at door.</i>
	HBL 219		25-Apr-16	D. Kellyman	13-Jul-16	N.S.M.O.M.O.
	HBL 220		25-Apr-16	D. Kellyman	13-Jul-16	N.S.M.O.M.O.
	HBL 221		25-Apr-16	D. Kellyman	13-Jul-16	N.S.M.O.M.O.
	HBL 216		25-Apr-16	D. Kellyman	13-Jul-16	N.S.M.O.M.O.
	HBL 247		25-Apr-16	D. Kellyman	13-Jul-16	N.S.M.O.M.O.
John W. Boich P.S.	HBL 247	5	03-May-16	J. Jones	9-Aug-16	N.S.M.O.M.O.
	HB 108		03-May-16	J. Jones	9-Aug-16	N.S.M.O.M.O.
	HB 109		03-May-16	J. Jones	9-Aug-16	N.S.M.O.M.O.
	HBL 217		03-May-16	J. Jones	9-Aug-16	N.S.M.O.M.O.
	HBL 218		03-May-16	J. Jones	9-Aug-16	N.S.M.O.M.O.
L.B. Pearson H.S.	RM 179 A	12	29-Apr-16	J. Jones	22-Aug-16	N.S.M.O.M.O.
	RM 180		29-Apr-16	J. Jones	22-Aug-16	N.S.M.O.M.O.
	RM 181		29-Apr-16	J. Jones	22-Aug-16	N.S.M.O.M.O.
	RM 182		29-Apr-16	J. Jones	22-Aug-16	N.S.M.O.M.O.
	RM 183		29-Apr-16	J. Jones	22-Aug-16	N.S.M.O.M.O.
	RM 184		29-Apr-16	J. Jones	22-Aug-16	N.S.M.O.M.O.
	RM 185		29-Apr-16	J. Jones	22-Aug-16	N.S.M.O.M.O.
	RM 186		29-Apr-16	J. Jones	22-Aug-16	N.S.M.O.M.O.
	RM 187		29-Apr-16	J. Jones	22-Aug-16	N.S.M.O.M.O.
	RM 188		29-Apr-16	J. Jones	22-Aug-16	N.S.M.O.M.O.
	RM 189		29-Apr-16	J. Jones	22-Aug-16	N.S.M.O.M.O.
	RM 190 A/B		29-Apr-16	J. Jones	22-Aug-16	N.S.M.O.M.O.
	M.M. Robinson H.S.		HB 010	3	29-Apr-16	J. Jones
HB 161		29-Apr-16	J. Jones		22-Aug-16	N.S.M.O.M.O.

Sir E. MacMillan P.S.	HB 017	6	18-May-16	C. Jagarnauth	25-Jul-16	<i>N.S.M.O.M.O.</i>
	HB 018		18-May-16	C. Jagarnauth	25-Jul-16	<i>N.S.M.O.M.O.</i>
	HB 019		18-May-16	C. Jagarnauth	25-Jul-16	<i>Exterior caulking degraded at air exchanger vent.</i>
	HB 020		18-May-16	C. Jagarnauth	25-Jul-16	<i>N.S.M.O.M.O.</i>
	HB 025		18-May-16	C. Jagarnauth	25-Jul-16	<i>Damaged wood siding observed.</i>
	HB 165		18-May-16	C. Jagarnauth	25-Jul-16	<i>Exterior caulking degraded at door.</i>
<b>Total Number of Portables</b>		<b>60</b>				

Notes:			
Scheduled inspection date subject to change due to availability of manpower and the facility.			
<b>N.S.M.O.M.O. =</b>	No Suspect Mould Or Moisture Observed		

**PM Inspection Schedule**

School	Portable Number	Portables on Site	Round 97 Inspection Date	ARCADIS Inspector	Proposed Round 98 Inspection Date	Comments from Round 97 Inspection
Captain R. Wilson P.S.	HB 014	1	12-May-16	S. Parliament	8-Aug-16	N.S.M.O.M.O.
Emily Carr P.S.	HB 084	4	12-May-16	S. Parliament	8-Aug-16	N.S.M.O.M.O.
	HBL 001		12-May-16	S. Parliament	8-Aug-16	N.S.M.O.M.O.
	HBL 002		12-May-16	S. Parliament	8-Aug-16	Skirting ventilation cover missing at right elevation.
	HBL 008		12-May-16	S. Parliament	8-Aug-16	N.S.M.O.M.O.
Forest Trail P.S.	HB 044	9	06-Apr-16	S. Parliament	14-Jul-16	N.S.M.O.M.O.
	HB 047		06-Apr-16	S. Parliament	14-Jul-16	N.S.M.O.M.O.
	HB 049		06-Apr-16	S. Parliament	14-Jul-16	N.S.M.O.M.O.
	HB 050		06-Apr-16	S. Parliament	14-Jul-16	N.S.M.O.M.O.
	HB 052		06-Apr-16	S. Parliament	14-Jul-16	N.S.M.O.M.O.
	HB 054		06-Apr-16	S. Parliament	14-Jul-16	Screw holes observed in metal cladding at left elevation. Junction box detached/hanging at left elevation.
	HB 058		06-Apr-16	S. Parliament	14-Jul-16	Stained ceiling tile (~1) observed along center seam (new) and evidence of previous water penetration observed on vapour barrier above (new). No moisture or mould observed in ceiling space above.
	HB 076		06-Apr-16	S. Parliament	14-Jul-16	N.S.M.O.M.O.
	HB 101		06-Apr-16	S. Parliament	14-Jul-16	N.S.M.O.M.O.
	Palmero P.S.		HB 086	5	15-May-16	S. Parliament
HB 087		15-May-16	S. Parliament		28-Jul-16	N.S.M.O.M.O.
HB 167		15-May-16	S. Parliament		28-Jul-16	Stained ceiling tile (~1) observed (new). No moisture or mould observed in ceiling space above.
HB 168		15-May-16	S. Parliament		28-Jul-16	N.S.M.O.M.O.
HB 170		15-May-16	S. Parliament		28-Jul-16	N.S.M.O.M.O.
Pine Grove P.S.	HB 043	10	26-Apr-16	D. Kellyman	18-Jul-16	N.S.M.O.M.O.
	HB 097		26-Apr-16	D. Kellyman	18-Jul-16	N.S.M.O.M.O.
	HB 123		26-Apr-16	D. Kellyman	18-Jul-16	N.S.M.O.M.O.
	HB 130		26-Apr-16	D. Kellyman	18-Jul-16	N.S.M.O.M.O.
	HB 131		26-Apr-16	D. Kellyman	18-Jul-16	N.S.M.O.M.O.
	HB 158		26-Apr-16	D. Kellyman	18-Jul-16	N.S.M.O.M.O.
	HB 159		26-Apr-16	D. Kellyman	18-Jul-16	N.S.M.O.M.O.
	HB 171		26-Apr-16	D. Kellyman	18-Jul-16	N.S.M.O.M.O.
	HB 175		26-Apr-16	D. Kellyman	18-Jul-16	N.S.M.O.M.O.
	HBL 006		26-Apr-16	D. Kellyman	18-Jul-16	N.S.M.O.M.O.
Sunningdale P.S.	HB 132	4	15-May-16	S. Parliament	28-Jul-16	N.S.M.O.M.O.
	HB145		15-May-16	S. Parliament	28-Jul-16	N.S.M.O.M.O.
	HB 072		15-May-16	S. Parliament	28-Jul-16	N.S.M.O.M.O.
	HB179		15-May-16	S. Parliament	28-Jul-16	Stained ceiling tile (~1) observed (new). No moisture or mould observed in ceiling space above.
W.H. Morden P.S.	HB 055	6	26-Apr-16	D. Kellyman	18-Jul-16	N.S.M.O.M.O.
	HB 138		26-Apr-16	D. Kellyman	18-Jul-16	N.S.M.O.M.O.
	HBL 007		26-Apr-16	D. Kellyman	18-Jul-16	N.S.M.O.M.O.
	HBL 249 (4447)		26-Apr-16	D. Kellyman	18-Jul-16	N.S.M.O.M.O.
	HBL 250 (931)		26-Apr-16	D. Kellyman	18-Jul-16	Exterior caulking missing at windows (new).
	HB 199		26-Apr-16	D. Kellyman	18-Jul-16	Exterior caulking missing/degraded at door and windows.

West Oak P.S.	RM 1	9	06-Apr-16	S. Parliament	14-Jul-16	<i>Section (6') of wooden skirting missing.</i>
	RM 2		06-Apr-16	S. Parliament	14-Jul-16	<i>N.S.M.O.M.O.</i>
	RM 3		06-Apr-16	S. Parliament	14-Jul-16	<i>N.S.M.O.M.O.</i>
	RM 4		06-Apr-16	S. Parliament	14-Jul-16	<i>N.S.M.O.M.O.</i>
	RM 5		06-Apr-16	S. Parliament	14-Jul-16	<i>N.S.M.O.M.O.</i>
	RM 6		06-Apr-16	S. Parliament	14-Jul-16	<i>N.S.M.O.M.O.</i>
	Work Room		06-Apr-16	S. Parliament	14-Jul-16	<i>N.S.M.O.M.O.</i>
	HB 107		06-Apr-16	S. Parliament	14-Jul-16	<i>N.S.M.O.M.O.</i>
	HB 088		06-Apr-16	S. Parliament	14-Jul-16	<i>Screw holes observed in metal cladding at front elevation.</i>
White Oaks Centre for Science and Technology (North Campus)	HB 060	5	12-May-16	C. Jagarnauth	08-Aug-16	<i>N.S.M.O.M.O.</i>
	HBL 092		12-May-16	C. Jagarnauth	08-Aug-16	<i>N.S.M.O.M.O.</i>
	HBL 093		12-May-16	C. Jagarnauth	08-Aug-16	<i>N.S.M.O.M.O.</i>
	HBL 094		12-May-16	C. Jagarnauth	08-Aug-16	<i>Rear eavestrough detached.</i>
	HBL 095		12-May-16	C. Jagarnauth	08-Aug-16	<i>Wooden skirting damaged at rear and left elevations.</i>
White Oaks School Admin. (South Campus)	HB 023	12	12-Apr-16	J. Jones	05-Jul-16	<i>N.S.M.O.M.O.</i>
	HB 042		12-Apr-16	J. Jones	05-Jul-16	<i>N.S.M.O.M.O.</i>
	HBL 016		12-Apr-16	J. Jones	05-Jul-16	<i>N.S.M.O.M.O.</i>
	HB 078		12-Apr-16	J. Jones	05-Jul-16	<i>N.S.M.O.M.O.</i>
	HB 112		12-Apr-16	J. Jones	05-Jul-16	<i>N.S.M.O.M.O.</i>
	HB 153		12-Apr-16	J. Jones	05-Jul-16	<i>N.S.M.O.M.O.</i>
	HBL 018		12-Apr-16	J. Jones	05-Jul-16	<i>N.S.M.O.M.O.</i>
	HB 201		12-Apr-16	J. Jones	05-Jul-16	<i>Missing ceiling tile observed near front door.</i>
	HB 205		12-Apr-16	J. Jones	05-Jul-16	<i>N.S.M.O.M.O.</i>
	HBL 017		12-Apr-16	J. Jones	05-Jul-16	<i>N.S.M.O.M.O.</i>
	HBL 096		12-Apr-16	J. Jones	05-Jul-16	<i>N.S.M.O.M.O.</i>
HBL 097	12-Apr-16	J. Jones	05-Jul-16	<i>N.S.M.O.M.O.</i>		
<b>Total Number of Portables</b>		<b>65</b>				

Notes:			
Scheduled inspection date subject to change due to availability of manpower and the facility.			
<b>N.S.M.O.M.O. =</b>	No Suspect Mould Or Moisture Observed		

PM Inspection Schedule						
School	Portable Number	Portables on Site	Round 97 Inspection Date	ARCADIS Inspector	Proposed Round 98 Inspection Date	Comments from Round 97 Inspection
Alton Village P.S.	HBL 234	9	29-Apr-16	S. Parliament	27-Jul-16	N.S.M.O.M.O.
	HBL 235		29-Apr-16	S. Parliament	27-Jul-16	N.S.M.O.M.O.
	HBL 236		29-Apr-16	S. Parliament	27-Jul-16	Exterior caulking degraded at door. Heavily stained ceiling tiles (3) observed No moisture or mould observed in ceiling space above.
	HBL 237		29-Apr-16	S. Parliament	27-Jul-16	N.S.M.O.M.O.
	HBL 238		29-Apr-16	S. Parliament	27-Jul-16	N.S.M.O.M.O.
	HBL 239		29-Apr-16	S. Parliament	27-Jul-16	Screw holes observed in metal cladding and center flashing at left elevation.
	HBL 225		29-Apr-16	S. Parliament	27-Jul-16	N.S.M.O.M.O.
	HB 068		29-Apr-16	S. Parliament	27-Jul-16	N.S.M.O.M.O.
	HB 037		29-Apr-16	S. Parliament	27-Jul-16	N.S.M.O.M.O.
Dr. Charles Best P.S.	HBL 210	2	April 22, 2016	R. Farnsworth	21-Jul-16	N.S.M.O.M.O.
	HBL 211		April 22, 2016	R. Farnsworth	21-Jul-16	N.S.M.O.M.O.
Florence Meares P.S.	HB 139	1	29-Apr-16	S. Parliament	27-Jul-16	End cap damaged at rear elevation eavestrough. Roof flashing (2') damaged at right elevation.
Kilbride P.S.	HB 074	1	29-Apr-16	S. Parliament	27-Jul-16	Holes observed in front and rear skirting.
Orchard Park P.S.	HB 040	4	03-May-16	J. Jones	9-Aug-16	N.S.M.O.M.O.
	HB 147		03-May-16	J. Jones	9-Aug-16	N.S.M.O.M.O.
	HB 166		03-May-16	J. Jones	9-Aug-16	N.S.M.O.M.O.
	HB 140		03-May-16	J. Jones	9-Aug-16	N.S.M.O.M.O.
Pauline Johnson P.S.	HBL 222	2	18-May-16	C. Jagarnauth	25-Jul-16	N.S.M.O.M.O.
	HB 102		18-May-16	C. Jagarnauth	25-Jul-16	N.S.M.O.M.O.
Tom Thompson P.S.	HB 169	10	April 22, 2016	R. Farnsworth	21-Jul-16	N.S.M.O.M.O.
	HB 098		April 22, 2016	R. Farnsworth	21-Jul-16	N.S.M.O.M.O.
	HB 012		April 22, 2016	R. Farnsworth	21-Jul-16	N.S.M.O.M.O.
	HB 031		April 22, 2016	R. Farnsworth	21-Jul-16	N.S.M.O.M.O.
	HB 053		April 22, 2016	R. Farnsworth	21-Jul-16	N.S.M.O.M.O.
	HB 105		April 22, 2016	R. Farnsworth	21-Jul-16	N.S.M.O.M.O.
	HB 124		April 22, 2016	R. Farnsworth	21-Jul-16	N.S.M.O.M.O.
	HB 141		April 22, 2016	R. Farnsworth	21-Jul-16	N.S.M.O.M.O.
	HB 148		April 22, 2016	R. Farnsworth	21-Jul-16	N.S.M.O.M.O.
	HB 206		April 22, 2016	R. Farnsworth	21-Jul-16	N.S.M.O.M.O.
<b>Total Number of Portables</b>		<b>29</b>				

Notes:	
Scheduled inspection date subject to change due to availability of manpower and the facility.	
N.S.M.O.M.O. =	No Suspect Mould Or Moisture Observed