

PM Inspection Schedule

School	Portable Number	Portables on Site	Round 104 Inspection Date	Arcadis Inspector	Proposed Round 105 Inspection Date	Comments from Round 104 Inspection
Anne J. MacArthur P.S.	HB 026	11	24-Nov-17	Amit Kaul	15-Jan-18	Sections of roof edge flashing (~6") missing at right elevation.
	HB 071		22-Nov-17	Amit Kaul	15-Jan-18	Damaged vinyl floor tiles and exposed subfloor. Degraded caulking on windows.
	HB 174		24-Nov-17	Amit Kaul	15-Jan-18	Caulking missing around the door frame and on air-exchanger.
	HBL 202		24-Nov-17	Amit Kaul	15-Jan-18	Two stained ceiling tiles (new).
	HBL 203		24-Nov-17	Amit Kaul	15-Jan-18	N.S.M.O.M.O.
	HBL 204		24-Nov-17	Amit Kaul	15-Jan-18	Caulking missing on air-exchanger vent at front elevation. Caulking degraded on the door. One damaged vinyl floor tile.
	HBL 205		24-Nov-17	Amit Kaul	15-Jan-18	Caulking missing around the door frame.
	HBL 214		24-Nov-17	Amit Kaul	15-Jan-18	Exterior caulking degraded on door. Exterior caulking missing around window frames and black staining observed on exposed wood at first window from the door. Caulking degraded on the door.
	HBL 215		24-Nov-17	Amit Kaul	15-Jan-18	Caulking degraded on door. Exterior caulking missing on air-exchanger vent and top of windows at front elevation. Vinyl floor tiles (~2) missing near air- exchanger unit.
	HBL 232		24-Nov-17	Amit Kaul	15-Jan-18	N.S.M.O.M.O.
HBL 233		24-Nov-17	Amit Kaul	15-Jan-18	Caulking degraded on the door. Caulking missing on air-exchanger vent at front elevation. Exterior caulking missing around window frames.	
Boyne P.S.	HB 008	18	28-Nov-17	Amit Kaul	17-Jan-18	Screw holes observed on metal cladding under windows.
	HB 015		28-Nov-17	Amit Kaul	17-Jan-18	Caulking degraded on air-exchanger vent at front elevation.
	HB 028		28-Nov-17	Amit Kaul	17-Jan-18	Exterior caulking degraded at window. Vinyl floor tiles (~15) damaged throughout. Vinyl floor tiles (~4) missing and floor tiles (~20) damaged. Caulking degraded on gable louvres at right elevation.
	HB 029		28-Nov-17	Amit Kaul	17-Jan-18	Screw holes observed in metal cladding next to door at front elevation. Caulking missing around the window frames.
	HB 032		28-Nov-17	Amit Kaul	17-Jan-18	Hole (3") observed in drywall near footwear and clothing storage. Exterior caulking degraded at front door.
	HB 033		28-Nov-17	Amit Kaul	17-Jan-18	Ceiling tile missing above air-exchanger unit at rear elevation. Caulking degraded on air-conditioner and air conditioner.
	HB 048		28-Nov-17	Amit Kaul	17-Jan-18	Caulking degraded on windows at front elevation. Long tear (~3") in metal cladding at rear elevation. Long cut (~2") in metal cladding above windows.
	HB 152		28-Nov-17	Amit Kaul	17-Jan-18	Downspout missing at rear elevation. Exterior caulking degraded on windows. Exterior caulking missing at front door.
	HB 179		28-Nov-17	Amit Kaul	17-Jan-18	Stained ceiling tile observed at C-1. No suspect mould or moisture was observed.
	HB 226		28-Nov-17	Amit Kaul	17-Jan-18	Vinyl floor tiles damaged (~12). Exterior caulking missing around window frames and the door frame.
	HBL 110		28-Nov-17	Amit Kaul	17-Jan-18	N.S.M.O.M.O.
	HBL 218		28-Nov-17	Amit Kaul	17-Jan-18	Vinyl floor tiles damaged (~15).
	HBL 241		28-Nov-17	Amit Kaul	17-Jan-18	Downspout detached from eavestrough at front elevation. Caulking missing on door frames.
	HBL 251		28-Nov-17	Amit Kaul	17-Jan-18	N.S.M.O.M.O.
	HBL 252		28-Nov-17	Amit Kaul	17-Jan-18	Exterior caulking degraded at door. Ceiling tile missing above air-exchanger unit. Vinyl floor tiles (>15) damaged throughout. Sections of baseboard (~7") missing at rear elevation. Hole (2") in metal cladding at the left elevation. Interior caulking degraded on the windows.
HBL 253		28-Nov-17	Amit Kaul	17-Jan-18	N.S.M.O.M.O.	
HBL 254		28-Nov-17	Amit Kaul	17-Jan-18	N.S.M.O.M.O.	
HBL 257		28-Nov-17	Amit Kaul	17-Jan-18	N.S.M.O.M.O.	
Bruce Trail P.S.	HB 046	14	13-Nov-17	Amit Kaul	8-Jan-18	Caulking degraded on windows.
	HB 062		13-Nov-17	Amit Kaul	8-Jan-18	Lintel flashing detached on metal cladding at right elevation. Degraded caulking on the second window from the door. Separation in metal cladding near conduits.
	HB 075		13-Nov-17	Amit Kaul	8-Jan-18	Screw holes (~6) observed along the right edge of front elevation. Hole (~3") observed in metal cladding at right elevation. Screw holes (~7) observed in metal cladding at right elevation.
	HB 103		13-Nov-17	Amit Kaul	8-Jan-18	Caulking missing on air-exchanger vent at left elevation.

	HB 110		14-Nov-17	Amit Kaul	8-Jan-18	An opening (3"x3") observed in metal cladding at right elevation. Damaged vinyl floor tiles (~5).
	HB 114		14-Nov-17	Amit Kaul	8-Jan-18	Vinyl floor tiles (~4) damaged. Vinyl floor tiles (~20) observed to be cracked throughout.
	HB 115		14-Nov-17	Amit Kaul	8-Jan-18	Six 1/2" tear on metal cladding at front elevation. Damaged vinyl floor tiles (~ 4).
	HBL 105		13-Nov-17	Amit Kaul	8-Jan-18	N.S.M.O.M.O.
	HBL 206		13-Nov-17	Amit Kaul	8-Jan-18	N.S.M.O.M.O.
	HBL 228		13-Nov-17	Amit Kaul	8-Jan-18	Stained ceiling tiles observed (~2). Vinyl floor tiles (~18) missing along right wall. Suspect mould on left wall next to door. Missing ceiling tiles (~2).
	HBL 229		13-Nov-17	Amit Kaul	8-Jan-18	Degraded caulking on windows.
	HBL 230		13-Nov-17	Amit Kaul	8-Jan-18	Stained ceiling tiles (~2) observed next to door. Damaged vinyl floor tiles near door at front elevation. Vinyl floor tiles (~6) missing at front-right corner. Moisture on vapour barrier observed in the ceiling tile above the door.
	HBL 231		13-Nov-17	Amit Kaul	8-Jan-18	Caulking degraded on air-exchanger unit.
	HBL 262		13-Nov-17	Amit Kaul	8-Jan-18	N.S.M.O.M.O.
Chris Hadfield P.S.	RM A1	12	08-Nov-17	Amit Kaul	3-Jan-18	Large crack observed on vinyl floor tiles from the front wall to rear wall. Vinyl wall paper on drywall at windows degraded.
	RM A2		08-Nov-17	Amit Kaul	3-Jan-18	Large crack observed on vinyl floor tiles from the front wall to rear wall.
	RM A3		08-Nov-17	Amit Kaul	3-Jan-18	Vinyl wall paper on drywall at windows degraded.
	RM A4		08-Nov-17	Amit Kaul	3-Jan-18	N.S.M.O.M.O.
	RM A5		08-Nov-17	Amit Kaul	3-Jan-18	N.S.M.O.M.O.
	RM A6		08-Nov-17	Amit Kaul	3-Jan-18	N.S.M.O.M.O.
	RM A7		08-Nov-17	Amit Kaul	3-Jan-18	N.S.M.O.M.O.
	RM A8		08-Nov-17	Amit Kaul	3-Jan-18	N.S.M.O.M.O.
	RM A9		08-Nov-17	Amit Kaul	3-Jan-18	N.S.M.O.M.O.
	RM A10		08-Nov-17	Amit Kaul	3-Jan-18	Large crack observed on vinyl floor tiles from the front wall to rear wall.
	RM A11		08-Nov-17	Amit Kaul	3-Jan-18	N.S.M.O.M.O.
	HBL 106		08-Nov-17	Amit Kaul	3-Jan-18	Caulking degraded on conduits at right elevation.
Craig Kielburger S.S.	HB 038	18	24-Nov-17	Amit Kaul	12-Jan-18	Baseboard (~4') detached at front elevation. Hole (2") observed in drywall at front elevation. Screw holes (~3) observed in metal cladding left of the door.
	HB 045		24-Nov-17	Amit Kaul	12-Jan-18	Vinyl floor tiles damaged near the door and swollen (signs of moisture). Caulking degraded on windows. Baseboard (~2') detached at left elevation. Screw holes in corner flashing at rear elevation. Screw holes (~5) observed in metal cladding near the door.
	HB 056		24-Nov-17	Amit Kaul	12-Jan-18	Minor hole (~2") observed on drywall at left wall. Damaged vinyl floor tiles (~4) observed at entrance.
	HB 057		24-Nov-17	Amit Kaul	12-Jan-18	Screw holes in metal cladding at rear elevation.
	HB 073		24-Nov-17	Amit Kaul	12-Jan-18	Hole (~ 4x4") observed in drywall above electrical panel at left elevation. Screw holes in metal cladding throughout rear elevation. Corner flashing damaged at rear elevation. Screw holes (~8) around the door.
	HB 090		24-Nov-17	Amit Kaul	12-Jan-18	Downspout detached at front elevation. Screw holes in metal cladding near the door at front elevation and 1 screw hole in metal cladding at right elevation. Vinyl floor tiles (~4) damaged at the entrance.
	HB 091		24-Nov-17	Amit Kaul	12-Jan-18	Eavestrough detached (~3') from side roof flashing at front elevation. Exterior caulking degraded on the window next to door.
	HB 100		24-Nov-17	Amit Kaul	12-Jan-18	Eavestrough detached (~6') from roof edge at rear elevation.
	HB 113		24-Nov-17	Amit Kaul	12-Jan-18	Damaged vinyl floor tiles (~3) at front and left elevations. Caulking degraded on the windows. Screw holes in metal cladding near corner flashing at rear elevation.
	HB 125		24-Nov-17	Amit Kaul	12-Jan-18	Screw holes in corner flashings at rear elevation.
	HB 133		24-Nov-17	Amit Kaul	12-Jan-18	Exterior caulking degraded on both windows at front elevation.
	HB 134		24-Nov-17	Amit Kaul	12-Jan-18	Two vinyl floor tiles swollen in front of the air-exchanger (signs of moisture in subfloor). Caulking degraded on the second window from the door.
	HB 135		24-Nov-17	Amit Kaul	15-Jan-18	Damaged vinyl floor tiles (~3). Missing vinyl floor tiles near entrance (~4).
	HB 143		24-Nov-17	Amit Kaul	15-Jan-18	Exterior caulking degraded on the door and the windows. Screw holes observed in metal claddings at front and rear elevations.
	HB 203		24-Nov-17	Amit Kaul	15-Jan-18	Screw holes throughout metal cladding at rear elevation.
	HBL 005		24-Nov-17	Amit Kaul	15-Jan-18	N.S.M.O.M.O.
	HBL 080		24-Nov-17	Amit Kaul	15-Jan-18	Minor hole (~2") on interior drywall above electrical panel.
	HBL 084		24-Nov-17	Amit Kaul	15-Jan-18	N.S.M.O.M.O.

Escarpment View P.S.	HB 005	11	09-Nov-17	Amit Kaul	4-Jan-18	Exterior caulking degraded at door and windows. Door frame loose at front elevation. Vinyl floor tiles (~4) missing next to air-exchanger. Three 1/4" holes in drywall near the door.
	HB 089		09-Nov-17	Amit Kaul	4-Jan-18	N.S.M.O.M.O.
	HB 144		09-Nov-17	Amit Kaul	4-Jan-18	Roof edge flashing (~3') missing at right elevation. Caulking degraded at air-exchanger.
	HBL 081		09-Nov-17	Amit Kaul	4-Jan-18	Caulking degraded on windows.
	HBL 082		09-Nov-17	Amit Kaul	4-Jan-18	Caulking degraded on windows.
	HBL 083		09-Nov-17	Amit Kaul	4-Jan-18	Caulking degraded on windows.
	HBL 088		09-Nov-17	Amit Kaul	4-Jan-18	Caulking degraded on one conduit at right elevation.
	HBL 089		09-Nov-17	Amit Kaul	4-Jan-18	N.S.M.O.M.O.
	HBL 090		09-Nov-17	Amit Kaul	4-Jan-18	N.S.M.O.M.O.
	HBL 103		09-Nov-17	Amit Kaul	4-Jan-18	Caulking degraded on windows.
HBL 104		09-Nov-17	Amit Kaul	4-Jan-18	N.S.M.O.M.O.	
E.W. Foster P.S.	HB 129	3	08-Nov-17	Amit Kaul	3-Jan-18	Downspout detached at rear elevation.
	HB 180		08-Nov-17	Amit Kaul	3-Jan-18	Downspout detached at front elevation. One damaged vinyl floor tile. Drywall damaged at rear elevation.
	HB 189		08-Nov-17	Amit Kaul	3-Jan-18	N.S.M.O.M.O.
Gardiner P.S.	HB 049	5	09-Nov-17	Amit Kaul	2-Jan-18	N.S.M.O.M.O.
	HB 208		09-Nov-17	Amit Kaul	2-Jan-18	Lower half of downspout missing at rear elevation. One stained ceiling tile (new).
	HBL 207		09-Nov-17	Amit Kaul	2-Jan-18	N.S.M.O.M.O.
	HBL 212		09-Nov-17	Amit Kaul	2-Jan-18	N.S.M.O.M.O.
	HBL 263		09-Nov-17	Amit Kaul	2-Jan-18	N.S.M.O.M.O.
Glen Williams P.S.	HB 178	2	07-Nov-17	Amit Kaul	2-Jan-18	N.S.M.O.M.O.
	HB 184		07-Nov-17	Amit Kaul	2-Jan-18	Missing vinyl floor tiles (~2) near air-exchanger and subfloor damaged. Hole (2") observed in metal cladding at right elevation.
Hawthorne Village P.S.	HB 013	24	15-Nov-17	Amit Kaul	9-Jan-18	Baseboard detached at rear elevation. Screw holes near the door.
	HB 034		15-Nov-17	Amit Kaul	9-Jan-18	One vinyl floor tile damaged near the door. Caulking missing around the window frames.
	HB 035		15-Nov-17	Amit Kaul	9-Jan-18	N.S.M.O.M.O.
	HB 036		15-Nov-17	Amit Kaul	9-Jan-18	N.S.M.O.M.O.
	HB 041		15-Nov-17	Amit Kaul	9-Jan-18	Screw holes in metal cladding at rear and front elevations.
	HB 136		15-Nov-17	Amit Kaul	9-Jan-18	Caulking missing on conduits. Caulking deficient on conduits. Vinyl floor tiles damaged (~5).
	HB 155		15-Nov-17	Amit Kaul	9-Jan-18	Hole (2") in corner flashing at left elevation. Damaged vinyl floor tiles (~2).
	HB 162		15-Nov-17	Amit Kaul	9-Jan-18	Screw holes observed on metal cladding at right elevation. Hole (~3") in metal cladding under conduits.
	HBL 223		15-Nov-17	Amit Kaul	9-Jan-18	N.S.M.O.M.O.
	RM 301		14-Nov-17	Amit Kaul	10-Jan-18	Crack (~20') observed on left concrete wall.
	RM 302		14-Nov-17	Amit Kaul	10-Jan-18	Crack (~5') observed on left concrete wall.
	RM 303		14-Nov-17	Amit Kaul	10-Jan-18	Crack (~8') observed on left concrete wall. Caulking degraded on exterior concrete panels.
	RM 304		14-Nov-17	Amit Kaul	10-Jan-18	Crack (~11') observed on right concrete wall. Caulking degraded on exterior concrete panels.
	RM 305		14-Nov-17	Amit Kaul	10-Jan-18	Caulking degraded on exterior concrete walls.
	RM 306		14-Nov-17	Amit Kaul	10-Jan-18	Crack (~4') observed on the concrete wall behind the door. Large crack on ceiling along right wall. Caulking degraded on exterior concrete walls at left elevation.
	RM 307		14-Nov-17	Amit Kaul	10-Jan-18	Crack (~1') observed on concrete wall next to door. Crack (~8') observed on left concrete wall.
	RM 308		14-Nov-17	Amit Kaul	10-Jan-18	Crack (~8') observed on concrete wall next to door.
	RM 309		14-Nov-17	Amit Kaul	10-Jan-18	Cracks (~10') observed on concrete wall both left and right side .
	RM 310		14-Nov-17	Amit Kaul	10-Jan-18	Crack (~12') observed on concrete wall next to door.
	Room 101		14-Nov-17	Amit Kaul	10-Jan-18	N.S.M.O.M.O.
Room 102		14-Nov-17	Amit Kaul	10-Jan-18	N.S.M.O.M.O.	
Room 103		14-Nov-17	Amit Kaul	10-Jan-18	N.S.M.O.M.O.	
Room 104		14-Nov-17	Amit Kaul	10-Jan-18	N.S.M.O.M.O.	
Room 105		14-Nov-17	Amit Kaul	10-Jan-18	N.S.M.O.M.O.	
Irma Coulson P.S.	HB 009	15	20-Nov-17	Amit Kaul	11-Jan-18	Sections of degraded baseboard (~20') detached at left elevation. Screw holes in metal cladding near the door at front elevation.

	HB 081		20-Nov-17	Amit Kaul	11-Jan-18	N.S.M.O.M.O
	HB 142		20-Nov-17	Amit Kaul	11-Jan-18	Caulking missing at conduit at right elevation. Baseboard (~10') detached from the wall at rear elevation.
	HB 146		20-Nov-17	Amit Kaul	11-Jan-18	Caulking degraded on door at front elevation. Screw holes in metal cladding near the door at front elevation. Screw holes (~4) observed under the last window from the door.
	HB 149		20-Nov-17	Amit Kaul	11-Jan-18	Screw hole on metal cladding around windows. Caulking degraded on the first window from the door.
	HB 150		20-Nov-17	Amit Kaul	11-Jan-18	Baseboard (~1') detached at front elevation, left of the door.
	HB 195		20-Nov-17	Amit Kaul	11-Jan-18	Screw holes in metal cladding at front and rear elevations. Screw holes (~9) in metal cladding near lintel at right elevation.
	HB 196		20-Nov-17	Amit Kaul	11-Jan-18	Downspout missing at rear elevation.
	HB 204		20-Nov-17	Amit Kaul	11-Jan-18	Caulking degraded on windows and the door. Caulking degraded on air-exchanger.
	HBL 111		20-Nov-17	Amit Kaul	11-Jan-18	N.S.M.O.M.O
	HBL 242		20-Nov-17	Amit Kaul	11-Jan-18	Exterior caulking missing at the first window from the door.
	HBL 243		20-Nov-17	Amit Kaul	11-Jan-18	Two 4" holes in drywall at rear elevation. Caulking degraded on windows.
	HBL 244		20-Nov-17	Amit Kaul	11-Jan-18	Caulking missing under the window frames.
	HBL 245		20-Nov-17	Amit Kaul	11-Jan-18	Corner flashing damaged (screw holes) at front elevation.
	HBL 246		20-Nov-17	Amit Kaul	11-Jan-18	Screw holes observed on corner edge flashing at right elevation. Sections of baseboard (17') damaged at left elevation.
Milton District H.S.	HB 001	3	09-Nov-17	Amit Kaul	5-Jan-18	Caulking missing on windows and the door. Downspout missing at front and rear elevations. Soffit missing at front elevation. Metal cladding damaged under conduits.
	HB 093		09-Nov-17	Amit Kaul	5-Jan-18	Caulking degraded on windows. Drywall damaged at two sections at front elevation near white boards. Hole (2") observed in metal cladding at rear elevation. Damaged vinyl floor tiles (~12). Baseboard detached at left elevation.
	HB 154		09-Nov-17	Amit Kaul	5-Jan-18	Exterior caulking missing at conduit at rear elevation. Hole (4") observed on the interior drywall at right elevation. Caulking degraded on windows. Hole (~6") observed in gable louver at right elevation.
P.L. Robertson P.S.	HB 004	12	21-Nov-17	Amit Kaul	18-Jan-18	N.S.M.O.M.O.
	HB 016		21-Nov-17	Amit Kaul	18-Jan-18	Caulking degraded at the second window from the door.
	HB 021		21-Nov-17	Amit Kaul	18-Jan-18	Caulking missing around the window frames.
	HB 022		21-Nov-17	Amit Kaul	18-Jan-18	Exterior caulking degraded at door. Caulking missing around the window frames.
	HB 027		21-Nov-17	Amit Kaul	18-Jan-18	Screw holes in metal cladding (between the windows). Hole (1/2") observed in drywall next to the door. Caulking degraded on the door.
	HB 030		21-Nov-17	Amit Kaul	18-Jan-18	Two holes (1") in metal cladding observed on right elevation. Hole (2") observed in drywall near the door.
	HB 039		21-Nov-17	Amit Kaul	18-Jan-18	Degraded caulking on air-exchanger.
	HB 051		21-Nov-17	Amit Kaul	18-Jan-18	Screw holes observed on metal cladding near the door.
	HBL 091		21-Nov-17	Amit Kaul	18-Jan-18	Vinyl floor tiles (~2) damaged and subfloor exposed.
	HBL 259		21-Nov-17	Amit Kaul	18-Jan-18	N.S.M.O.M.O.
	HBL 265		21-Nov-17	Amit Kaul	18-Jan-18	Caulking degraded on the conduits. One ceiling tile missing.
	HBL 266		21-Nov-17	Amit Kaul	18-Jan-18	N.S.M.O.M.O.
Robert Baldwin P.S.	HBL 079	1	07-Nov-17	Amit Kaul	2-Jan-18	Hole (2") observed in metal cladding at right elevation.
Robert Little P.S.	HBL 107	1	07-Nov-17	Amit Kaul	2-Jan-18	Hole (~2") observed in metal cladding at left elevation.
Sam Sherratt P.S.	HB 066	6	13-Nov-17	Amit Kaul	5-Jan-18	Caulking missing at air-conditioning and conduits at right elevation. Caulking degraded on windows. Screw holes in metal cladding under the windows.
	HB 082		13-Nov-17	Amit Kaul	5-Jan-18	Downspout detached at rear elevation. Stained ceiling tiles (4) observed at front elevation near door (new). Tear in metal deck above ceiling tile near the door.
	HB 083		13-Nov-17	Amit Kaul	5-Jan-18	N.S.M.O.M.O.
	HB 127		13-Nov-17	Amit Kaul	5-Jan-18	Screw holes (~7) observed on exterior metal cladding at rear elevation. Hole (2") observed on metal cladding above door at rear elevation. Caulking degraded on the door.
	HBL 099		13-Nov-17	Amit Kaul	5-Jan-18	N.S.M.O.M.O.
	HBL 227		13-Nov-17	Amit Kaul	5-Jan-18	Exterior caulking degraded on the windows. Hole (2") observed in metal cladding at right elevation.
Tiger Jeet Singh P.S.	HB 063	12	27-Nov-17	Amit Kaul	16-Jan-18	Vinyl floor tile missing (1) and floor tiles damaged (~4).
	HB 095		27-Nov-17	Amit Kaul	16-Jan-18	Black staining on center beam framing

	HB 109		27-Nov-17	Amit Kaul	16-Jan-18	Exterior caulking degraded at second window. Vinyl floor tiles (~3) missing at the entrance. Damaged vinyl floor tiles (~6).
	HB 116		27-Nov-17	Amit Kaul	16-Jan-18	Exterior caulking degraded on windows. Caulking degraded on air-exchanger. Caulking missing around the door frame.
	HB 126		27-Nov-17	Amit Kaul	16-Jan-18	Vinyl floor tiles (~7) damaged.
	HB 187		27-Nov-17	Amit Kaul	16-Jan-18	N.S.M.O.M.O.
	HBL 013		27-Nov-17	Amit Kaul	16-Jan-18	N.S.M.O.M.O.
	HBL 014		27-Nov-17	Amit Kaul	16-Jan-18	Exterior caulking missing around the window frames.
	HBL 015		27-Nov-17	Amit Kaul	16-Jan-18	Exterior caulking missing around the window frames.
	HBL 098		27-Nov-17	Amit Kaul	16-Jan-18	N.S.M.O.M.O.
	HBL 213		27-Nov-17	Amit Kaul	16-Jan-18	Two 1" holes observed in drywall at rear and left elevations. Screw holes observed in exterior metal corner flashing at right elevation. Exterior caulking degraded on the first window from the door.
	HBL 258		27-Nov-17	Amit Kaul	16-Jan-18	N.S.M.O.M.O.
W.I. Dick P.S.	HB 002	3	09-Nov-17	Amit Kaul	4-Jan-18	Damaged vinyl floor tile (~1).
	HB 007		09-Nov-17	Amit Kaul	4-Jan-18	N.S.M.O.M.O.
	HB 183		09-Nov-17	Amit Kaul	4-Jan-18	Hole (1") observed in metal cladding at front elevation.
Total Portables		171				

Notes:			
Scheduled inspection date subject to change due to availability of manpower and the facility.			
<b>N.S.M.O.M.O. =</b>	No Suspect Mould Or Moisture Observed		

School	Portable Number	Portables on Site	Round 104 Inspection Date	Arcadis Inspector	Proposed Round 105 Inspection Date	Comments from Round 104 Inspection
Charles R. Beaudoin P.S.	HBL 100	3	12-Dec-17	Amit Kaul	31-Jan-18	N.S.M.O.M.O.
	HBL 101		12-Dec-17	Amit Kaul	31-Jan-18	Caulking missing around the door frame and on air-exchanger.
	HBL 102		12-Dec-17	Amit Kaul	31-Jan-18	Degraded caulking on conduits at right elevation.
Dr. Frank Hayden S.S.	HB 010	12	12-Nov-17	Amit Kaul	1-Feb-18	Hole (1") in metal cladding at left elevation.
	HB 059		12-Nov-17	Amit Kaul	1-Feb-18	Caulking missing on air-exchanger vent at front elevation. Caulking degraded on the door. One damaged vinyl floor tile.
	HB 092		12-Nov-17	Amit Kaul	1-Feb-18	Caulking missing around the door frame.
	HB 120		12-Nov-17	Amit Kaul	1-Feb-18	Exterior caulking degraded on door. Exterior caulking missing around window frames and black staining observed on exposed wood at first window from the door. Caulking degraded on the door.
	HB 137		12-Nov-17	Amit Kaul	1-Feb-18	Caulking degraded on door. Exterior caulking missing on air-exchanger vent and top of windows at front elevation. Vinyl floor tiles (~2) missing near air-exchanger unit.
	HB 151		12-Nov-17	Amit Kaul	1-Feb-18	N.S.M.O.M.O.
	HB 172		12-Nov-17	Amit Kaul	1-Feb-18	Caulking degraded on the door. Caulking missing on air-exchanger vent at front elevation. Exterior caulking missing around window frames.
	HB 207		12-Nov-17	Amit Kaul	1-Feb-18	Screw holes observed on metal cladding under windows.
	HBL 210		12-Nov-17	Amit Kaul	1-Feb-18	Caulking degraded on air-exchanger vent at front elevation.
	HBL 211		12-Nov-17	Amit Kaul	1-Feb-18	Exterior caulking degraded at window. Vinyl floor tiles (~15) damaged throughout. Vinyl floor tiles (~4) missing and floor tiles (~20) damaged. Caulking degraded on gable louvres at right elevation.
	HBL 255 (1114)		12-Nov-17	Amit Kaul	1-Feb-18	Screw holes observed in metal cladding next to door at front elevation. Caulking missing around the window frames.
	HBL 256 (1362)		12-Nov-17	Amit Kaul	1-Feb-18	Hole (3") observed in drywall near footwear and clothing storage. Exterior caulking degraded at front door.
	J.W. Singleton Education Centre	HB 003	4	13-Dec-17	Amit Kaul	2-Feb-18
HB 117			13-Dec-17	Amit Kaul	2-Feb-18	Caulking degraded on windows at front elevation. Long tear (~3") in metal cladding at rear elevation. Long cut (~2") in metal cladding above windows.
HB 118			13-Dec-17	Amit Kaul	2-Feb-18	Downspout missing at rear elevation. Exterior caulking degraded on windows. Exterior caulking missing at front door.
HB 119			13-Dec-17	Amit Kaul	2-Feb-18	Stained ceiling tile observed at C-1. No suspect mould or moisture was observed.
John T. Tuck P.S.	HB 064	10	09-Dec-17	Amit Kaul	5-Feb-18	Vinyl floor tiles damaged (~12). Exterior caulking missing around window frames and the door frame.
	HB 122		09-Dec-17	Amit Kaul	5-Feb-18	Vinyl floor tiles damaged (~6). Rear downspout missing. Corner flashing damaged at front-left corner.
	HB 156		09-Dec-17	Amit Kaul	5-Feb-18	Vinyl floor tiles damaged (~15).
	HB 157		09-Dec-17	Amit Kaul	5-Feb-18	Downspout detached from eavestrough at front elevation. Caulking missing on door frames.
	HB 165		09-Dec-17	Amit Kaul	5-Feb-18	Downspout damaged at rear elevation.
	HB 173		09-Dec-17	Amit Kaul	5-Feb-18	Exterior caulking degraded at door. Ceiling tile missing above air-exchanger unit. Vinyl floor tiles (>15) damaged throughout. Sections of baseboard (~7") missing at rear elevation. Hole (2") in metal cladding at the left elevation. Interior caulking degraded on the windows.
	HBL 216		09-Dec-17	Amit Kaul	5-Feb-18	N.S.M.O.M.O.
	HBL 219		09-Dec-17	Amit Kaul	5-Feb-18	N.S.M.O.M.O.
HBL 220		09-Dec-17	Amit Kaul	5-Feb-18	N.S.M.O.M.O.	
HBL 221		09-Dec-17	Amit Kaul	5-Feb-18	N.S.M.O.M.O.	
John W. Boich P.S.	HB 108	3	14-Dec-17	Amit Kaul	6-Feb-18	N.S.M.O.M.O.
	HB 109		14-Dec-17	Amit Kaul	6-Feb-18	N.S.M.O.M.O.
	HBL 247		14-Dec-17	Amit Kaul	6-Feb-18	Caulking missing on air-exchanger vent at left elevation.

L.B. Pearson H.S.	RM 179 A/B	12	13-Dec-17	Amit Kaul	2-Feb-18	Suspect mould on few spots throughout the floor in Room 179A.
	RM 180		13-Dec-17	Amit Kaul	2-Feb-18	Vinyl floor tiles (~4) damaged. Vinyl floor tiles (~20) observed to be cracked throughout.
	RM 181		13-Dec-17	Amit Kaul	2-Feb-18	Exterior window caulking degraded. Suspect mould on front wall and left wall near the door.
	RM 182		13-Dec-17	Amit Kaul	2-Feb-18	Caulking degraded on air-exchanger. Suspect mould on left wall near the center of it.
	RM 183		13-Dec-17	Amit Kaul	2-Feb-18	Ceiling tile damaged next to the door. Suspect mould on the left wall near the door and few spots spread throughout the floor.
	RM 184		13-Dec-17	Amit Kaul	2-Feb-18	Stained ceiling tiles observed (~2). Vinyl floor tiles (~18) missing along right wall. Suspect mould on left wall next to door. Missing ceiling tiles (~2).
	RM 185		13-Dec-17	Amit Kaul	2-Feb-18	Suspect mould on few spots throughout the floor. Moisture on vapour barrier observed in ceiling tile C-2 (above the door).
	RM 186		13-Dec-17	Amit Kaul	2-Feb-18	Stained ceiling tiles (~2) observed next to door. Damaged vinyl floor tiles near door at front elevation. Vinyl floor tiles (~6) missing at front-right corner. Moisture on vapour barrier observed in the ceiling tile above the door.
	RM 187		13-Dec-17	Amit Kaul	2-Feb-18	Caulking degraded on air-exchanger unit.
	RM 188		13-Dec-17	Amit Kaul	2-Feb-18	Vinyl floor tiles (~6) missing at right elevation. One ceiling tile damaged.
	RM 189		13-Dec-17	Amit Kaul	2-Feb-18	Suspect mould on few spots throughout the floor.
	RM 190 A/B		13-Dec-17	Amit Kaul	2-Feb-18	Suspect mould on wall behind the door at right elevation in Room 190B.
Pineland P.S.	HB 069	1	14-Dec-17	Amit Kaul	6-Feb-18	Ceiling tile missing above air-exchanger.
Alton Village P.S.	HB 037	9	11-Dec-17	Amit Kaul	31-Jan-18	Exterior caulking missing around the window frames. Caulking missing on two conduits at left elevation.
	HB 068		11-Dec-17	Amit Kaul	31-Jan-18	Caulking missing around the door frame and on air-exchanger.
	HBL 225		11-Dec-17	Amit Kaul	31-Jan-18	N.S.M.O.M.O.
	HBL 234		11-Dec-17	Amit Kaul	31-Jan-18	N.S.M.O.M.O.
	HBL 235		11-Dec-17	Amit Kaul	31-Jan-18	Caulking missing on air-exchanger vent at front elevation. Caulking degraded on the door. One damaged vinyl floor tile.
	HBL 236		11-Dec-17	Amit Kaul	31-Jan-18	Caulking missing around the door frame.
	HBL 237		11-Dec-17	Amit Kaul	31-Jan-18	Exterior caulking degraded on door. Exterior caulking missing around window frames and black staining observed on exposed wood at first window from the door. Caulking degraded on the door.
	HBL 238		11-Dec-17	Amit Kaul	31-Jan-18	Caulking degraded on door. Exterior caulking missing on air-exchanger vent and top of windows at front elevation. Vinyl floor tiles (~2) missing near air- exchanger unit.
	HBL 239		11-Dec-17	Amit Kaul	31-Jan-18	N.S.M.O.M.O.
Florence Meares P.S.	HB 139	1	12-Dec-17	Amit Kaul	1-Feb-18	Caulking degraded on the door. Caulking missing on air-exchanger vent at front elevation. Exterior caulking missing around window frames.
Kilbride P.S.	HB 074	1	21-Nov-17	Amit Kaul	18-Jan-18	Screw holes observed on metal cladding under windows.
Orchard Park P.S.	HB 040	3	14-Dec-17	Amit Kaul	30-Jan-18	Caulking degraded on air-exchanger vent at front elevation.
	HB 140		14-Dec-17	Amit Kaul	30-Jan-18	Exterior caulking degraded at window. Vinyl floor tiles (~15) damaged throughout. Vinyl floor tiles (~4) missing and floor tiles (~20) damaged. Caulking degraded on gable louvres at right elevation.
	HB 166		14-Dec-17	Amit Kaul	30-Jan-18	Screw holes observed in metal cladding next to door at front elevation. Caulking missing around the window frames.
Pauline Johnson P.S.	HB 024	3	14-Dec-17	Amit Kaul	6-Feb-18	Hole (3") observed in drywall near footwear and clothing storage. Exterior caulking degraded at front door.
	HB 102		14-Dec-17	Amit Kaul	6-Feb-18	Ceiling tile missing above air-exchanger unit at rear elevation. Caulking degraded on air-conditioner and air conditioner.
	HBL 222		14-Dec-17	Amit Kaul	6-Feb-18	Caulking degraded on windows at front elevation. Long tear (~3") in metal cladding at rear elevation. Long cut (~2") in metal cladding above windows.
Tom Thompson P.S.	HB 012	8	12-Dec-17	Amit Kaul	5-Feb-18	Downspout missing at rear elevation. Exterior caulking degraded on windows. Exterior caulking missing at front door.
	HB 031		12-Dec-17	Amit Kaul	5-Feb-18	Stained ceiling tile observed at C-1. No suspect mould or moisture was observed.
	HB 098		12-Dec-17	Amit Kaul	5-Feb-18	Vinyl floor tiles damaged (~12). Exterior caulking missing around window frames and the door frame.
	HB 105		12-Dec-17	Amit Kaul	5-Feb-18	N.S.M.O.M.O.
	HB 124		12-Dec-17	Amit Kaul	5-Feb-18	Vinyl floor tiles damaged (~15).
	HB 141		12-Dec-17	Amit Kaul	5-Feb-18	Downspout detached from eavestrough at front elevation. Caulking missing on door frames.

	HB 148		12-Dec-17	Amit Kaul	5-Feb-18	Roof flashing damaged at left elevation. Damaged vinyl floor tiles (~6).
	HB 169		12-Dec-17	Amit Kaul	5-Feb-18	Exterior caulking degraded at door. Ceiling tile missing above air-exchanger unit. Vinyl floor tiles (>15) damaged throughout. Sections of baseboard (~7') missing at rear elevation. Hole (2") in metal cladding at the left elevation. Interior caulking degraded on the windows.
Total Portables		70				

Notes:			
Scheduled inspection date subject to change due to availability of manpower and the facility.			
<b>N.S.M.O.M.O. =</b>	No Suspect Mould Or Moisture Observed		



School	Portable Number	Portables on Site	Round 104 Inspection Date	Arcadis Inspector	Proposed Round 105 Inspection Date	Comments from Round 104 Inspection
Abbey Park H.S.	HB 053	7	30-Nov-17	Amit Kaul	23-Jan-18	Caulking degraded on air-exchanger and on the door. Baseboard (~3') detached at front and rear elevations.
	HB 108		30-Nov-17	Amit Kaul	23-Jan-18	Caulking missing around the door frame and on air-exchanger.
	HB 163		30-Nov-17	Amit Kaul	23-Jan-18	N.S.M.O.M.O.
	HB 164		30-Nov-17	Amit Kaul	23-Jan-18	Caulking degraded on air conditioner. Exterior caulking degraded on 2nd window from the door. Rear downspout detached.
	HB 177		30-Nov-17	Amit Kaul	23-Jan-18	Caulking missing on air-exchanger vent at front elevation. Caulking degraded on the door. One damaged vinyl floor tile.
	HB 206		30-Nov-17	Amit Kaul	23-Jan-18	Caulking missing around the door frame.
	HBL 224		30-Nov-17	Amit Kaul	23-Jan-18	Exterior caulking degraded on door. Exterior caulking missing around window frames and black staining observed on exposed wood at first window from the door. Caulking degraded on the door.
E.J. James P.S.	HB 061	5	29-Nov-17	Amit Kaul	22-Jan-18	Caulking degraded on door. Exterior caulking missing on air-exchanger vent and top of windows at front elevation. Vinyl floor tiles (~2) missing near air-exchanger unit.
	HB 111		29-Nov-17	Amit Kaul	22-Jan-18	N.S.M.O.M.O.
	HB 121		29-Nov-17	Amit Kaul	22-Jan-18	Caulking degraded on the door. Caulking missing on air-exchanger vent at front elevation. Exterior caulking missing around window frames.
	HBL 009		29-Nov-17	Amit Kaul	22-Jan-18	Screw holes observed on metal cladding under windows.
	HBL 085		29-Nov-17	Amit Kaul	22-Jan-18	Caulking degraded on air-exchanger vent at front elevation.
Iroquois Ridge H.S.	HB 070	5	29-Nov-17	Amit Kaul	19-Jan-18	Exterior caulking degraded at window. Vinyl floor tiles (~15) damaged throughout. Vinyl floor tiles (~4) missing and floor tiles (~20) damaged. Caulking degraded on gable louvres at right elevation.
	HB 088		29-Nov-17	Amit Kaul	19-Jan-18	Screw holes observed in metal cladding next to door at front elevation. Caulking missing around the window frames.
	HB 202		29-Nov-17	Amit Kaul	19-Jan-18	Hole (3") observed in drywall near footwear and clothing storage. Exterior caulking degraded at front door.
	HB 209		29-Nov-17	Amit Kaul	19-Jan-18	Ceiling tile missing above air-exchanger unit at rear elevation. Caulking degraded on air-conditioner and air conditioner.
	HBL 262		29-Nov-17	Amit Kaul	19-Jan-18	Caulking degraded on windows at front elevation. Long tear (~3") in metal cladding at rear elevation. Long cut (~2") in metal cladding above windows.
James W. Hill P.S.	HB 050	6	27-Nov-17	Amit Kaul	19-Jan-18	Downspout missing at rear elevation. Exterior caulking degraded on windows. Exterior caulking missing at front door.
	HB 054		27-Nov-17	Amit Kaul	19-Jan-18	Stained ceiling tile observed at C-1. No suspect mould or moisture was observed.
	HB 080		27-Nov-17	Amit Kaul	19-Jan-18	Vinyl floor tiles damaged (~12). Exterior caulking missing around window frames and the door frame.
	HB 086		27-Nov-17	Amit Kaul	19-Jan-18	Damaged vinyl floor tiles (~2). One ceiling tile damaged and One ceiling tile missing. Hole (2"x3") in drywall at rear elevation.
	HB 099		27-Nov-17	Amit Kaul	19-Jan-18	Vinyl floor tiles damaged (~15).
	HB 176		27-Nov-17	Amit Kaul	19-Jan-18	Downspout detached from eavestrough at front elevation. Caulking missing on door frames.
Joshua Creek P.S.	HB 011	4	27-Nov-17	Amit Kaul	19-Jan-18	N.S.M.O.M.O.
	HB 077		27-Nov-17	Amit Kaul	19-Jan-18	Exterior caulking degraded at door. Ceiling tile missing above air-exchanger unit. Vinyl floor tiles (>15) damaged throughout. Sections of baseboard (~7') missing at rear elevation. Hole (2") in metal cladding at the left elevation. Interior caulking degraded on the windows.
	HB 085		27-Nov-17	Amit Kaul	19-Jan-18	N.S.M.O.M.O.
	HB 160		27-Nov-17	Amit Kaul	19-Jan-18	Hole (1") in metal cladding at rear elevation. One stained ceiling tile (new). Damaged vinyl floor tiles (~2).
Munn's P.S.	HBL 001	2	08-Dec-17	Amit Kaul	29-Jan-18	Exterior caulking missing around the window frames. Corner flashing damaged at rear elevation.
	HBL 002		08-Dec-17	Amit Kaul	29-Jan-18	Exterior caulking missing around the window frames. Caulking degraded on conduits at right elevation.
Oakville Trafalgar H.S.	RM 189A	12	29-Nov-17	Amit Kaul	22-Jan-18	N.S.M.O.M.O.
	RM 189 B		29-Nov-17	Amit Kaul	22-Jan-18	N.S.M.O.M.O.

	RM 190		29-Nov-17	Amit Kaul	22-Jan-18	Caulking missing on air-exchanger vent at left elevation.
	RM 191		29-Nov-17	Amit Kaul	22-Jan-18	N.S.M.O.M.O.
	RM 192		29-Nov-17	Amit Kaul	22-Jan-18	Vinyl floor tiles (~4) damaged. Vinyl floor tiles (~20) observed to be cracked throughout.
	RM 193		29-Nov-17	Amit Kaul	22-Jan-18	N.S.M.O.M.O.
	RM 194		29-Nov-17	Amit Kaul	22-Jan-18	One damaged vinyl floor tile.
	RM 195		29-Nov-17	Amit Kaul	22-Jan-18	N.S.M.O.M.O.
	RM 196		29-Nov-17	Amit Kaul	22-Jan-18	Stained ceiling tiles observed (~2). Vinyl floor tiles (~18) missing along right wall. Suspect mould on left wall next to door. Missing ceiling tiles (~2).
	RM 197		29-Nov-17	Amit Kaul	22-Jan-18	N.S.M.O.M.O.
	RM 198		29-Nov-17	Amit Kaul	22-Jan-18	Stained ceiling tiles (~2) observed next to door. Damaged vinyl floor tiles near door at front elevation. Vinyl floor tiles (~6) missing at front-right corner. Moisture on vapour barrier observed in the ceiling tile above the door.
	RM 199		29-Nov-17	Amit Kaul	22-Jan-18	Caulking degraded on air-exchanger unit.
Captain R. Wilson P.S.	HB 014	4	13-Dec-17	Amit Kaul	30-Jan-18	Rear downspout detached from eavestrough. Screw holes (2) at rear elevation. Hole (~ 2") in left drywall under shelves.
	HB 047		13-Dec-17	Amit Kaul	30-Jan-18	Caulking missing around the door frame and on air-exchanger.
	HB 065		13-Dec-17	Amit Kaul	30-Jan-18	Rear downspout missing. One damaged vinyl floor tile.
	HB 106		13-Dec-17	Amit Kaul	30-Jan-18	Damaged vinyl floor tiles (~9) along center seam. Caulking degraded on air exchanger. Screw holes in metal cladding near the corner flashing at rear elevation. Screw holes (4) in metal cladding near the front door.
Emily Carr P.S.	HB 147	5	30-Nov-17	Amit Kaul	23-Jan-18	Caulking missing on air-exchanger vent at front elevation. Caulking degraded on the door. One damaged vinyl floor tile.
	HBL 006		30-Nov-17	Amit Kaul	23-Jan-18	Caulking missing around the door frame.
	HBL 008		30-Nov-17	Amit Kaul	23-Jan-18	Exterior caulking degraded on door. Exterior caulking missing around window frames and black staining observed on exposed wood at first window from the door. Caulking degraded on the door.
	HBL 084		30-Nov-17	Amit Kaul	23-Jan-18	Caulking degraded on door. Exterior caulking missing on air-exchanger vent and top of windows at front elevation. Vinyl floor tiles (~2) missing near air- exchanger unit.
	HBL 217		30-Nov-17	Amit Kaul	23-Jan-18	N.S.M.O.M.O.
Oodenawi P.S.	HB 044	12	08-Dec-17	Amit Kaul	29-Jan-18	Caulking degraded on the door. Caulking missing on air-exchanger vent at front elevation. Exterior caulking missing around window frames.
	HB 058		08-Dec-17	Amit Kaul	29-Jan-18	Screw holes observed on metal cladding under windows.
	HB 067		08-Dec-17	Amit Kaul	29-Jan-18	Caulking degraded on air-exchanger vent at front elevation.
	HB 094		08-Dec-17	Amit Kaul	29-Jan-18	Exterior caulking degraded at window. Vinyl floor tiles (~15) damaged throughout. Vinyl floor tiles (~4) missing and floor tiles (~20) damaged. Caulking degraded on gable louvres at right elevation.
	HB 096		08-Dec-17	Amit Kaul	29-Jan-18	Screw holes observed in metal cladding next to door at front elevation. Caulking missing around the window frames.
	HB 101		08-Dec-17	Amit Kaul	29-Jan-18	Hole (3") observed in drywall near footwear and clothing storage. Exterior caulking degraded at front door.
	HB 128		08-Dec-17	Amit Kaul	29-Jan-18	Ceiling tile missing above air-exchanger unit at rear elevation. Caulking degraded on air-conditioner and air conditioner.
	HB 171		08-Dec-17	Amit Kaul	29-Jan-18	Caulking degraded on windows at front elevation. Long tear (~3") in metal cladding at rear elevation. Long cut (~2") in metal cladding above windows.
	HB 175		08-Dec-17	Amit Kaul	29-Jan-18	Downspout missing at rear elevation. Exterior caulking degraded on windows. Exterior caulking missing at front door.
	HBL 086		08-Dec-17	Amit Kaul	29-Jan-18	Stained ceiling tile observed at C-1. No suspect mould or moisture was observed.
	HBL 248		08-Dec-17	Amit Kaul	29-Jan-18	Vinyl floor tiles damaged (~12). Exterior caulking missing around window frames and the door frame.
	HBL 260		08-Dec-17	Amit Kaul	29-Jan-18	Caulking missing at air-exchanger vent at left elevation.
	Palermo P.S.	HB 087	4	14-Dec-17	Amit Kaul	30-Jan-18
HB 167			14-Dec-17	Amit Kaul	30-Jan-18	Downspout detached from eavestrough at front elevation. Caulking missing on door frames.
HB 168			14-Dec-17	Amit Kaul	30-Jan-18	Exterior caulking degraded on windows at front elevation. Downspout detached from eavestrough at rear elevation and lower part of the downspout missing. Hole (~2") in metal cladding at rear elevation.

	HB 170		14-Dec-17	Amit Kaul	30-Jan-18	Exterior caulking degraded at door. Ceiling tile missing above air-exchanger unit. Vinyl floor tiles (>15) damaged throughout. Sections of baseboard (~7') missing at rear elevation. Hole (2") in metal cladding at the left elevation. Interior caulking degraded on the windows.
Pine Grove P.S.	HB 043	2	04-Dec-17	Amit Kaul	25-Jan-18	Hole (~2") in metal cladding next to conduits at right elevation. Exterior caulking missing around window frames.
	HB 131		04-Dec-17	Amit Kaul	25-Jan-18	Caulking degraded at air-exchanger vent at right elevation. Screw holes (2) at right elevation. Exterior caulking degraded on the first window from the door.
W.H. Morden P.S.	HB 055	10	04-Dec-17	Amit Kaul	25-Jan-18	Flashing above the door missing and exterior sheeting exposed.
	HB 097		04-Dec-17	Amit Kaul	25-Jan-18	Exterior caulking degraded on air exchanger, windows and the door. Vinyl floor tiles (~4) missing and subfloor exposed.
	HB 138		04-Dec-17	Amit Kaul	25-Jan-18	Rear downspout detached from eavestrough. Baseboard (~7') missing on left drywall.
	HB 199		04-Dec-17	Amit Kaul	25-Jan-18	Exterior caulking degraded on air exchanger, windows and the door.
	HB 200		04-Dec-17	Amit Kaul	25-Jan-18	Caulking missing on air-exchanger vent at left elevation.
	HBL 006		04-Dec-17	Amit Kaul	25-Jan-18	Screw holes (~8) on metal cladding observed at left elevation. Screw holes (4) in metal cladding near the door at front elevation.
	HBL 007		04-Dec-17	Amit Kaul	25-Jan-18	Vinyl floor tiles (~4) damaged. Vinyl floor tiles (~20) observed to be cracked throughout.
	HBL 201		04-Dec-17	Amit Kaul	25-Jan-18	N.S.M.O.M.O.
	HBL 249		04-Dec-17	Amit Kaul	25-Jan-18	Damaged vinyl floor tiles (~10). Exterior caulking degraded on the middle window. Exterior caulking missing around the window frame.
	HBL 250		04-Dec-17	Amit Kaul	25-Jan-18	Exterior caulking degraded on the first two windows from the door. Vinyl floor tiles damaged (~8).
West Oak P.S.	RM 1	10	07-Dec-17	Amit Kaul	26-Jan-18	Stained ceiling tiles observed (~2). Vinyl floor tiles (~18) missing along right wall. Suspect mould on left wall next to door. Missing ceiling tiles (~2).
	RM 2		07-Dec-17	Amit Kaul	26-Jan-18	N.S.M.O.M.O.
	RM 3		07-Dec-17	Amit Kaul	26-Jan-18	Stained ceiling tiles (~2) observed next to door. Damaged vinyl floor tiles near door at front elevation. Vinyl floor tiles (~6) missing at front-right corner. Moisture on vapour barrier observed in the ceiling tile above the door.
	RM 4		07-Dec-17	Amit Kaul	26-Jan-18	Caulking degraded on air-exchanger unit.
	RM 5		07-Dec-17	Amit Kaul	26-Jan-18	N.S.M.O.M.O.
	RM 6		07-Dec-17	Amit Kaul	26-Jan-18	N.S.M.O.M.O.
	WR		07-Dec-17	Amit Kaul	26-Jan-18	N.S.M.O.M.O.
	HB 072		07-Dec-17	Amit Kaul	26-Jan-18	Caulking degraded on air exchanger and air conditioner. Damaged vinyl floor tiles (~4) near the door. Screw holes in metal cladding near the door.
	HB 107		07-Dec-17	Amit Kaul	26-Jan-18	Vinyl floor tiles (~4) damaged and vinyl floor tiles (~10) cracked.
	HB 145		07-Dec-17	Amit Kaul	26-Jan-18	Caulking missing on conduits at right elevation. Damaged vinyl floor tiles (~3). Screw holes in metal cladding at right, rear, and front elevations.
White Oaks Centre for Science and Technology (North Campus)	HB 060	5	01-Dec-17	Amit Kaul	26-Jan-18	Eavestrough damaged at rear elevation. Stained ceiling tile observed above air-exchanger unit (new).
	HBL 92		01-Dec-17	Amit Kaul	26-Jan-18	Exterior caulking degraded on windows. Two 2" holes in metal cladding at right elevation (near conduits).
	HBL 93		01-Dec-17	Amit Kaul	26-Jan-18	N.S.M.O.M.O.
	HBL 94		01-Dec-17	Amit Kaul	26-Jan-18	N.S.M.O.M.O.
	HBL 95		01-Dec-17	Amit Kaul	26-Jan-18	N.S.M.O.M.O.
White Oaks School Admin. (South Campus)	HB 023	12	01-Dec-17	Amit Kaul	24-Jan-18	Hole (2") observed on metal cladding next to conduit at right elevation. Two 3' drywall panel capping missing under windows at front elevation.
	HB 042		01-Dec-17	Amit Kaul	24-Jan-18	Drywall panel capping (3') missing under windows at front elevation.
	HB 078		01-Dec-17	Amit Kaul	24-Jan-18	N.S.M.O.M.O.
	HB 112		01-Dec-17	Amit Kaul	24-Jan-18	Vinyl paper on drywall damaged at rear elevation. Hole (1") in drywall at rear elevation.
	HB 153		01-Dec-17	Amit Kaul	24-Jan-18	Minor hole (~2") observed on drywall at left wall. Damaged vinyl floor tiles (~4) observed at entrance.
	HB 201		01-Dec-17	Amit Kaul	24-Jan-18	Vinyl floor tiles (~6) damaged near the door. Baseboard detached at front elevation.

	HB 205		01-Dec-17	Amit Kaul	24-Jan-18	Cover missing at IP-1 (tape was used to seal the port). Damaged vinyl floor tiles (~10). Sections of baseboard (~3') detached at rear elevation.
	HBL 016		01-Dec-17	Amit Kaul	24-Jan-18	N.S.M.O.M.O.
	HBL 017		01-Dec-17	Amit Kaul	24-Jan-18	Eavestrough detached (~3') from side roof flashing at front elevation. Exterior caulking degraded on the window next to door.
	HBL 018		01-Dec-17	Amit Kaul	24-Jan-18	Eavestrough detached (~6') from roof edge at rear elevation.
	HBL 096		01-Dec-17	Amit Kaul	24-Jan-18	N.S.M.O.M.O.
	HBL 097		01-Dec-17	Amit Kaul	24-Jan-18	N.S.M.O.M.O.
Total Portables		105				

Notes:			
Scheduled inspection date subject to change due to availability of manpower and the facility.			
<b>N.S.M.O.M.O. =</b>	No Suspect Mould Or Moisture Observed		