

**TABLE 1
PORTABLE CLASSROOM PREVENTATIVE MAINTENANCE INSPECTION NO. 93 SUMMARY**

School	Portable Number	Portables on Site	PM Inspection Schedule		Proposed Round 94 Inspections Date	Comments from Round 93 Inspection
			Round 93 Inspection Date	ARCADIS Inspector		
Anne J. MacArthur P.S.	HB 026	18	26-May-15	S.Parliament	24-Jul-15	N.S.M.O.M.O.
	HB 041		26-May-15	S.Parliament	24-Jul-15	Caulking degraded at door and conduits. Roof edge flashing detached at right elevation. Hole in drywall (~2") observed in northeast wall. Stained ceiling tiles (~2) observed in southwest section of portable.
	HB 066		26-May-15	S.Parliament	24-Jul-15	N.S.M.O.M.O.
	HB 071		26-May-15	S.Parliament	24-Jul-15	N.S.M.O.M.O.
	HB 113		26-May-15	S.Parliament	24-Jul-15	N.S.M.O.M.O.
	HB 125		26-May-15	S.Parliament	24-Jul-15	N.S.M.O.M.O.
	HB 127		26-May-15	S.Parliament	24-Jul-15	N.S.M.O.M.O.
	HB 195		26-May-15	S.Parliament	24-Jul-15	N.S.M.O.M.O.
	HB 204		26-May-15	S.Parliament	24-Jul-15	Exterior caulking degraded at door and second window. Stained ceiling tile (~1) observed
	HBL 111		26-May-15	S.Parliament	24-Jul-15	N.S.M.O.M.O.
	HBL 202		26-May-15	S.Parliament	24-Jul-15	N.S.M.O.M.O.
	HBL 203		26-May-15	S.Parliament	24-Jul-15	N.S.M.O.M.O.
	HBL 204		26-May-15	S.Parliament	24-Jul-15	N.S.M.O.M.O.
	HBL 205		26-May-15	S.Parliament	24-Jul-15	N.S.M.O.M.O.
	HBL 214		26-May-15	S.Parliament	24-Jul-15	Screw holes observed in corner flashings at right elevation.
	HBL 215		26-May-15	S.Parliament	24-Jul-15	N.S.M.O.M.O.
	HBL 232		26-May-15	S.Parliament	24-Jul-15	N.S.M.O.M.O.
	HBL 233		26-May-15	S.Parliament	24-Jul-15	Screw holes observed in metal cladding at left elevation. Exterior caulking degraded at door.
Brookville P.S.	HBL 201	1	04-Jun-15	S.Parliament	12-Aug-15	N.S.M.O.M.O.
Bruce Trail P.S.	HB 046	13	08-Jun-15	D.Kellyman	4-Aug-15	Exterior caulking degraded at second window.
	HB 062		08-Jun-15	D.Kellyman	4-Aug-15	N.S.M.O.M.O.
	HB 075		08-Jun-15	D.Kellyman	4-Aug-15	Exterior caulking degraded at both windows. Vinyl floor tiles (~4) damaged throughout.
	HB 103		08-Jun-15	D.Kellyman	4-Aug-15	Exterior caulking degraded at door.
	HB 110		08-Jun-15	D.Kellyman	4-Aug-15	N.S.M.O.M.O.
	HB 114		08-Jun-15	D.Kellyman	4-Aug-15	N.S.M.O.M.O.
	HB 115		08-Jun-15	D.Kellyman	4-Aug-15	Screw holes/tears observed in metal cladding at front and left walls (existing). Exterior caulking degraded at conduit.
	HB 149		08-Jun-15	D.Kellyman	4-Aug-15	Hole (.5") and screw holes observed in metal cladding at front elevation.
	HBL 105		08-Jun-15	D.Kellyman	4-Aug-15	N.S.M.O.M.O.
	HBL 228		08-Jun-15	D.Kellyman	4-Aug-15	N.S.M.O.M.O.
	HBL 229		08-Jun-15	D.Kellyman	4-Aug-15	N.S.M.O.M.O.
	HBL 230		08-Jun-15	D.Kellyman	4-Aug-15	N.S.M.O.M.O.
	HBL 231		08-Jun-15	D.Kellyman	4-Aug-15	N.S.M.O.M.O.
Chris Hadfield P.S.	RM A1	12	04-Jun-15	S.Parliament	12-Aug-15	N.S.M.O.M.O.
	RM A2		04-Jun-15	S.Parliament	12-Aug-15	N.S.M.O.M.O.
	RM A3		04-Jun-15	S.Parliament	12-Aug-15	N.S.M.O.M.O.
	RM A4		04-Jun-15	S.Parliament	12-Aug-15	N.S.M.O.M.O.
	RM A5		04-Jun-15	S.Parliament	12-Aug-15	Exterior caulking degraded at second window.
	RM A6		04-Jun-15	S.Parliament	12-Aug-15	N.S.M.O.M.O.
	RM A7		04-Jun-15	S.Parliament	12-Aug-15	N.S.M.O.M.O.
	RM A8		04-Jun-15	S.Parliament	12-Aug-15	N.S.M.O.M.O.
	RM A9		04-Jun-15	S.Parliament	12-Aug-15	N.S.M.O.M.O.
	RM A10		04-Jun-15	S.Parliament	12-Aug-15	N.S.M.O.M.O.
	RM A11		04-Jun-15	S.Parliament	12-Aug-15	N.S.M.O.M.O.
	HBL 106		04-Jun-15	S.Parliament	12-Aug-15	N.S.M.O.M.O.
Craig Kielburger S.S.	HB 038	16	03-Jun-15	S.Parliament	11-Aug-15	N.S.M.O.M.O.
	HB 045		03-Jun-15	S.Parliament	11-Aug-15	N.S.M.O.M.O.
	HB 056		03-Jun-15	S.Parliament	11-Aug-15	N.S.M.O.M.O.
	HB 057		03-Jun-15	S.Parliament	11-Aug-15	N.S.M.O.M.O.
	HB 073		03-Jun-15	S.Parliament	11-Aug-15	Suspect mould observed on interior side of drywall and moisture observed on bottom plate, framing, insulation and vapour barrier IP-I and IP-II .

**TABLE 1
PORTABLE CLASSROOM PREVENTATIVE MAINTENANCE INSPECTION NO. 93 SUMMARY**

School	Portable Number	Portables on Site	PM Inspection Schedule		Proposed Round 94 Inspections Date	Comments from Round 93 Inspection
			Round 93 Inspection Date	ARCADIS Inspector		
	HB 090		03-Jun-15	S.Parliament	11-Aug-15	N.S.M.O.M.O.
	HB 091		03-Jun-15	S.Parliament	11-Aug-15	Stained ceiling tile observed.
	HB 100		03-Jun-15	S.Parliament	11-Aug-15	Hole (~2") observed in wooden sheathing and metal cladding.
	HB 133		03-Jun-15	S.Parliament	11-Aug-15	N.S.M.O.M.O.
	HB 134		03-Jun-15	S.Parliament	11-Aug-15	N.S.M.O.M.O.
	HB 135		03-Jun-15	S.Parliament	11-Aug-15	Exterior caulking degraded at door, air-exchanger vent and conduit. Screw holes observed in metal cladding at rear and left elevations.
	HB 143		03-Jun-15	S.Parliament	11-Aug-15	N.S.M.O.M.O.
	HB 203		03-Jun-15	S.Parliament	11-Aug-15	Exterior caulking degraded at second window.
	HBL 005		03-Jun-15	S.Parliament	11-Aug-15	N.S.M.O.M.O.
	HBL 080		03-Jun-15	S.Parliament	11-Aug-15	N.S.M.O.M.O.
	HBL 084		03-Jun-15	S.Parliament	11-Aug-15	N.S.M.O.M.O.
E.W. Foster P.S.	HB 129	5	02-Jun-15	S.Parliament	10-Aug-15	N.S.M.O.M.O.
	HB 160		02-Jun-15	S.Parliament	10-Aug-15	Corner flashing at left elevation detached and damaged.
	HB 180		02-Jun-15	S.Parliament	10-Aug-15	N.S.M.O.M.O.
	HB 189		02-Jun-15	S.Parliament	10-Aug-15	N.S.M.O.M.O.
	HBL 086		02-Jun-15	S.Parliament	10-Aug-15	N.S.M.O.M.O.
Escarpment View P.S.	HBL 212	14	21-May-15	C. Jagarnauth	6-Aug-15	N.S.M.O.M.O.
	HBL 213		21-May-15	C. Jagarnauth	6-Aug-15	N.S.M.O.M.O.
	HBL 103		21-May-15	C. Jagarnauth	6-Aug-15	N.S.M.O.M.O.
	HB 005		21-May-15	C. Jagarnauth	6-Aug-15	N.S.M.O.M.O.
	HB 089		21-May-15	C. Jagarnauth	6-Aug-15	N.S.M.O.M.O.
	HB 144		21-May-15	C. Jagarnauth	6-Aug-15	N.S.M.O.M.O.
	HBL 081		21-May-15	C. Jagarnauth	6-Aug-15	N.S.M.O.M.O.
	HBL 082		21-May-15	C. Jagarnauth	6-Aug-15	N.S.M.O.M.O.
	HBL 083		21-May-15	C. Jagarnauth	6-Aug-15	N.S.M.O.M.O.
	HBL 088		21-May-15	C. Jagarnauth	6-Aug-15	N.S.M.O.M.O.
	HBL 090		21-May-15	C. Jagarnauth	6-Aug-15	N.S.M.O.M.O.
	HBL 091		21-May-15	C. Jagarnauth	6-Aug-15	N.S.M.O.M.O.
	HBL 104		21-May-15	C. Jagarnauth	6-Aug-15	N.S.M.O.M.O.
	HBL 089		21-May-15	C. Jagarnauth	6-Aug-15	N.S.M.O.M.O.
Gardiner P.S.	HBL 207	1	28-May-15	S.Parliament	3-Aug-15	N.S.M.O.M.O.
Glen Williams P.S.	HB 178	2	28-May-15	S.Parliament	3-Aug-15	N.S.M.O.M.O.
	HB 184		28-May-15	S.Parliament	3-Aug-15	N.S.M.O.M.O.
Hawthorne Village P.S.	HB 013	22	11-Jun-15	S.Parliament	13-Aug-15	Screw holes observed in metal cladding at front elevation.
	HB 034		11-Jun-15	S.Parliament	13-Aug-15	N.S.M.O.M.O.
	HB 035		11-Jun-15	S.Parliament	13-Aug-15	N.S.M.O.M.O.
	HB 036		11-Jun-15	S.Parliament	13-Aug-15	N.S.M.O.M.O.
	HB 136		11-Jun-15	S.Parliament	13-Aug-15	N.S.M.O.M.O.
	HB 155		11-Jun-15	S.Parliament	13-Aug-15	Vinyl floor tiles (~5) damaged throughout.
	HB 162		11-Jun-15	S.Parliament	13-Aug-15	N.S.M.O.M.O.
	RM 101		10-Jun-15	S.Parliament	13-Aug-15	N.S.M.O.M.O.
	RM 102		10-Jun-15	S.Parliament	13-Aug-15	Stained ceiling tile (~1) observed.
	RM 103		10-Jun-15	S.Parliament	13-Aug-15	N.S.M.O.M.O.
	RM 104		10-Jun-15	S.Parliament	13-Aug-15	N.S.M.O.M.O.
	RM 105		10-Jun-15	S.Parliament	13-Aug-15	N.S.M.O.M.O.
	RM 301		10-Jun-15	S.Parliament	13-Aug-15	N.S.M.O.M.O.
	RM 302		10-Jun-15	S.Parliament	13-Aug-15	N.S.M.O.M.O.
	RM 303		10-Jun-15	S.Parliament	13-Aug-15	N.S.M.O.M.O.
	RM 304		10-Jun-15	S.Parliament	13-Aug-15	N.S.M.O.M.O.
	RM 305		10-Jun-15	S.Parliament	13-Aug-15	N.S.M.O.M.O.

**TABLE 1
PORTABLE CLASSROOM PREVENTATIVE MAINTENANCE INSPECTION NO. 93 SUMMARY**

School	Portable Number	Portables on Site	PM Inspection Schedule		Proposed Round 94 Inspections Date	Comments from Round 93 Inspection
			Round 93 Inspection Date	ARCADIS Inspector		
	RM 306		10-Jun-15	S.Parliament	13-Aug-15	N.S.M.O.M.O.
	RM 307		10-Jun-15	S.Parliament	13-Aug-15	N.S.M.O.M.O.
	RM 308		10-Jun-15	S.Parliament	13-Aug-15	N.S.M.O.M.O.
	RM 309		10-Jun-15	S.Parliament	13-Aug-15	N.S.M.O.M.O.
	RM 310		10-Jun-15	S.Parliament	13-Aug-15	N.S.M.O.M.O.
Irma Coulson P.S.	HB 009	10	25-May-15	S.Parliament	27-Jul-15	N.S.M.O.M.O.
	HB 081		25-May-15	S.Parliament	27-Jul-15	N.S.M.O.M.O.
	HB 142		25-May-15	S.Parliament	27-Jul-15	N.S.M.O.M.O.
	HB 146		25-May-15	S.Parliament	27-Jul-15	Screw holes observed in metal cladding and corner flashing at right elevation.
	HB 150		25-May-15	S.Parliament	27-Jul-15	Eavestrough (~5') damaged and/or detached at front elevation.
	HBL 242		25-May-15	S.Parliament	27-Jul-15	N.S.M.O.M.O.
	HBL 243		25-May-15	S.Parliament	27-Jul-15	Exterior caulking degraded at door.
	HBL 244		25-May-15	S.Parliament	27-Jul-15	N.S.M.O.M.O.
	HBL 245		25-May-15	S.Parliament	27-Jul-15	Screw holes observed in metal cladding at front elevation.
	HBL 246		25-May-15	S.Parliament	27-Jul-15	N.S.M.O.M.O.
Martin Street P.S.	HB 015	2	27-May-15	S.Parliament	20-Aug-15	N.S.M.O.M.O.
	HB 152		27-May-15	S.Parliament	20-Aug-15	Exterior caulking missing at front door.
Milton District H.S.	HB 001	3	01-Jun-15	S.Parliament	5-Aug-15	Vent damaged at left side of portable (existing).
	HB 093		01-Jun-15	S.Parliament	5-Aug-15	Section of metal cladding (4"x4") damaged underneath light at left elevation.
	HB 154		01-Jun-15	S.Parliament	5-Aug-15	N.S.M.O.M.O.
P.L. Robertson P.S.	HB 004	7	27-May-15	S.Parliament	20-Aug-15	N.S.M.O.M.O.
	HB 016		27-May-15	S.Parliament	20-Aug-15	Exterior caulking degraded at air-exchanger vent.
	HB 021		27-May-15	S.Parliament	20-Aug-15	N.S.M.O.M.O.
	HB 022		27-May-15	S.Parliament	20-Aug-15	Caulking degraded at front right downspout.
	HB 027		27-May-15	S.Parliament	20-Aug-15	Stained ceiling tile (~1) observed.
	HB 030		27-May-15	S.Parliament	20-Aug-15	Hole (~1") observed in metal cladding at right elevation.
	HB 039		27-May-15	S.Parliament	20-Aug-15	Screws protruding from metal cladding at rear elevation.
Park P.S.	HB 048	1	28-May-15	S.Parliament	3-Aug-15	N.S.M.O.M.O.
Robert Baldwin P.S.	HB 122	4	02-Jun-15	S.Parliament	10-Aug-15	N.S.M.O.M.O.
	HB 174		02-Jun-15	S.Parliament	10-Aug-15	N.S.M.O.M.O.
	HBL 079		02-Jun-15	S.Parliament	10-Aug-15	N.S.M.O.M.O.
	HBL 248 (1072)		02-Jun-15	S.Parliament	10-Aug-15	N.S.M.O.M.O.
Robert Little P.S.	HB 208	2	28-May-15	S.Parliament	3-Aug-15	N.S.M.O.M.O.
	HBL 10		28-May-15	S.Parliament	3-Aug-15	N.S.M.O.M.O.
Sam Sherratt P.S.	HB 082	6	02-Jun-15	S.Parliament	10-Aug-15	Stained ceiling tile (~1) observed at south-west corner.
	HB 083		02-Jun-15	S.Parliament	10-Aug-15	N.S.M.O.M.O.
	HBL 087		02-Jun-15	S.Parliament	10-Aug-15	N.S.M.O.M.O.
	HBL 099		02-Jun-15	S.Parliament	10-Aug-15	N.S.M.O.M.O.
	HBL 223		02-Jun-15	S.Parliament	10-Aug-15	N.S.M.O.M.O.
	HBL 227		02-Jun-15	S.Parliament	10-Aug-15	N.S.M.O.M.O.
Silver Creek P.S.	HB 029	2	28-May-15	S.Parliament	3-Aug-15	N.S.M.O.M.O.
	HB 033		28-May-15	S.Parliament	3-Aug-15	N.S.M.O.M.O.

**TABLE 1
PORTABLE CLASSROOM PREVENTATIVE MAINTENANCE INSPECTION NO. 93 SUMMARY**

School	Portable Number	Portables on Site	PM Inspection Schedule		Proposed Round 94 Inspections Date	Comments from Round 93 Inspection
			Round 93 Inspection Date	ARCADIS Inspector		
Tiger Jeet Singh P.S.	HB 063	10	01-Jun-15	S.Parliament	5-Aug-15	<i>Exterior caulking degraded at door and air-exchanger vent.</i>
	HB 095		01-Jun-15	S.Parliament	5-Aug-15	<i>N.S.M.O.M.O.</i>
	HB 109		01-Jun-15	S.Parliament	5-Aug-15	<i>N.S.M.O.M.O.</i>
	HB 116		01-Jun-15	S.Parliament	5-Aug-15	<i>Exterior caulking missing at gable-louvre at right elevation.</i>
	HB 126		01-Jun-15	S.Parliament	5-Aug-15	<i>N.S.M.O.M.O.</i>
	HB 187		01-Jun-15	S.Parliament	5-Aug-15	<i>N.S.M.O.M.O.</i>
	HBL 013		01-Jun-15	S.Parliament	5-Aug-15	<i>N.S.M.O.M.O.</i>
	HBL 014		01-Jun-15	S.Parliament	5-Aug-15	<i>N.S.M.O.M.O.</i>
	HBL 015		01-Jun-15	S.Parliament	5-Aug-15	<i>N.S.M.O.M.O.</i>
	HBL 098		01-Jun-15	S.Parliament	5-Aug-15	<i>N.S.M.O.M.O.</i>
W.I. Dick P.S.	HB 002	3	27-May-15	S.Parliament	20-Aug-15	<i>N.S.M.O.M.O.</i>
	HB 007		27-May-15	S.Parliament	20-Aug-15	<i>Vinyl floor tiles (~5) damaged throughout.</i>
	HB 183		27-May-15	S.Parliament	20-Aug-15	<i>Skirting at rear elevation damaged.</i>
Total Portables:		154				

NOTE:	
Scheduled inspection date subject to change due to availability of manpower and the facility.	
N.S.M.O.M.O.=	No Suspect Mould or Moisture Observed

**TABLE 1
PORTABLE CLASSROOM PREVENTATIVE MAINTENANCE INSPECTION NO. 93 SUMMARY**

School	Portable Number	Portables on Site	PM Inspection Schedule		Proposed Round 94 Inspections Date	Comments from Round 93 Inspection
			Round 93 Inspection Date	ARCADIS Inspector		
Abbey Park H.S.	HB 108	3	18-May-15	S.Parliament	15-Jul-15	<i>N.S.M.O.M.O.</i>
	HB 163		18-May-15	S.Parliament	15-Jul-15	<i>N.S.M.O.M.O.</i>
	HB 164		18-May-15	S.Parliament	15-Jul-15	<i>Exterior caulking degraded at air-exchanger vent.</i>
E.J. James P.S.	HB 061	5	21-May-15	S.Parliament	20-Jul-15	<i>N.S.M.O.M.O.</i>
	HB 079		21-May-15	S.Parliament	20-Jul-15	<i>N.S.M.O.M.O.</i>
	HB 111		21-May-15	S.Parliament	20-Jul-15	<i>N.S.M.O.M.O.</i>
	HB 121		21-May-15	S.Parliament	20-Jul-15	<i>N.S.M.O.M.O.</i>
	HBL 009		21-May-15	S.Parliament	20-Jul-15	<i>N.S.M.O.M.O.</i>
Heritage Glen P.S.	HBL 216	4	18-May-15	S.Parliament	15-Jul-15	<i>N.S.M.O.M.O.</i>
	HBL 217		18-May-15	S.Parliament	15-Jul-15	<i>N.S.M.O.M.O.</i>
	HBL 218		18-May-15	S.Parliament	15-Jul-15	<i>N.S.M.O.M.O.</i>
	HBL 241		18-May-15	S.Parliament	15-Jul-15	<i>N.S.M.O.M.O.</i>
Iroquois Ridge H.S.	HB 070	2	20-May-15	S.Parliament	16-Jul-15	<i>N.S.M.O.M.O.</i>
	HB 209		20-May-15	S.Parliament	16-Jul-15	<i>N.S.M.O.M.O.</i>
James W. Hill P.S.	HB 080	3	20-May-15	S.Parliament	16-Jul-15	<i>N.S.M.O.M.O.</i>
	HB 099		20-May-15	S.Parliament	16-Jul-15	<i>N.S.M.O.M.O.</i>
	HB 176		20-May-15	S.Parliament	16-Jul-15	<i>N.S.M.O.M.O.</i>
Joshua Creek P.S.	HB 011	5	20-May-15	S.Parliament	16-Jul-15	<i>Screw holes observed in metal cladding at front elevation beside door.</i>
	HB 077		20-May-15	S.Parliament	16-Jul-15	<i>Exterior caulking degraded at front door. Screw holes observed in metal cladding at front elevation. Small tear observed in metal cladding underneath second window.</i>
	HB 085		20-May-15	S.Parliament	16-Jul-15	<i>N.S.M.O.M.O.</i>
	HB 199		20-May-15	S.Parliament	16-Jul-15	<i>N.S.M.O.M.O.</i>
	HB 200		20-May-15	S.Parliament	16-Jul-15	<i>Eavestrough (~10') missing at front elevation. Screw holes observed in metal cladding and corner flashing at right elevation.</i>
Munn's P.S.	HB 177	1	14-May-15	S.Parliament	14-Jul-15	<i>N.S.M.O.M.O.</i>
Oakville Trafalgar H.S. (Portable)	RM 190	7	21-May-15	S.Parliament	20-Jul-15	<i>N.S.M.O.M.O.</i>
	RM 191		21-May-15	S.Parliament	20-Jul-15	<i>N.S.M.O.M.O.</i>
	RM 192		21-May-15	S.Parliament	20-Jul-15	<i>N.S.M.O.M.O.</i>
	RM 193		21-May-15	S.Parliament	20-Jul-15	<i>N.S.M.O.M.O.</i>
	RM 194		21-May-15	S.Parliament	20-Jul-15	<i>N.S.M.O.M.O.</i>
	RM 198		21-May-15	S.Parliament	20-Jul-15	<i>N.S.M.O.M.O.</i>
	RM 199		21-May-15	S.Parliament	20-Jul-15	<i>N.S.M.O.M.O.</i>
Pilgrim Wood P.S.	HBL 110	3	18-May-15	S. Parliament	15-Jul-15	<i>N.S.M.O.M.O.</i>
	HBL 224		18-May-15	S. Parliament	15-Jul-15	<i>Stained ceiling tile observed. Vapour barrier damaged above ceiling space in south-west corner.</i>
	HBL 225		18-May-15	S. Parliament	15-Jul-15	<i>N.S.M.O.M.O.</i>
Post's Corners P.S.	HB 065	1	20-May-15	S.Parliament	16-Jul-15	<i>Exterior caulking missing at front door.</i>
Sheridan P.S.	HBL 226	1	20-May-15	S.Parliament	16-Jul-15	<i>Small tear observed in metal cladding at left elevation.</i>
River Oaks P.S.	HB 088	3	12-May-15	S. Parliament	14-Jul-15	<i>Downspout damaged at rear elevation.</i>
	HB 196		12-May-15	S. Parliament	14-Jul-15	<i>N.S.M.O.M.O.</i>
	HB 202		12-May-15	S. Parliament	14-Jul-15	<i>N.S.M.O.M.O.</i>
Total Portables:		38				

NOTE:	
Scheduled inspection date subject to change due to availability of manpower and the facility.	
<i>N.S.M.O.M.O.</i> =	No Suspect Mould or Moisture Observed

**TABLE 1
PORTABLE CLASSROOM PREVENTATIVE MAINTENANCE INSPECTION NO. 93 SUMMARY**

School	Portable Number	Portables on Site	PM Inspection Schedule		Proposed Round 94 Inspections Date	Comments from Round 93 Inspection
			Round 93 Inspection Date	ARCADIS Inspector		
Alexander's P.S.	HB 008	5	13-May-15	S.Parliament	13-Jul-15	<i>N.S.M.O.M.O.</i>
	HB 024		13-May-15	S.Parliament	13-Jul-15	<i>Screw holes observed in metal cladding and corner flashing at front elevation.</i>
	HB 028		13-May-15	S.Parliament	13-Jul-15	<i>N.S.M.O.M.O.</i>
	HB 032		13-May-15	S.Parliament	13-Jul-15	<i>N.S.M.O.M.O.</i>
	HB 051		13-May-15	S.Parliament	13-Jul-15	<i>N.S.M.O.M.O.</i>
Charles R. Beaudoin P.S.	HBL 100	4	12-May-15	S.Parliament	9-Jul-15	<i>N.S.M.O.M.O.</i>
	HBL 101		12-May-15	S.Parliament	9-Jul-15	<i>N.S.M.O.M.O.</i>
	HBL 102		12-May-15	S.Parliament	9-Jul-15	<i>N.S.M.O.M.O.</i>
	HBL 206		12-May-15	S.Parliament	9-Jul-15	<i>N.S.M.O.M.O.</i>
J.W. Singleton Education Centre	HB 003	4	11-May-15	S.Parliament	30-Jul-15	<i>Holes observed in cement board skirting at rear elevation.</i>
	HB 117		11-May-15	S.Parliament	30-Jul-15	<i>Exterior caulking missing at air-conditioning unit wiring.</i>
	HB 118		11-May-15	S.Parliament	30-Jul-15	<i>N.S.M.O.M.O.</i>
	HB 119		11-May-15	S.Parliament	30-Jul-15	<i>N.S.M.O.M.O.</i>
John T. Tuck P.S.	HB 064	7	08-Jun-15	S.Parliament	18-Aug-15	<i>N.S.M.O.M.O.</i>
	HB 156		08-Jun-15	S.Parliament	18-Aug-15	<i>N.S.M.O.M.O.</i>
	HB 157		08-Jun-15	S.Parliament	18-Aug-15	<i>N.S.M.O.M.O.</i>
	HB 173		08-Jun-15	S.Parliament	18-Aug-15	<i>Screw holes observed in metal cladding at front elevation.</i>
	HBL 219		08-Jun-15	S.Parliament	18-Aug-15	<i>N.S.M.O.M.O.</i>
	HBL 220		08-Jun-15	S.Parliament	18-Aug-15	<i>N.S.M.O.M.O.</i>
	HBL 221		08-Jun-15	S.Parliament	18-Aug-15	<i>N.S.M.O.M.O.</i>
John W. Boich P.S.	HB 108	3	13-May-15	S.Parliament	13-Jul-15	<i>N.S.M.O.M.O.</i>
	HBL 109		13-May-15	S.Parliament	13-Jul-15	<i>N.S.M.O.M.O.</i>
	HBL 247		13-May-15	S.Parliament	13-Jul-15	<i>N.S.M.O.M.O.</i>
L.B. Pearson H.S.	RM 179 A/B	12	11-May-15	S.Parliament	30-Jul-15	<i>N.S.M.O.M.O.</i>
	RM 180		11-May-15	S.Parliament	30-Jul-15	<i>N.S.M.O.M.O.</i>
	RM 181		11-May-15	S.Parliament	30-Jul-15	<i>N.S.M.O.M.O.</i>
	RM 182		11-May-15	S.Parliament	30-Jul-15	<i>N.S.M.O.M.O.</i>
	RM 183		11-May-15	S.Parliament	30-Jul-15	<i>N.S.M.O.M.O.</i>
	RM 184		11-May-15	S.Parliament	30-Jul-15	<i>Black staining observed on wood sheathing in ceiling space at C-2 (new).</i>
	RM 185		11-May-15	S.Parliament	30-Jul-15	<i>N.S.M.O.M.O.</i>
	RM 186		11-May-15	S.Parliament	30-Jul-15	<i>N.S.M.O.M.O.</i>
	RM 187		11-May-15	S.Parliament	30-Jul-15	<i>N.S.M.O.M.O.</i>
	RM 188		11-May-15	S.Parliament	30-Jul-15	<i>N.S.M.O.M.O.</i>
	RM 189		11-May-15	S.Parliament	30-Jul-15	<i>N.S.M.O.M.O.</i>
	RM 190 A/B		11-May-15	S.Parliament	30-Jul-15	<i>N.S.M.O.M.O.</i>
M.M. Robinson H.S.	HB 010	3	11-May-15	S.Parliament	30-Jul-15	<i>N.S.M.O.M.O.</i>
	HB 151		11-May-15	S.Parliament	30-Jul-15	<i>N.S.M.O.M.O.</i>
	HB 161		11-May-15	S.Parliament	30-Jul-15	<i>N.S.M.O.M.O.</i>

**TABLE 1
PORTABLE CLASSROOM PREVENTATIVE MAINTENANCE INSPECTION NO. 93 SUMMARY**

School	Portable Number	Portables on Site	PM Inspection Schedule		Proposed Round 94 Inspections Date	Comments from Round 93 Inspection
			Round 93 Inspection Date	ARCADIS Inspector		
Pineland P.S.	HB 006	6	09-Jun-15	S.Parliament	19-Aug-15	<i>N.S.M.O.M.O.</i>
	HB 067		09-Jun-15	S.Parliament	19-Aug-15	<i>N.S.M.O.M.O.</i>
	HB 069		09-Jun-15	S.Parliament	19-Aug-15	<i>N.S.M.O.M.O.</i>
	HB 094		09-Jun-15	S.Parliament	19-Aug-15	<i>Metal cladding damaged underneath second window. Glass pane at second window shattered/cracked.</i>
	HB 096		09-Jun-15	S.Parliament	19-Aug-15	<i>N.S.M.O.M.O.</i>
	HB 128		09-Jun-15	S.Parliament	19-Aug-15	<i>N.S.M.O.M.O.</i>
Sir E. MacMillan P.S.	HB 017	6	09-Jun-15	S.Parliament	19-Aug-15	<i>Skirting vent missing at rear elevation.</i>
	HB 018		09-Jun-15	S.Parliament	19-Aug-15	<i>N.S.M.O.M.O.</i>
	HB 019		09-Jun-15	S.Parliament	19-Aug-15	<i>N.S.M.O.M.O.</i>
	HB 020		09-Jun-15	S.Parliament	19-Aug-15	<i>N.S.M.O.M.O.</i>
	HB 025		09-Jun-15	S.Parliament	19-Aug-15	<i>N.S.M.O.M.O.</i>
	HB 165		09-Jun-15	S.Parliament	19-Aug-15	<i>Screw holes observed in metal cladding at rear elevation.</i>
Total Portables:		50				

NOTE:	
Scheduled inspection date subject to change due to availability of manpower and the facility.	
<i>N.S.M.O.M.O.</i> =	No Suspect Mould or Moisture Observed

**TABLE 1
PORTABLE CLASSROOM PREVENTATIVE MAINTENANCE INSPECTION NO. 93 SUMMARY**

School	Portable Number	Portables on Site	PM Inspection Schedule		Proposed Round 94 Inspections Date	Comments from Round 93 Inspection
			Round 93 Inspection Date	ARCADIS Inspector		
Captain R. Wilson P.S.	HB 014	1	18-May-15	S. Parliament	15-Jul-15	<i>Caulking degraded at rear right downspout.</i>
Emily Carr P.S.	HB 084	6	16-Jun-15	S. Parliament	29-Jul-15	<i>N.S.M.O.M.O.</i>
	HB 106		16-Jun-15	S. Parliament	29-Jul-15	<i>Stained ceiling tile observed at C-6.</i>
	HBL 001		16-Jun-15	S. Parliament	29-Jul-15	<i>N.S.M.O.M.O.</i>
	HBL 002		16-Jun-15	S. Parliament	29-Jul-15	<i>N.S.M.O.M.O.</i>
	HBL 008		16-Jun-15	S. Parliament	29-Jul-15	<i>N.S.M.O.M.O.</i>
	HBL 085		16-Jun-15	S. Parliament	29-Jul-15	<i>N.S.M.O.M.O.</i>
Forest Trail P.S.	HB 044	9	22-May-15	S. Parliament	23-Jul-15	<i>N.S.M.O.M.O.</i>
	HB 047		22-May-15	S. Parliament	23-Jul-15	<i>N.S.M.O.M.O.</i>
	HB 049		22-May-15	S. Parliament	23-Jul-15	<i>N.S.M.O.M.O.</i>
	HB 050		22-May-15	S. Parliament	23-Jul-15	<i>N.S.M.O.M.O.</i>
	HB 052		22-May-15	S. Parliament	23-Jul-15	<i>N.S.M.O.M.O.</i>
	HB 054		22-May-15	S. Parliament	23-Jul-15	<i>Stained ceiling tiles (~3) observed along center seam.Screw holes observed in metal cladding at front elevation.</i>
	HB 058		22-May-15	S. Parliament	23-Jul-15	<i>N.S.M.O.M.O.</i>
	HB 076		22-May-15	S. Parliament	23-Jul-15	<i>N.S.M.O.M.O.</i>
	HB 101		22-May-15	S. Parliament	23-Jul-15	<i>Screw holes observed in metal cladding at right elevation. Exterior caulking missing at air-conditioning unit supports.</i>
Gladys Speers P.S.	HB 104	1	14-May-15	S. Parliament	14-Jul-15	<i>Small tear observed in metal cladding under second window. Downspout detached at rear right corner elevation. Exterior caulking degraded at gable louvre at right elevation.</i>
Palmero P.S.	HB 037	7	16-Jun-15	S. Parliament	29-Jul-15	<i>N.S.M.O.M.O.</i>
	HB 068		16-Jun-15	S. Parliament	29-Jul-15	<i>N.S.M.O.M.O.</i>
	HB 086		16-Jun-15	S. Parliament	29-Jul-15	<i>N.S.M.O.M.O.</i>
	HB 087		16-Jun-15	S. Parliament	29-Jul-15	<i>N.S.M.O.M.O.</i>
	HB 167		16-Jun-15	S. Parliament	29-Jul-15	<i>N.S.M.O.M.O.</i>
	HB 168		16-Jun-15	S. Parliament	29-Jul-15	<i>N.S.M.O.M.O.</i>
	HB 170		16-Jun-15	S. Parliament	29-Jul-15	<i>N.S.M.O.M.O.</i>
Pine Grove P.S.	HB 043	10	17-Jun-15	S. Parliament	21-Jul-15	<i>Screw holes observed in metal cladding at right and left elevations.</i>
	HB 097		17-Jun-15	S. Parliament	21-Jul-15	<i>N.S.M.O.M.O.</i>
	HB 123		17-Jun-15	S. Parliament	21-Jul-15	<i>Exterior caulking degraded at air-exchanger vent.</i>
	HB 130		17-Jun-15	S. Parliament	21-Jul-15	<i>N.S.M.O.M.O.</i>
	HB 131		17-Jun-15	S. Parliament	21-Jul-15	<i>N.S.M.O.M.O.</i>
	HB 158		17-Jun-15	S. Parliament	21-Jul-15	<i>N.S.M.O.M.O.</i>
	HB 159		17-Jun-15	S. Parliament	21-Jul-15	<i>N.S.M.O.M.O.</i>
	HB 171		17-Jun-15	S. Parliament	21-Jul-15	<i>N.S.M.O.M.O.</i>
	HB 175		17-Jun-15	S. Parliament	21-Jul-15	<i>N.S.M.O.M.O.</i>
	HBL 006		17-Jun-15	S. Parliament	21-Jul-15	<i>N.S.M.O.M.O.</i>
Sunningdale P.S.	HB 059	10	14-May-15	S. Parliament	14-Jul-15	<i>N.S.M.O.M.O.</i>
	HB 072		14-May-15	S. Parliament	14-Jul-15	<i>Exterior caulking degraded at air-exchanger vent.</i>
	HB 092		14-May-15	S. Parliament	14-Jul-15	<i>N.S.M.O.M.O.</i>
	HB 120		14-May-15	S. Parliament	14-Jul-15	<i>N.S.M.O.M.O.</i>
	HB 132		14-May-15	S. Parliament	14-Jul-15	<i>Exterior caulking degraded at second window. Hole (3") observed in skirting at front elevation.</i>
	HB 137		14-May-15	S. Parliament	14-Jul-15	<i>N.S.M.O.M.O.</i>
	HB 145		14-May-15	S. Parliament	14-Jul-15	<i>Downspout at front elevation damaged.</i>
	HB 172		14-May-15	S. Parliament	14-Jul-15	<i>N.S.M.O.M.O.</i>
	HB 179		14-May-15	S. Parliament	14-Jul-15	<i>N.S.M.O.M.O.</i>
	HB 207		14-May-15	S. Parliament	14-Jul-15	<i>N.S.M.O.M.O.</i>
W.H. Morden P.S.	HB 055	5	17-Jun-15	S. Parliament	21-Jul-15	<i>N.S.M.O.M.O.</i>
	HB 138		17-Jun-15	S. Parliament	21-Jul-15	<i>N.S.M.O.M.O.</i>

**TABLE 1
PORTABLE CLASSROOM PREVENTATIVE MAINTENANCE INSPECTION NO. 93 SUMMARY**

School	Portable Number	Portables on Site	PM Inspection Schedule		Proposed Round 94 Inspections Date	Comments from Round 93 Inspection
			Round 93 Inspection Date	ARCADIS Inspector		
	HBL 007		17-Jun-15	S. Parliament	21-Jul-15	<i>N.S.M.O.M.O.</i>
	HBL 249 (1147)		17-Jun-15	S. Parliament	21-Jul-15	<i>N.S.M.O.M.O.</i>
	HBL 250 (931)		17-Jun-15	S. Parliament	21-Jul-15	<i>N.S.M.O.M.O.</i>
West Oak P.S.	RM 1	8	22-May-15	S. Parliament	23-Jul-15	<i>N.S.M.O.M.O.</i>
	RM 2		22-May-15	S. Parliament	23-Jul-15	<i>N.S.M.O.M.O.</i>
	RM 3		22-May-15	S. Parliament	23-Jul-15	<i>N.S.M.O.M.O.</i>
	RM 4		22-May-15	S. Parliament	23-Jul-15	<i>N.S.M.O.M.O.</i>
	RM 5		22-May-15	S. Parliament	23-Jul-15	<i>N.S.M.O.M.O.</i>
	RM 6		22-May-15	S. Parliament	23-Jul-15	<i>Exterior caulking degraded at window.</i>
	Work Room		22-May-15	S. Parliament	23-Jul-15	<i>N.S.M.O.M.O.</i>
	HB 107		22-May-15	S. Parliament	23-Jul-15	<i>N.S.M.O.M.O.</i>
White Oaks Centre for Science and	HB 060	5	29-Jun-15	D.Kellyman	22-Jul-15	<i>N.S.M.O.M.O.</i>
	HBL 092		29-Jun-15	D.Kellyman	22-Jul-15	<i>N.S.M.O.M.O.</i>
	HBL 093		29-Jun-15	D.Kellyman	22-Jul-15	<i>N.S.M.O.M.O.</i>
	HBL 094		29-Jun-15	D.Kellyman	22-Jul-15	<i>N.S.M.O.M.O.</i>
	HBL 095		29-Jun-15	D.Kellyman	22-Jul-15	<i>N.S.M.O.M.O.</i>
White Oaks School Admin. (South)	HB 023	12	29-Jun-15	D.Kellyman	22-Jul-15	<i>N.S.M.O.M.O.</i>
	HB 042		29-Jun-15	D.Kellyman	22-Jul-15	<i>N.S.M.O.M.O.</i>
	HB 078		29-Jun-15	D.Kellyman	22-Jul-15	<i>N.S.M.O.M.O.</i>
	HB 112		29-Jun-15	D.Kellyman	22-Jul-15	<i>N.S.M.O.M.O.</i>
	HB 153		29-Jun-15	D.Kellyman	22-Jul-15	<i>N.S.M.O.M.O.</i>
	HB 201		29-Jun-15	D.Kellyman	22-Jul-15	<i>N.S.M.O.M.O.</i>
	HB 205		29-Jun-15	D.Kellyman	22-Jul-15	<i>N.S.M.O.M.O.</i>
	HBL 016		29-Jun-15	D.Kellyman	22-Jul-15	<i>N.S.M.O.M.O.</i>
	HBL 017		29-Jun-15	D.Kellyman	22-Jul-15	<i>N.S.M.O.M.O.</i>
	HBL 018		29-Jun-15	D.Kellyman	22-Jul-15	<i>N.S.M.O.M.O.</i>
	HBL 096		29-Jun-15	D.Kellyman	22-Jul-15	<i>N.S.M.O.M.O.</i>
	HBL 097		29-Jun-15	D.Kellyman	22-Jul-15	<i>N.S.M.O.M.O.</i>
Total Portables:		74				

NOTE:	
Scheduled inspection date subject to change due to availability of manpower and the facility.	
<i>N.S.M.O.M.O.</i> =	No Suspect Mould or Moisture Observed

**TABLE 1
PORTABLE CLASSROOM PREVENTATIVE MAINTENANCE INSPECTION NO. 93 SUMMARY**

School	Portable Number	Portables on Site	PM Inspection Schedule		Proposed Round 94 Inspections Date	Comments from Round 93 Inspection
			Round 93 Inspection Date	ARCADIS Inspector		
Alton Village P.S.	HBL 225	7	12-May-15	S.Parliament	9-Jul-15	<i>Exterior caulking degraded at conduit at right elevation.</i>
	HBL 234 (P1)		12-May-15	S.Parliament	9-Jul-15	<i>N.S.M.O.M.O.</i>
	HBL 235 (P2)		12-May-15	S.Parliament	9-Jul-15	<i>N.S.M.O.M.O.</i>
	HBL 236 (P3)		12-May-15	S.Parliament	9-Jul-15	<i>Stained ceiling tile (~2) observed, caused by unsealed conduit.</i>
	HBL 237 (P4)		12-May-15	S.Parliament	9-Jul-15	<i>N.S.M.O.M.O.</i>
	HBL 238 (P5)		12-May-15	S.Parliament	9-Jul-15	<i>N.S.M.O.M.O.</i>
	HBL 239 (P6)		12-May-15	S.Parliament	9-Jul-15	<i>Screw holes observed in metal cladding at left elevation.</i>
Dr. Charles Best P.S.	HBL 210	2	09-Jun-15	S.Parliament	19-Aug-15	<i>Eavestrough end cap missing at rear elevation.</i>
	HBL 211		09-Jun-15	S.Parliament	19-Aug-15	<i>N.S.M.O.M.O.</i>
Florence Meares P.S.	HB 139	1	12-May-15	S.Parliament	9-Jul-15	<i>Roof flashing at right elevation damaged.</i>
Kilbride P.S.	HB 074	1	12-May-15	S.Parliament	9-Jul-15	<i>N.S.M.O.M.O.</i>
Orchard Park P.S.	HB 040	4	13-May-15	S.Parliament	13-Jul-15	<i>N.S.M.O.M.O.</i>
	HB 140		13-May-15	S.Parliament	13-Jul-15	<i>N.S.M.O.M.O.</i>
	HB 147		13-May-15	S.Parliament	13-Jul-15	<i>Exterior caulking degraded at conduit at left elevation.</i>
	HB 166		13-May-15	S.Parliament	13-Jul-15	<i>N.S.M.O.M.O.</i>
Pauline Johnson P.S.	HB 102	2	09-Jun-15	S.Parliament	19-Aug-15	<i>N.S.M.O.M.O.</i>
	HBL 222		09-Jun-15	S.Parliament	19-Aug-15	<i>N.S.M.O.M.O.</i>
Tom Thompson P.S.	HB 012	10	08-Jun-15	S.Parliament	18-Aug-15	<i>Screw holes observed in center flashing and metal cladding at right elevation.</i>
	HB 031		08-Jun-15	S.Parliament	18-Aug-15	<i>Exterior caulking degraded at conduit at rear elevation.</i>
	HB 053		08-Jun-15	S.Parliament	18-Aug-15	<i>Exterior caulking degraded at air-exchanger vent.</i>
	HB 098		08-Jun-15	S.Parliament	18-Aug-15	<i>N.S.M.O.M.O.</i>
	HB 105		08-Jun-15	S.Parliament	18-Aug-15	<i>N.S.M.O.M.O.</i>
	HB 124		08-Jun-15	S.Parliament	18-Aug-15	<i>N.S.M.O.M.O.</i>
	HB 141		08-Jun-15	S.Parliament	18-Aug-15	<i>Tear (~2") observed in metal cladding at front elevation. Stained ceiling tiles (~2) observed.</i>
	HB 148		08-Jun-15	S.Parliament	18-Aug-15	<i>N.S.M.O.M.O.</i>
	HB 169		08-Jun-15	S.Parliament	18-Aug-15	<i>Metal cladding damaged and/or cut at rear elevation leaving sharp edge</i>
	HB 206		08-Jun-15	S.Parliament	18-Aug-15	<i>N.S.M.O.M.O.</i>
Total Portables:		27				

NOTE:	
Scheduled inspection date subject to change due to availability of manpower and the facility.	
<i>N.S.M.O.M.O.</i> =	No Suspect Mould or Moisture Observed