

**PM Inspection Schedule**

School	Portable Number	Portables on Site	Round 99 Inspection Date	ARCADIS Inspector	Proposed Round 100 Inspection Date	Comments from Round 99 Inspection
Anne J. MacArthur P.S.	HBL 215	11	28-Jun-16	S.Parliament	1-Dec-16	<i>N.S.M.O.M.O.</i>
	HB 071		28-Jun-16	S.Parliament	1-Dec-16	<i>Exterior caulking degraded at front door. Screw holes observed in metal flashing at left elevation.</i>
	HBL 214		28-Jun-16	S.Parliament	1-Dec-16	<i>N.S.M.O.M.O.</i>
	HBL 204		28-Jun-16	S.Parliament	1-Dec-16	<i>Exterior caulking degraded at first and second windows.</i>
	HBL 26		28-Jun-16	S.Parliament	1-Dec-16	<i>N.S.M.O.M.O.</i>
	HBL 203		28-Jun-16	S.Parliament	1-Dec-16	<i>N.S.M.O.M.O.</i>
	HBL 202		28-Jun-16	S.Parliament	1-Dec-16	<i>Screw holes observed in metal cladding at right elevation. Exterior caulking degraded at conduits.</i>
	HBL 223		28-Jun-16	S.Parliament	1-Dec-16	<i>N.S.M.O.M.O.</i>
	HBL 233		28-Jun-16	S.Parliament	1-Dec-16	<i>N.S.M.O.M.O.</i>
	HBL 205		28-Jun-16	S.Parliament	1-Dec-16	<i>N.S.M.O.M.O.</i>
	HBL 174		28-Jun-16	S.Parliament	01-Dec-16	<i>N.S.M.O.M.O.</i>
Boyne P.S.	HBL 251	13	18-Jul-16	D.Kellyman	7-Nov-16	<i>N.S.M.O.M.O.</i>
	HB 015		18-Jul-16	D.Kellyman	7-Nov-16	<i>N.S.M.O.M.O.</i>
	HB 152		18-Jul-16	D.Kellyman	7-Nov-16	<i>N.S.M.O.M.O.</i>
	HBL 253		18-Jul-16	D.Kellyman	7-Nov-16	<i>N.S.M.O.M.O.</i>
	HBL 252		18-Jul-16	D.Kellyman	7-Nov-16	<i>N.S.M.O.M.O.</i>
	HBL 254		18-Jul-16	D.Kellyman	7-Nov-16	<i>N.S.M.O.M.O.</i>
	HB 029		29-Jun-16	S.Parliament	7-Nov-16	<i>Exterior caulking degraded at conduit (existing).</i>
	HB 033		29-Jun-16	S.Parliament	7-Nov-16	<i>Hole (1") observed in metal cladding at right elevation.</i>
	HB 048		29-Jun-16	S.Parliament	7-Nov-16	<i>N.S.M.O.M.O.</i>
	HBL 241		28-Jul-16	J. Jones	7-Nov-16	<i>N.S.M.O.M.O.</i>
	HB 008		28-Jul-16	J. Jones	7-Nov-16	<i>N.S.M.O.M.O.</i>
	HB 032		28-Jul-16	J. Jones	7-Nov-16	<i>Hole (1.5") in drywall (existing).</i>
	HBL 218		28-Jul-16	J. Jones	7-Nov-16	<i>N.S.M.O.M.O.</i>
Brookville P.S.	HBL 201	0	29-Jul-16	C. Jagarnauth	-	<i>Portable in the process of being relocated. Portable to be inspected at new location during the next round of inspections.</i>
Bruce Trail P.S.	HB 046	12	27-Jul-16	S. Parliament	3-Nov-16	<i>N.S.M.O.M.O.</i>
	HB 062		27-Jul-16	S. Parliament	3-Nov-16	<i>Exterior caulking degraded at windows and air-exchanger vent.</i>
	HB 075		27-Jul-16	S. Parliament	3-Nov-16	<i>Exterior caulking degraded at windows. Downspout missing at front elevation. Screw holes observed in metal cladding and corner flashing at front elevation.</i>
	HB 103		27-Jul-16	S. Parliament	3-Nov-16	<i>N.S.M.O.M.O.</i>
	HB 105		27-Jul-16	S. Parliament	3-Nov-16	<i>N.S.M.O.M.O.</i>
	HB 110		27-Jul-16	S. Parliament	3-Nov-16	<i>Vinyl floor tiles damaged throughout (existing).</i>
	HB 115		27-Jul-16	S. Parliament	3-Nov-16	<i>Tear (1") observed in metal cladding at front elevation. Screw holes observed in metal cladding at front and left elevations and corner flashing.</i>
	HB 149		27-Jul-16	S. Parliament	3-Nov-16	<i>Portable in the process of being relocated. Portable to be inspected at new location during the next round of inspections.</i>
	HBL 229		27-Jul-16	S. Parliament	3-Nov-16	<i>N.S.M.O.M.O.</i>
	HBL 231		27-Jul-16	S. Parliament	3-Nov-16	<i>N.S.M.O.M.O.</i>
	HBL 228		27-Jul-16	S. Parliament	3-Nov-16	<i>N.S.M.O.M.O.</i>
	HBL 230		27-Jul-16	S. Parliament	3-Nov-16	<i>N.S.M.O.M.O.</i>
	HB 114		27-Jul-16	S. Parliament	3-Nov-16	<i>Exterior caulking degraded at front door. Downspout missing at rear elevation.</i>
Chris Hadfield P.S.	RM A1	12	05-Jul-16	C. Jagarnauth	7-Dec-16	<i>N.S.M.O.M.O.</i>
	RM A2		05-Jul-16	C. Jagarnauth	7-Dec-16	<i>N.S.M.O.M.O.</i>
	RM A3		05-Jul-16	C. Jagarnauth	7-Dec-16	<i>N.S.M.O.M.O.</i>
	RM A4		05-Jul-16	C. Jagarnauth	7-Dec-16	<i>N.S.M.O.M.O.</i>
	RM A5		05-Jul-16	C. Jagarnauth	7-Dec-16	<i>N.S.M.O.M.O.</i>
	RM A6		05-Jul-16	C. Jagarnauth	7-Dec-16	<i>N.S.M.O.M.O.</i>

**PM Inspection Schedule**

School	Portable Number	Portables on Site	Round 99 Inspection Date	ARCADIS Inspector	Proposed Round 100 Inspection Date	Comments from Round 99 Inspection
	RM A7		05-Jul-16	C. Jagarnauth	7-Dec-16	N.S.M.O.M.O.
	RM A8		05-Jul-16	C. Jagarnauth	7-Dec-16	N.S.M.O.M.O.
	RM A9		05-Jul-16	C. Jagarnauth	7-Dec-16	N.S.M.O.M.O.
	RM A10		05-Jul-16	C. Jagarnauth	7-Dec-16	N.S.M.O.M.O.
	RM A11		05-Jul-16	C. Jagarnauth	7-Dec-16	Interior caulking missing at all windows (existing).
	HBL 106		05-Jul-16	C. Jagarnauth	7-Dec-16	Exterior caulking missing at conduits at right elevation (existing). Screw holes at left and rear elevation.
Craig Kielburger S.S.	HBL 084	18	29-Jun-16	C. Jagarnauth	13-Dec-16	Screw holes in cladding at rear elevation
	HBL 005		29-Jun-16	C. Jagarnauth	13-Dec-16	N.S.M.O.M.O.
	HB 100		29-Jun-16	C. Jagarnauth	13-Dec-16	Exterior caulking degraded at windows and doors (existing).
	HB 135		29-Jun-16	C. Jagarnauth	13-Dec-16	Exterior window caulking degraded.
	HB 056		29-Jun-16	C. Jagarnauth	13-Dec-16	Portable in the process of being relocated. Portable to be inspected at new location during the next round of inspections.
	HB 203		29-Jun-16	C. Jagarnauth	13-Dec-16	Exterior caulking degraded at window and air-exchanger vent (existing). Metal cladding and corner flashing damaged at front elevation (existing). Holes (1/4") observed underneath air-conditioner unit.
	HB 045		29-Jun-16	C. Jagarnauth	13-Dec-16	Screw holes at front elevation. Exterior caulking degraded at door and air-exchanger.
	HB 038		29-Jun-16	C. Jagarnauth	13-Dec-16	Door caulking degraded.
	HBL 80		29-Jun-16	C. Jagarnauth	13-Dec-16	Screw holes observed in metal cladding at right elevation (existing).
	HB 090		29-Jun-16	C. Jagarnauth	14-Dec-16	N.S.M.O.M.O.
	HB 091		29-Jun-16	C. Jagarnauth	14-Dec-16	Exterior door caulking degraded.
	HB 057		30-Jun-16	C. Jagarnauth	14-Dec-16	Screw holes observed at front cladding (existing).
	HB 143		30-Jun-16	C. Jagarnauth	14-Dec-16	Exterior door and window caulking missing/ degraded.
	HB 133		30-Jun-16	C. Jagarnauth	14-Dec-16	Screw holes at front elevation.
	HB 134		30-Jun-16	C. Jagarnauth	14-Dec-16	Screw holes at front elevation.
	HB 073		30-Jun-16	C. Jagarnauth	14-Dec-16	Evidence of rodent activity observed in ceiling space at C-3 and C-4 (existing).
	HB 125		30-Jun-16	C. Jagarnauth	14-Dec-16	N.S.M.O.M.O.
	HB 113		30-Jun-16	C. Jagarnauth	14-Dec-16	N.S.M.O.M.O.
Escarpment View P.S.	HBL 103	11	20-Jul-16	D.Kellyman	8-Nov-16	N.S.M.O.M.O.
	HB 005		20-Jul-16	D.Kellyman	8-Nov-16	Exterior caulking degraded at door (existing).
	HB 089		20-Jul-16	D.Kellyman	8-Nov-16	N.S.M.O.M.O.
	HB 144		20-Jul-16	D.Kellyman	8-Nov-16	Roof edge flashing missing (2') (new).
	HBL 081		20-Jul-16	D.Kellyman	8-Nov-16	N.S.M.O.M.O.
	HBL 082		20-Jul-16	D.Kellyman	8-Nov-16	N.S.M.O.M.O.
	HBL 088		20-Jul-16	D.Kellyman	8-Nov-16	N.S.M.O.M.O.
	HBL 090		20-Jul-16	D.Kellyman	8-Nov-16	N.S.M.O.M.O.
	HBL 091		20-Jul-16	D.Kellyman	8-Nov-16	N.S.M.O.M.O.
	HBL 104		20-Jul-16	D.Kellyman	8-Nov-16	N.S.M.O.M.O.
	HBL 089		20-Jul-16	D.Kellyman	8-Nov-16	N.S.M.O.M.O.
E.W. Foster P.S.	HB 086	6	28-Jul-16	D.Kellyman	2-Nov-16	Exterior caulking degraded at front windows (existing).
	HB 129		28-Jul-16	D.Kellyman	2-Nov-16	Exterior caulking degraded at door (existing).
	HB 160		28-Jul-16	D.Kellyman	2-Nov-16	Exterior caulking missing and/or degraded at front windows (existing).
	HB 180		28-Jul-16	D.Kellyman	2-Nov-16	Damaged wood skirting located at the front of the portable (new).
	HB 189		28-Jul-16	D.Kellyman	2-Nov-16	Exterior caulking missing at downspout.
	HBL 248		28-Jul-16	D.Kellyman	2-Nov-16	N.S.M.O.M.O.
Gardiner P.S.	HBL 207	2	29-Jun-16	S.Parliament	2-Nov-16	Degraded caulking around windows (existing).
	HBL 212		29-Jun-16	S.Parliament	2-Nov-16	Hole (1") observed in metal cladding at left elevation. Screw holes observed in corner flashing at left elevation.
Glen Williams P.S.	HB 178	2	29-Jun-16	S.Parliament	2-Nov-16	N.S.M.O.M.O.

PM Inspection Schedule						
School	Portable Number	Portables on Site	Round 99 Inspection Date	ARCADIS Inspector	Proposed Round 100 Inspection Date	Comments from Round 99 Inspection
	HB184		29-Jun-16	S.Parliament	2-Nov-16	<i>Damaged wood skirting located at the rear side of the portable (existing).</i>
Hawthorne Village P.S.	HB 013	17	20-Jul-16	C. Jagarnauth	15-Nov-16	<i>Screw holes observed at front elevation (existing).</i>
	HB 034		20-Jul-16	C. Jagarnauth	15-Nov-16	<i>N.S.M.O.M.O.</i>
	HB 035		20-Jul-16	C. Jagarnauth	15-Nov-16	<i>Exterior caulking degraded at window (existing).</i>
	HB 036		20-Jul-16	C. Jagarnauth	15-Nov-16	<i>N.S.M.O.M.O.</i>
	HB 136		20-Jul-16	C. Jagarnauth	15-Nov-16	<i>Exterior caulking degraded at windows and doors.</i>
	HB 155		20-Jul-16	C. Jagarnauth	15-Nov-16	<i>N.S.M.O.M.O.</i>
	HB 162		20-Jul-16	C. Jagarnauth	15-Nov-16	<i>Screw holes observed at front elevation.</i>
	RM 301		20-Jul-16	C. Jagarnauth	15-Nov-16	<i>N.S.M.O.M.O.</i>
	RM 302		20-Jul-16	C. Jagarnauth	15-Nov-16	<i>N.S.M.O.M.O.</i>
	RM 303		20-Jul-16	C. Jagarnauth	15-Nov-16	<i>N.S.M.O.M.O.</i>
	RM 304		20-Jul-16	C. Jagarnauth	15-Nov-16	<i>N.S.M.O.M.O.</i>
	RM 305		20-Jul-16	C. Jagarnauth	15-Nov-16	<i>N.S.M.O.M.O.</i>
	RM 306		20-Jul-16	C. Jagarnauth	15-Nov-16	<i>N.S.M.O.M.O.</i>
	RM 307		20-Jul-16	C. Jagarnauth	15-Nov-16	<i>N.S.M.O.M.O.</i>
	RM 308		20-Jul-16	C. Jagarnauth	15-Nov-16	<i>N.S.M.O.M.O.</i>
	RM 309		20-Jul-16	C. Jagarnauth	15-Nov-16	<i>N.S.M.O.M.O.</i>
	RM 310		20-Jul-16	C. Jagarnauth	15-Nov-16	<i>N.S.M.O.M.O.</i>
Irma Coulson P.S.	HB 009	14	28-Jul-16	D.Kellyman	15-Nov-16	<i>Screw holes observed in metal cladding at door, front and left elevation (existing). Baseboard (12') detached at south interior wall (existing).</i>
	HB 081		28-Jul-16	D.Kellyman	15-Nov-16	<i>Screw holes observed in metal cladding at front and right elevations (existing). Exterior caulking degraded at conduit (existing).</i>
	HB 142		28-Jul-16	D.Kellyman	15-Nov-16	<i>Exterior caulking degraded and/or missing at conduits at right elevation (existing). Screw holes observed in metal cladding at front elevation (existing).</i>
	HB 146		28-Jul-16	D.Kellyman	15-Nov-16	<i>Exterior caulking degraded at front door (existing).</i>
	HB 150		28-Jul-16	D.Kellyman	15-Nov-16	<i>Screw holes observed in metal cladding at front elevation (existing).</i>
	HBL 242		28-Jul-16	D.Kellyman	15-Nov-16	<i>Exterior caulking degraded at window. Screw holes observed in metal cladding at left elevation.</i>
	HBL 243		28-Jul-16	D.Kellyman	15-Nov-16	<i>Screw holes observed in corner flashing at left elevation. Downspout detached at left elevation.</i>
	HBL 244		28-Jul-16	D.Kellyman	15-Nov-16	<i>N.S.M.O.M.O.</i>
	HBL 245		28-Jul-16	D.Kellyman	15-Nov-16	<i>Corner flashing damaged at front elevation (existing).</i>
	HBL 246		28-Jul-16	D.Kellyman	15-Nov-16	<i>Screw holes observed in metal cladding at right elevation.</i>
	HB 204		28-Jul-16	D.Kellyman	15-Nov-16	<i>Exterior caulking missing at windows, door, and air-exchanger vent.</i>
	HBL 111		28-Jul-16	D.Kellyman	15-Nov-16	<i>N.S.M.O.M.O.</i>
	HB 196		28-Jul-16	D.Kellyman	15-Nov-16	<i>N.S.M.O.M.O.</i>
	HB 149		28-Jul-16	D.Kellyman	15-Nov-16	<i>N.S.M.O.M.O.</i>
Milton District H.S.	HB 001	3	20-Jul-16	D.Kellyman	8-Nov-16	<i>N.S.M.O.M.O.</i>
	HB 093		20-Jul-16	D.Kellyman	8-Nov-16	<i>Wood fascia damaged below eavestrough at front elevation. Hole (2") in cladding near roof at rear elevation.</i>
	HB 154		20-Jul-16	D.Kellyman	8-Nov-16	<i>Exterior caulking degraded at conduit (existing) and air conditioning unit (new).</i>
P.L. Robertson P.S.	HB 004	8	26-Jul-16	C. Jagarnauth	29-Nov-16	<i>Exterior caulking missing from window and door (existing).</i>
	HB 016		26-Jul-16	C. Jagarnauth	29-Nov-16	<i>Exterior caulking missing from window and door (existing).</i>
	HB 021		26-Jul-16	C. Jagarnauth	29-Nov-16	<i>N.S.M.O.M.O.</i>
	HB 022		26-Jul-16	C. Jagarnauth	29-Nov-16	<i>Exterior caulking missing from window and door (existing).</i>
	HB 027		26-Jul-16	C. Jagarnauth	29-Nov-16	<i>Screw holes at front elevation.</i>
	HB 030		26-Jul-16	C. Jagarnauth	29-Nov-16	<i>Screw holes at front elevation.</i>
	HB 039		26-Jul-16	C. Jagarnauth	29-Nov-16	<i>Screw holes at front and left elevations.</i>
	HBL 091		26-Jul-16	C. Jagarnauth	29-Nov-16	<i>N.S.M.O.M.O.</i>

PM Inspection Schedule						
School	Portable Number	Portables on Site	Round 99 Inspection Date	ARCADIS Inspector	Proposed Round 100 Inspection Date	Comments from Round 99 Inspection
Park P.S.	HB 048	0	29-Jun-16	S.Parliament	-	Portable in the process of being relocated. Portable to be inspected at new location during the next round of inspections.
Robert Baldwin P.S.	HBL 079	2	30-Jun-16	S. Parliament	3-Nov-16	Front downspout detached
	HB 122		30-Jun-16	S. Parliament	3-Nov-16	N.S.M.O.M.O.
Robert Little P.S.	HB 208	2	29-Jun-16	S.Parliament	2-Nov-16	Screw holes observed in metal cladding at front elevation (existing). Stained ceiling tile (~1) observed (new). No moisture observed in ceiling space above.
	HB 107		29-Jun-16	S.Parliament	2-Nov-16	N.S.M.O.M.O.
Sam Sherratt P.S.	HB 082	10	30-Jun-16	C. Jagarnauth	14-Dec-16	N.S.M.O.M.O.
	HB 083		30-Jun-16	C. Jagarnauth	14-Dec-16	N.S.M.O.M.O.
	HBL 087		30-Jun-16	C. Jagarnauth	14-Dec-16	N.S.M.O.M.O.
	HBL 099		30-Jun-16	C. Jagarnauth	14-Dec-16	N.S.M.O.M.O.
	HBL 223		30-Jun-16	C. Jagarnauth	14-Dec-16	Hole (1") observed in metal cladding at right elevation.
	HBL 227		30-Jun-16	C. Jagarnauth	14-Dec-16	Caulking degraded at air- exchanger vent (existing).
	HB 041		30-Jun-16	C. Jagarnauth	14-Dec-16	Exterior caulking missing at rear elevation conduit. Hole in drywall at rear wall. Screw holes at left elevation.
	HB 195		30-Jun-16	C. Jagarnauth	14-Dec-16	Exterior caulking degraded at front door (existing). Screw holes observed in metal cladding at front elevation.
	HB 066		30-Jun-16	C. Jagarnauth	14-Dec-16	Exterior caulking degraded at conduit (existing). Section of metal cladding missing around conduit bracket.
	HB 127		30-Jun-16	C. Jagarnauth	14-Dec-16	Screw holes observed in rear right corner flashing and center flashing at left elevation.
Silver Creek P.S.	HB 029	0	29-Jun-16	S.Parliament	2-Nov-16	Portable in the process of being relocated. Portable to be inspected at new location during the next round of inspections.
	HB 033		29-Jun-16	S.Parliament	2-Nov-16	Portable in the process of being relocated. Portable to be inspected at new location during the next round of inspections.
Tiger Jeet Singh P.S.	HB 063	11	18-Jul-16	D.Kellyman	7-Dec-16	N.S.M.O.M.O.
	HB 095		18-Jul-16	D.Kellyman	7-Dec-16	N.S.M.O.M.O.
	HB 109		18-Jul-16	D.Kellyman	7-Dec-16	N.S.M.O.M.O.
	HB 116		18-Jul-16	D.Kellyman	7-Dec-16	N.S.M.O.M.O.
	HB 126		18-Jul-16	D.Kellyman	7-Dec-16	N.S.M.O.M.O.
	HB 187		18-Jul-16	D.Kellyman	7-Dec-16	Downspout missing at front left corner of portable (existing).
	HBL 098		18-Jul-16	D.Kellyman	7-Dec-16	Downspout damaged at front elevation (existing).
	HBL 013		18-Jul-16	D.Kellyman	7-Dec-16	N.S.M.O.M.O.
	HBL 014		18-Jul-16	D.Kellyman	7-Dec-16	N.S.M.O.M.O.
	HBL 015		18-Jul-16	D.Kellyman	7-Dec-16	N.S.M.O.M.O.
	HBL 213		18-Jul-16	D.Kellyman	7-Dec-16	N.S.M.O.M.O.
W.I. Dick P.S.	HB 002	3	28-Jun-16	S.Parliament	1-Dec-16	Hole (1") observed in metal cladding at rear elevation (existing).
	HB 007		28-Jun-16	S.Parliament	1-Dec-16	Exterior caulking degraded at front door.
	HB 183		28-Jun-16	S.Parliament	1-Dec-16	Hole (1") observed in metal cladding at front elevation (existing.)
<b>Total Number of Portables</b>		<b>157</b>				

Notes:	
Scheduled inspection date subject to change due to availability of manpower and the facility.	
<b>N.S.M.O.M.O. =</b>	No Suspect Mould Or Moisture Observed

PM Inspection Schedule						
School	Portable Number	Portables on Site	Round 99 Inspection Date	ARCADIS Inspector	Proposed Round 100 Inspection Date	Comments from Round 99 Inspection
Abbey Park H.S.	HB 164	4	27-Jul-16	C. Jagarnauth	20-Dec-16	N.S.M.O.M.O.
	HB 108		27-Jul-16	C. Jagarnauth	20-Dec-16	Screw holes observed at rear elevation.
	HB 163		27-Jul-16	C. Jagarnauth	20-Dec-16	N.S.M.O.M.O.
	HBL 224		25-Jul-16	S.Parliament	5-Dec-16	Stained ceiling tile (-2) observed (new). No moisture observed in ceiling space above.
E.J. James P.S.	HB 085	7	03-Aug-16	C. Jagarnauth	12-Dec-16	N.S.M.O.M.O.
	HB 079		03-Aug-16	C. Jagarnauth	12-Dec-16	N.S.M.O.M.O.
	HB 111		03-Aug-16	C. Jagarnauth	12-Dec-16	Floor tiles damaged.
	HB 121		03-Aug-16	C. Jagarnauth	12-Dec-16	N.S.M.O.M.O.
	HB 061		03-Aug-16	C. Jagarnauth	12-Dec-16	N.S.M.O.M.O.
	HBL 09		03-Aug-16	C. Jagarnauth	12-Dec-16	N.S.M.O.M.O.
	HBL 226		05-Aug-16	D. Kellyman	12-Dec-16	N.S.M.O.M.O.
	Iroquois Ridge H.S.		HB 070	4	05-Aug-16	D.Kellyman
HB 209		05-Aug-16	D.Kellyman		8-Dec-16	N.S.M.O.M.O.
HB 202		05-Aug-16	D.Kellyman		8-Dec-16	N.S.M.O.M.O.
HB 088		04-Aug-16	D.Kellyman		8-Dec-16	Screw holes observed in metal cladding at front elevation.
James W. Hill P.S.	HB 080	4	05-Aug-16	D.Kellyman	12-Dec-16	N.S.M.O.M.O.
	HB 099		05-Aug-16	D.Kellyman	12-Dec-16	Exterior caulking degraded at front door (existing).
	HB 176		05-Aug-16	D.Kellyman	12-Dec-16	Vinyl floor tiles (~12) damaged throughout (existing). Baseboard (8') missing at corners (existing). Hole (1") observed in drywall. Wood fascia damaged at left elevation. Large quantities of dirt/debris observed on vapour barrier in ceiling space at C-2.
	HB 086		05-Aug-16	D.Kellyman	12-Dec-16	Screw holes observed in metal cladding at right elevation (existing). Exterior caulking degraded at right elevation conduit (existing).
Joshua Creek P.S.	HB 085	3	05-Aug-16	D.Kellyman	8-Dec-16	Exterior caulking missing at left elevation conduit.
	HB 011		05-Aug-16	D.Kellyman	8-Dec-16	N.S.M.O.M.O.
	HB 077		05-Aug-16	D.Kellyman	8-Dec-16	Exterior caulking degraded at front door (existing). Tear (1") observed in metal cladding at front elevation (existing).
Munn's P.S.	HB 106	4	25-Jul-16	S.Parliament	5-Dec-16	N.S.M.O.M.O.
	HB 177		25-Jul-16	S.Parliament	5-Dec-16	N.S.M.O.M.O.
	HBL 001		25-Jul-16	S.Parliament	5-Dec-16	N.S.M.O.M.O.
	HBL 002		25-Jul-16	S.Parliament	5-Dec-16	N.S.M.O.M.O.
Oakville Trafalgar H.S.	RM 189A	11	03-Aug-16	C. Jagarnauth	30-Nov-16	N.S.M.O.M.O.
	RM 189 B		03-Aug-16	C. Jagarnauth	30-Nov-16	N.S.M.O.M.O.
	RM 190		03-Aug-16	C. Jagarnauth	30-Nov-16	N.S.M.O.M.O.
	RM 191		03-Aug-16	C. Jagarnauth	30-Nov-16	Exterior caulking degraded at top of second window.
	RM 192		03-Aug-16	C. Jagarnauth	30-Nov-16	N.S.M.O.M.O.
	RM 193		03-Aug-16	C. Jagarnauth	30-Nov-16	N.S.M.O.M.O.
	RM 194		03-Aug-16	C. Jagarnauth	30-Nov-16	N.S.M.O.M.O.
	RM 195		03-Aug-16	C. Jagarnauth	30-Nov-16	N.S.M.O.M.O.
	RM 196		03-Aug-16	C. Jagarnauth	30-Nov-16	N.S.M.O.M.O.
	RM 197		03-Aug-16	C. Jagarnauth	30-Nov-16	N.S.M.O.M.O.
RM 198	03-Aug-16	C. Jagarnauth	30-Nov-16	N.S.M.O.M.O.		
Pilgrim Wood P.S.	HB 110	1	25-Jul-16	S.Parliament	5-Dec-16	N.S.M.O.M.O.
Post's Corners P.S.	HB 065	1	26-Aug-16	D. Kellyman	8-Dec-16	Screw holes observed in corner flashing and metal cladding at rear elevation (existing). Exterior caulking missing at front door (existing). Exterior caulking missing at rear elevation conduit (existing). Downspout missing at rear elevation.
Sheridan P.S.	HBL 226	0	05-Aug-16	D.Kellyman	-	Portable in the process of being relocated. Portable to be inspected at new location during the next round of inspections.
<b>Total Number of Portables</b>		<b>39</b>				

Notes:	
Scheduled inspection date subject to change due to availability of manpower and the facility.	
N.S.M.O.M.O. =	No Suspect Mould Or Moisture Observed

**PM Inspection Schedule**

School	Portable Number	Portables on Site	Round 99 Inspection Date	ARCADIS Inspector	Proposed Round 100 Inspection Date	Comments from Round 99 Inspection		
Alexander's P.S.	HB 024	3	28-Jul-16	J. Jones	22-Nov-16	N.S.M.O.M.O.		
	HB 028		28-Jul-16	J. Jones	22-Nov-16	N.S.M.O.M.O.		
	HB 051		28-Jul-16	J. Jones	22-Nov-16	N.S.M.O.M.O.		
	HB 008		28-Jul-16	J. Jones	22-Nov-16	Portable in the process of being relocated. Portable to be inspected at new location during the next round of inspections.		
	HB 032		28-Jul-16	J. Jones	22-Nov-16	Portable in the process of being relocated. Portable to be inspected at new location during the next round of inspections.		
	HBL 241		28-Jul-16	J. Jones	22-Nov-16	Portable in the process of being relocated. Portable to be inspected at new location during the next round of inspections.		
Charles R. Beaudoin P.S.	HBL 100	4	26-Jul-16	D.Kellyman	9-Nov-16	N.S.M.O.M.O.		
	HBL 101		26-Jul-16	D.Kellyman	9-Nov-16	N.S.M.O.M.O.		
	HBL 102		26-Jul-16	D.Kellyman	9-Nov-16	N.S.M.O.M.O.		
	HBL 247		26-Jul-16	D.Kellyman	9-Nov-16	N.S.M.O.M.O.		
Dr. Frank Hayden	HB 059	12	31-Aug-16	C. Jagarnauth	6-Dec-16	Exterior door caulking missing/ degraded (existing).		
	HB 120		31-Aug-16	C. Jagarnauth	6-Dec-16	Exterior door caulking missing/ degraded (existing).		
	HB 137		31-Aug-16	C. Jagarnauth	6-Dec-16	N.S.M.O.M.O.		
	HB 172		31-Aug-16	C. Jagarnauth	6-Dec-16	Exterior door caulking missing/ degraded (existing).		
	HB 207		31-Aug-16	C. Jagarnauth	6-Dec-16	N.S.M.O.M.O.		
	HB 092		31-Aug-16	C. Jagarnauth	6-Dec-16	Exterior door caulking missing/ degraded (existing).		
	HBL 210		31-Aug-16	C. Jagarnauth	6-Dec-16	N.S.M.O.M.O.		
	1114L		31-Aug-16	C. Jagarnauth	6-Dec-16	N.S.M.O.M.O.		
	1362		31-Aug-16	C. Jagarnauth	6-Dec-16	Portable under construction. Portable to be inspected during next round of inspections.		
	HB 010		31-Aug-16	C. Jagarnauth	6-Dec-16	N.S.M.O.M.O.		
	HB 151		31-Aug-16	C. Jagarnauth	6-Dec-16	Portable under construction. Portable to be inspected during next round of inspections.		
			HBL 211		31-Aug-16	C. Jagarnauth	6-Dec-16	N.S.M.O.M.O.
	J.W. Singleton Education Centre		HB 003	5	25-Jul-16	J. Jones	28-Nov-16	N.S.M.O.M.O.
HB 117		25-Jul-16	J. Jones		28-Nov-16	N.S.M.O.M.O.		
HB 118		25-Jul-16	J. Jones		28-Nov-16	N.S.M.O.M.O.		
HB 161		25-Jul-16	J. Jones		28-Nov-16	N.S.M.O.M.O.		
HB 119		25-Jul-16	J. Jones		28-Nov-16	N.S.M.O.M.O.		
John T. Tuck P.S.	HB 064	9	26-Jul-16	D.Kellyman	9-Nov-16	Exterior caulking missing and/or degraded at door (existing).		
	HB 156		26-Jul-16	D.Kellyman	9-Nov-16	Edge flashing missing at front and right elevations (existing).		
	HB 157		26-Jul-16	D.Kellyman	9-Nov-16	Exterior caulking degraded at air conditioning unit.		
	HB 173		26-Jul-16	D.Kellyman	9-Nov-16	Exterior caulking degraded at door.		
	HBL 219		26-Jul-16	D.Kellyman	9-Nov-16	N.S.M.O.M.O.		
	HBL 220		26-Jul-16	D.Kellyman	9-Nov-16	N.S.M.O.M.O.		
	HBL 221		26-Jul-16	D.Kellyman	9-Nov-16	N.S.M.O.M.O.		
	HBL 216		26-Jul-16	D.Kellyman	9-Nov-16	N.S.M.O.M.O.		
	HB 165		27-Jul-16	C. Jagarnauth	21-Nov-16	Exterior caulking degraded at door.		
John W. Boich P.S.	HBL 247	4	28-Jul-16	J. Jones	6-Dec-16	N.S.M.O.M.O.		
	HB 108		28-Jul-16	J. Jones	6-Dec-16	N.S.M.O.M.O.		
	HB 109		28-Jul-16	J. Jones	6-Dec-16	N.S.M.O.M.O. Minor damage observed at bottom of downspout on front elevation. Not significant.		
	HBL 217		28-Jul-16	J. Jones	6-Dec-16	N.S.M.O.M.O.		
L.B. Pearson H.S.	RM 179 A	12	25-Jul-16	J. Jones	28-Nov-16	N.S.M.O.M.O.		
	RM 180		25-Jul-16	J. Jones	28-Nov-16	N.S.M.O.M.O.		
	RM 181		25-Jul-16	J. Jones	28-Nov-16	N.S.M.O.M.O.		
	RM 182		25-Jul-16	J. Jones	28-Nov-16	N.S.M.O.M.O.		

**PM Inspection Schedule**

School	Portable Number	Portables on Site	Round 99 Inspection Date	ARCADIS Inspector	Proposed Round 100 Inspection Date	Comments from Round 99 Inspection
	RM 183		25-Jul-16	J. Jones	28-Nov-16	N.S.M.O.M.O.
	RM 184		25-Jul-16	J. Jones	28-Nov-16	N.S.M.O.M.O.
	RM 185		25-Jul-16	J. Jones	28-Nov-16	N.S.M.O.M.O.
	RM 186		25-Jul-16	J. Jones	28-Nov-16	N.S.M.O.M.O.
	RM 187		25-Jul-16	J. Jones	28-Nov-16	N.S.M.O.M.O.
	RM 188		25-Jul-16	J. Jones	28-Nov-16	N.S.M.O.M.O.
	RM 189		25-Jul-16	J. Jones	28-Nov-16	N.S.M.O.M.O.
	RM 190 A/B		25-Jul-16	J. Jones	28-Nov-16	N.S.M.O.M.O.
M.M. Robinson H.S.	HB 010	0	25-Jul-16	J. Jones	28-Nov-16	<i>Portable in the process of being relocated. Portable to be inspected at new location during the next round of inspections.</i>
	HB 151		25-Jul-16	J. Jones	28-Nov-16	<i>Portable in the process of being relocated. Portable to be inspected at new location during the next round of inspections.</i>
Pineland P.S.	HB 069	6	27-Jul-16	C. Jagarnauth	21-Nov-16	N.S.M.O.M.O.
	HB 128		27-Jul-16	C. Jagarnauth	21-Nov-16	N.S.M.O.M.O.
	HB 096		27-Jul-16	C. Jagarnauth	21-Nov-16	N.S.M.O.M.O.
	HB 006		27-Jul-16	C. Jagarnauth	21-Nov-16	N.S.M.O.M.O.
	HB 067		27-Jul-16	C. Jagarnauth	21-Nov-16	<i>Screw holes observed at front elevation.</i>
	HB 094		27-Jul-16	C. Jagarnauth	21-Nov-16	N.S.M.O.M.O.
Sir E. MacMillan P.S.	HB 017	5	27-Jul-16	C. Jagarnauth	21-Nov-16	N.S.M.O.M.O.
	HB 018		27-Jul-16	C. Jagarnauth	21-Nov-16	N.S.M.O.M.O.
	HB 019		27-Jul-16	C. Jagarnauth	21-Nov-16	N.S.M.O.M.O.
	HB 020		27-Jul-16	C. Jagarnauth	21-Nov-16	N.S.M.O.M.O.
	HB 025		27-Jul-16	C. Jagarnauth	21-Nov-16	N.S.M.O.M.O.
<b>Total Number of Portables</b>		<b>60</b>				

<b>Notes:</b>	
Scheduled inspection date subject to change due to availability of manpower and the facility.	
<b>N.S.M.O.M.O. =</b>	No Suspect Mould Or Moisture Observed

**PM Inspection Schedule**

School	Portable Number	Portables on Site	Round 99 Inspection Date	ARCADIS Inspector	Proposed Round 100 Inspection Date	Comments from Round 99 Inspection
Captain R. Wilson P.S.	HB 014	1	25-Jul-16	S.Parliament	24-Nov-16	N.S.M.O.M.O.
Emily Carr P.S.	HBL 084	2	25-Jul-16	S.Parliament	24-Nov-16	N.S.M.O.M.O.
	HBL 001		25-Jul-16	S.Parliament	24-Nov-16	Portable in the process of being relocated. Portable to be inspected at new location during the next round of inspections.
	HBL 002		25-Jul-16	S.Parliament	24-Nov-16	Portable in the process of being relocated. Portable to be inspected at new location during the next round of inspections.
	HBL 008		25-Jul-16	S.Parliament	24-Nov-16	N.S.M.O.M.O.
Forest Trail P.S.	HB 044	7	04-Aug-16	D.Kellyman	10-Nov-16	Stained ceiling tile (~1) observed along center seam (existing).
	HB 047		04-Aug-16	D.Kellyman	10-Nov-16	N.S.M.O.M.O.
	HB 049		04-Aug-16	D.Kellyman	10-Nov-16	N.S.M.O.M.O.
	HB 050		04-Aug-16	D.Kellyman	10-Nov-16	Exterior caulking degraded at conduit (new).
	HB 052		04-Aug-16	D.Kellyman	10-Nov-16	N.S.M.O.M.O.
	HB 054		04-Aug-16	D.Kellyman	10-Nov-16	N.S.M.O.M.O.
	HB 076		04-Aug-16	D.Kellyman	10-Nov-16	N.S.M.O.M.O.
Oodenawi P.S.	HB 058	2	31-Aug-16	C. Jagarnauth	1-Nov-16	Ceiling tile missing from portable.
	HB 101		31-Aug-16	C. Jagarnauth	1-Nov-16	Screw holes in left elevation flashing.
Palmero P.S.	HB 170	4	27-Jul-16	C. Jagarnauth	24-Nov-16	N.S.M.O.M.O.
	HB 087		27-Jul-16	C. Jagarnauth	24-Nov-16	N.S.M.O.M.O.
	HB 167		27-Jul-16	C. Jagarnauth	24-Nov-16	Exterior caulking missing/ degraded from downspout (existing).
	HB 168		27-Jul-16	C. Jagarnauth	24-Nov-16	N.S.M.O.M.O.
Pine Grove P.S.	HB 043	9	27-Jul-16	C. Jagarnauth	05-Dec-16	N.S.M.O.M.O.
	HB 097		27-Jul-16	C. Jagarnauth	5-Dec-16	Exterior caulking degraded at windows, door and air exchanger (existing).
	HB 123		27-Jul-16	C. Jagarnauth	5-Dec-16	N.S.M.O.M.O.
	HB 130		27-Jul-16	C. Jagarnauth	5-Dec-16	N.S.M.O.M.O.
	HB 131		27-Jul-16	C. Jagarnauth	5-Dec-16	N.S.M.O.M.O.
	HB 158		27-Jul-16	C. Jagarnauth	5-Dec-16	N.S.M.O.M.O.
	HB 159		27-Jul-16	C. Jagarnauth	5-Dec-16	Door caulking degraded (existing).
	HB 171		27-Jul-16	C. Jagarnauth	5-Dec-16	N.S.M.O.M.O.
	HB 175		27-Jul-16	C. Jagarnauth	5-Dec-16	Downspout damaged at front elevation (existing).
Sunningdale P.S.	HB 072	4	27-Jul-16	C. Jagarnauth	8-Dec-16	N.S.M.O.M.O.
	HB 132		27-Jul-16	C. Jagarnauth	8-Dec-16	N.S.M.O.M.O.
	HB 145		27-Jul-16	C. Jagarnauth	8-Dec-16	Downspout damaged at front elevation (existing).
	HB 179		27-Jul-16	C. Jagarnauth	8-Dec-16	N.S.M.O.M.O.
W.H. Morden P.S.	HB 200	9	31-Aug-16	C. Jagarnauth	14-Nov-16	N.S.M.O.M.O.
	HB 199		31-Aug-16	C. Jagarnauth	14-Nov-16	Exterior caulking degraded at windows and doors (existing).
	HB 055		31-Aug-16	C. Jagarnauth	14-Nov-16	N.S.M.O.M.O.
	HB 138		31-Aug-16	C. Jagarnauth	14-Nov-16	N.S.M.O.M.O.
	HBL 007		31-Aug-16	C. Jagarnauth	14-Nov-16	N.S.M.O.M.O.
	HBL 249		31-Aug-16	C. Jagarnauth	14-Nov-16	N.S.M.O.M.O.
	HBL 250		31-Aug-16	C. Jagarnauth	14-Nov-16	N.S.M.O.M.O.
	HBL 201		31-Aug-16	C. Jagarnauth	14-Nov-16	N.S.M.O.M.O.
	HBL 006		31-Aug-16	C. Jagarnauth	14-Nov-16	N.S.M.O.M.O.



**PM Inspection Schedule**

School	Portable Number	Portables on Site	Round 99 Inspection Date	ARCADIS Inspector	Proposed Round 100 Inspection Date	Comments from Round 99 Inspection
West Oak P.S.	RM 1	7	04-Aug-16	D.Kellyman	10-Nov-16	<i>Section (6') of wooden skirting missing.</i>
	RM 2		04-Aug-16	D.Kellyman	10-Nov-16	<i>N.S.M.O.M.O.</i>
	RM 3		04-Aug-16	D.Kellyman	10-Nov-16	<i>N.S.M.O.M.O.</i>
	RM 4		04-Aug-16	D.Kellyman	10-Nov-16	<i>N.S.M.O.M.O.</i>
	RM 5		04-Aug-16	D.Kellyman	10-Nov-16	<i>N.S.M.O.M.O.</i>
	RM 6		04-Aug-16	D.Kellyman	10-Nov-16	<i>N.S.M.O.M.O.</i>
	HB 107		04-Aug-16	D.Kellyman	10-Nov-16	<i>Vinyl floor tiles (~5) damaged throughout (existing).</i>
White Oaks SS North	HB 060	5	25-Jul-16	S.Parliament	14-Nov-16	<i>N.S.M.O.M.O.</i>
	HBL 92		25-Jul-16	S.Parliament	14-Nov-16	<i>N.S.M.O.M.O.</i>
	HBL 93		25-Jul-16	S.Parliament	14-Nov-16	<i>N.S.M.O.M.O.</i>
	HBL 94		25-Jul-16	S.Parliament	14-Nov-16	<i>N.S.M.O.M.O.</i>
	HBL 95		25-Jul-16	S.Parliament	14-Nov-16	<i>N.S.M.O.M.O.</i>
White Oaks SS South	HBL 018	12	03-Aug-16	C. Jagarnauth	1-Nov-16	<i>N.S.M.O.M.O.</i>
	HBL 016		03-Aug-16	C. Jagarnauth	1-Nov-16	<i>N.S.M.O.M.O.</i>
	HB 023		03-Aug-16	C. Jagarnauth	1-Nov-16	<i>N.S.M.O.M.O.</i>
	HB 042		03-Aug-16	C. Jagarnauth	1-Nov-16	<i>N.S.M.O.M.O.</i>
	HB 078		03-Aug-16	C. Jagarnauth	1-Nov-16	<i>N.S.M.O.M.O.</i>
	HB 112		03-Aug-16	C. Jagarnauth	1-Nov-16	<i>N.S.M.O.M.O.</i>
	HB 153		03-Aug-16	C. Jagarnauth	1-Nov-16	<i>N.S.M.O.M.O.</i>
	HB 201		03-Aug-16	C. Jagarnauth	1-Nov-16	<i>N.S.M.O.M.O.</i>
	HB 205		03-Aug-16	C. Jagarnauth	1-Nov-16	<i>N.S.M.O.M.O.</i>
	HBL 17		03-Aug-16	C. Jagarnauth	1-Nov-16	<i>N.S.M.O.M.O.</i>
	HBL 096		03-Aug-16	C. Jagarnauth	1-Nov-16	<i>N.S.M.O.M.O.</i>
	HBL 097		03-Aug-16	C. Jagarnauth	1-Nov-16	<i>N.S.M.O.M.O.</i>
<b>Total Number of Portables</b>		<b>62</b>				

Notes:	
Scheduled inspection date subject to change due to availability of manpower and the facility.	
<b>N.S.M.O.M.O. =</b>	No Suspect Mould Or Moisture Observed

PM Inspection Schedule						
School	Portable Number	Portables on Site	Round 99 Inspection Date	ARCADIS Inspector	Proposed Round 100 Inspection Date	Comments from Round 99 Inspection
Alton Village P.S.	HBL 234	9	03-Aug-16	C. Jagarnauth	23-Nov-16	N.S.M.O.M.O.
	HBL 235		03-Aug-16	C. Jagarnauth	23-Nov-16	N.S.M.O.M.O.
	HBL 236		03-Aug-16	C. Jagarnauth	23-Nov-16	N.S.M.O.M.O.
	HBL 237		03-Aug-16	C. Jagarnauth	23-Nov-16	N.S.M.O.M.O.
	HBL 238		03-Aug-16	C. Jagarnauth	23-Nov-16	N.S.M.O.M.O.
	HBL 239		03-Aug-16	C. Jagarnauth	23-Nov-16	Screw holes observed in metal cladding and center flashing at left elevation.
	HB 037		03-Aug-16	C. Jagarnauth	23-Nov-16	N.S.M.O.M.O.
	HB 068		03-Aug-16	C. Jagarnauth	23-Nov-16	N.S.M.O.M.O.
	HBL 225		03-Aug-16	C. Jagarnauth	23-Nov-16	N.S.M.O.M.O.
Dr. Charles Best P.S.	HBL 210	0	25 July 16	C. Jagarnauth	-	Portable in the process of being relocated. Portable to be inspected at new location during the next round of inspections.
	HBL 211		25 July 16	C. Jagarnauth	-	Portable in the process of being relocated. Portable to be inspected at new location during the next round of inspections.
Florence Meares P.S.	HB 139	1	03-Aug-16	C. Jagarnauth	23-Nov-16	Screw holes at rear elevation
Kilbride P.S.	HB 074	1	03-Aug-16	C. Jagarnauth	7-Nov-16	Holes observed in front and rear skirting.
Orchard Park P.S.	HB 040	4	28-Jul-16	J. Jones	22-Nov-16	N.S.M.O.M.O.
	HB 147		28-Jul-16	J. Jones	22-Nov-16	N.S.M.O.M.O.
	HB 166		28-Jul-16	J. Jones	22-Nov-16	N.S.M.O.M.O.
	HB 140		28-Jul-16	J. Jones	22-Nov-16	N.S.M.O.M.O.
Pauline Johnson P.S.	HBL 222	2	27-Jul-16	C. Jagarnauth	21-Nov-16	N.S.M.O.M.O.
	HB 102		27-Jul-16	C. Jagarnauth	21-Nov-16	N.S.M.O.M.O.
Tom Thompson P.S.	HB 169	10	25 July 16	C. Jagarnauth	17-Nov-16	N.S.M.O.M.O.
	HB 098		25 July 16	C. Jagarnauth	17-Nov-16	Exterior caulking degraded at conduit. Holes in metal cladding.
	HB 012		25 July 16	C. Jagarnauth	17-Nov-16	Holes in front elevation.
	HB 031		25 July 16	C. Jagarnauth	17-Nov-16	Holes in front elevation.
	HB 053		25 July 16	C. Jagarnauth	17-Nov-16	N.S.M.O.M.O.
	HB 105		25 July 16	C. Jagarnauth	17-Nov-16	N.S.M.O.M.O.
	HB 124		25 July 16	C. Jagarnauth	17-Nov-16	Holes in front elevation.
	HB 141		25 July 16	C. Jagarnauth	17-Nov-16	Door caulking degraded at front door
	HB 148		25 July 16	C. Jagarnauth	17-Nov-16	N.S.M.O.M.O.
	HB 205		25 July 16	C. Jagarnauth	17-Nov-16	N.S.M.O.M.O.
	<b>Total Number of Portables</b>		<b>27</b>			

Notes:	
Scheduled inspection date subject to change due to availability of manpower and the facility.	
<b>N.S.M.O.M.O. =</b>	No Suspect Mould Or Moisture Observed