

**TABLE 1
PORTABLE CLASSROOM PREVENTATIVE MAINTENANCE INSPECTION NO. 94 SUMMARY**

School	Portable Number	Portables on Site	PM Inspection Schedule		Proposed Round 95 Inspection Date	Comments from Round 94 Inspection
			Round 94 Inspection Date	ARCADIS Inspector		
Anne J. MacArthur P.S.	HB 026	15	22-Jul-15	D.Kellyman	17-Sep-15	<i>Portable in the process of being relocated.</i>
	HB 071		22-Jul-15	D.Kellyman	17-Sep-15	<i>Portable in the process of being relocated.</i>
	HB 113		22-Jul-15	D.Kellyman	17-Sep-15	<i>Portable not present on site at the time of inspection. Portable to be inspected at new location during next round of inspections.</i>
	HB 125		22-Jul-15	D.Kellyman	17-Sep-15	<i>Portable not present on site at the time of inspection. Portable to be inspected at new location during next round of inspections.</i>
	HB 127		22-Jul-15	D.Kellyman	17-Sep-15	<i>Portable not present on site at the time of inspection. Portable to be inspected at new location during next round of inspections.</i>
	HB 204		22-Jul-15	D.Kellyman	17-Sep-15	<i>Portable not present on site at the time of inspection. Portable to be inspected at new location during next round of inspections.</i>
	HBL 111		22-Jul-15	D.Kellyman	17-Sep-15	<i>Portable not present on site at the time of inspection. Portable to be inspected at new location during next round of inspections.</i>
	HBL 202		22-Jul-15	D.Kellyman	17-Sep-15	<i>N.S.M.O.M.O.</i>
	HBL 203		22-Jul-15	D.Kellyman	17-Sep-15	<i>N.S.M.O.M.O.</i>
	HBL 204		22-Jul-15	D.Kellyman	17-Sep-15	<i>N.S.M.O.M.O.</i>
	HBL 205		22-Jul-15	D.Kellyman	17-Sep-15	<i>N.S.M.O.M.O.</i>
	HBL 214		22-Jul-15	D.Kellyman	17-Sep-15	<i>N.S.M.O.M.O.</i>
	HBL 215		22-Jul-15	D.Kellyman	17-Sep-15	<i>N.S.M.O.M.O.</i>
	HBL 232		22-Jul-15	D.Kellyman	17-Sep-15	<i>N.S.M.O.M.O.</i>
	HBL 233		22-Jul-15	D.Kellyman	17-Sep-15	<i>Stained ceiling tiles (2) observed (new).</i>
Brookville P.S.	HBL 201	1	11-Aug-15	S.Parliament	1-Oct-15	<i>N.S.M.O.M.O.</i>
Bruce Trail P.S.	HB 046	13	28-Jul-15	D.Kellyman	23-Sep-15	<i>Exterior caulking degraded at second window.</i>
	HB 062		28-Jul-15	D.Kellyman	23-Sep-15	<i>N.S.M.O.M.O.</i>
	HB 075		28-Jul-15	D.Kellyman	23-Sep-15	<i>Exterior caulking degraded at both windows. Vinyl floor tiles (~4) damaged throughout.</i>
	HB 103		28-Jul-15	D.Kellyman	23-Sep-15	<i>Exterior caulking degraded at door.</i>
	HB 110		28-Jul-15	D.Kellyman	23-Sep-15	<i>N.S.M.O.M.O.</i>
	HB 114		28-Jul-15	D.Kellyman	23-Sep-15	<i>N.S.M.O.M.O.</i>
	HB 115		28-Jul-15	D.Kellyman	23-Sep-15	<i>Exterior caulking degraded at conduit.</i>
	HB 149		28-Jul-15	D.Kellyman	23-Sep-15	<i>Hole (.5") and screw holes observed in metal cladding at front elevation.</i>
	HBL 105		28-Jul-15	D.Kellyman	23-Sep-15	<i>N.S.M.O.M.O.</i>
	HBL 228		28-Jul-15	D.Kellyman	23-Sep-15	<i>N.S.M.O.M.O.</i>
	HBL 229		28-Jul-15	D.Kellyman	23-Sep-15	<i>N.S.M.O.M.O.</i>
	HBL 230		28-Jul-15	D.Kellyman	23-Sep-15	<i>N.S.M.O.M.O.</i>
	HBL 231		28-Jul-15	D.Kellyman	23-Sep-15	<i>N.S.M.O.M.O.</i>
Chris Hadfield P.S.	RM A1	12	11-Aug-15	S.Parliament	1-Oct-15	<i>N.S.M.O.M.O.</i>
	RM A2		11-Aug-15	S.Parliament	1-Oct-15	<i>N.S.M.O.M.O.</i>
	RM A3		11-Aug-15	S.Parliament	1-Oct-15	<i>N.S.M.O.M.O.</i>
	RM A4		11-Aug-15	S.Parliament	1-Oct-15	<i>N.S.M.O.M.O.</i>
	RM A5		11-Aug-15	S.Parliament	1-Oct-15	<i>N.S.M.O.M.O.</i>
	RM A6		11-Aug-15	S.Parliament	1-Oct-15	<i>N.S.M.O.M.O.</i>
	RM A7		11-Aug-15	S.Parliament	1-Oct-15	<i>N.S.M.O.M.O.</i>
	RM A8		11-Aug-15	S.Parliament	1-Oct-15	<i>N.S.M.O.M.O.</i>
	RM A9		11-Aug-15	S.Parliament	1-Oct-15	<i>N.S.M.O.M.O.</i>
	RM A10		11-Aug-15	S.Parliament	1-Oct-15	<i>N.S.M.O.M.O.</i>
	RM A11		11-Aug-15	S.Parliament	1-Oct-15	<i>N.S.M.O.M.O.</i>
			HBL 106		11-Aug-15	S.Parliament
Craig Kielburger S.S.	HB 038	21	01-Sep-15	S.Parliament	29-Sept-15	<i>N.S.M.O.M.O.</i>
	HB 045		01-Sep-15	S.Parliament	29-Sept-15	<i>Screw holes observed in metal cladding and corner flashing at left elevation (existing). Exterior caulking degraded at bottom of second window.</i>
	HB 056		01-Sep-15	S.Parliament	29-Sept-15	<i>N.S.M.O.M.O.</i>
	HB 057		01-Sep-15	S.Parliament	29-Sept-15	<i>N.S.M.O.M.O.</i>

**TABLE 1
PORTABLE CLASSROOM PREVENTATIVE MAINTENANCE INSPECTION NO. 94 SUMMARY**

School	Portable Number	Portables on Site	PM Inspection Schedule		Proposed Round 95 Inspection Date	Comments from Round 94 Inspection
			Round 94 Inspection Date	ARCADIS Inspector		
	HB 073		01-Sep-15	S.Parliament	29-Sept-15	N.S.M.O.M.O.
	HB 090		01-Sep-15	S.Parliament	29-Sept-15	N.S.M.O.M.O.
	HB 091		01-Sep-15	S.Parliament	29-Sept-15	N.S.M.O.M.O.
	HB 100		01-Sep-15	S.Parliament	29-Sept-15	N.S.M.O.M.O.
	HB 133		01-Sep-15	S.Parliament	29-Sept-15	N.S.M.O.M.O.
	HB 134		01-Sep-15	S.Parliament	29-Sept-15	Screw holes observed in metal cladding at front and rear elevations. Exterior caulking degraded at conduits.
	HB 113		01-Sep-15	S.Parliament	29-Sept-15	Exterior caulking degraded and/or missing at door, air-conditioner supports and conduits. Screw holes observed in metal cladding at front and right elevations.
	HB 125		01-Sep-15	S.Parliament	29-Sept-15	Exterior caulking missing at front door. Screw holes observed at metal cladding at front and rear elevations.
	HB 180		01-Sep-15	S.Parliament	29-Sept-15	N.S.M.O.M.O.
	HB 189		01-Sep-15	S.Parliament	29-Sept-15	N.S.M.O.M.O.
	HBL 086		01-Sep-15	S.Parliament	29-Sept-15	N.S.M.O.M.O.
Escarpment View P.S.	HBL 212	14	04-Aug-15	D.Kellyman	28-Sep-15	Portable not present on site at the time of inspection. Portable to be inspected at new location during next round of inspections.
	HBL 213		04-Aug-15	D.Kellyman	28-Sep-15	Portable not present on site at the time of inspection. Portable to be inspected at new location during next round of inspections.
	HBL 103		04-Aug-15	D.Kellyman	28-Sep-15	N.S.M.O.M.O.
	HB 005		04-Aug-15	D.Kellyman	28-Sep-15	N.S.M.O.M.O.
	HB 089		04-Aug-15	D.Kellyman	28-Sep-15	N.S.M.O.M.O.
	HB 144		04-Aug-15	D.Kellyman	28-Sep-15	N.S.M.O.M.O.
	HBL 081		04-Aug-15	D.Kellyman	28-Sep-15	N.S.M.O.M.O.
	HBL 082		04-Aug-15	D.Kellyman	28-Sep-15	N.S.M.O.M.O.
	HBL 083		04-Aug-15	D.Kellyman	28-Sep-15	N.S.M.O.M.O.
	HBL 088		04-Aug-15	D.Kellyman	28-Sep-15	N.S.M.O.M.O.
	HBL 090		04-Aug-15	D.Kellyman	28-Sep-15	N.S.M.O.M.O.
	HBL 091		04-Aug-15	D.Kellyman	28-Sep-15	N.S.M.O.M.O.
	HBL 104		04-Aug-15	D.Kellyman	28-Sep-15	N.S.M.O.M.O.
	HBL 089		04-Aug-15	D.Kellyman	28-Sep-15	N.S.M.O.M.O.
Gardiner P.S.	HBL 207	1	27-Jul-15	D.Kellyman	22-Sep-15	N.S.M.O.M.O.
Glen Williams P.S.	HB 178	2	27-Jul-15	D.Kellyman	22-Sep-15	N.S.M.O.M.O.
	HB 184		27-Jul-15	D.Kellyman	22-Sep-15	Eavestrough (5') damaged at front elevation.
Hawthorne Village P.S.	HB 013	22	13-Aug-15	S.Parliament	6-Oct-15	N.S.M.O.M.O.
	HB 034		13-Aug-15	S.Parliament	6-Oct-15	Exterior caulking degraded at door. Screw holes observed in metal cladding at front and right elevations.
	HB 035		13-Aug-15	S.Parliament	6-Oct-15	Hole (1") and screw holes observed in metal cladding at left elevation.
	HB 036		13-Aug-15	S.Parliament	6-Oct-15	N.S.M.O.M.O.
	HB 136		13-Aug-15	S.Parliament	6-Oct-15	N.S.M.O.M.O.
	HB 155		13-Aug-15	S.Parliament	6-Oct-15	Hole (1") observed in metal cladding at left elevation due to missing caulking.
	HB 162		13-Aug-15	S.Parliament	6-Oct-15	N.S.M.O.M.O.
	RM 101		13-Aug-15	S.Parliament	6-Oct-15	N.S.M.O.M.O.
	RM 102		13-Aug-15	S.Parliament	6-Oct-15	N.S.M.O.M.O.
	RM 103		13-Aug-15	S.Parliament	6-Oct-15	N.S.M.O.M.O.
	RM 104		13-Aug-15	S.Parliament	6-Oct-15	N.S.M.O.M.O.
	RM 105		13-Aug-15	S.Parliament	6-Oct-15	N.S.M.O.M.O.
	RM 301		13-Aug-15	S.Parliament	6-Oct-15	N.S.M.O.M.O.
	RM 302		13-Aug-15	S.Parliament	6-Oct-15	N.S.M.O.M.O.
	RM 303		13-Aug-15	S.Parliament	6-Oct-15	N.S.M.O.M.O.
	RM 304		13-Aug-15	S.Parliament	6-Oct-15	N.S.M.O.M.O.
	RM 305		13-Aug-15	S.Parliament	6-Oct-15	N.S.M.O.M.O.
	RM 306		13-Aug-15	S.Parliament	6-Oct-15	N.S.M.O.M.O.
	RM 307		13-Aug-15	S.Parliament	6-Oct-15	N.S.M.O.M.O.

**TABLE 1
PORTABLE CLASSROOM PREVENTATIVE MAINTENANCE INSPECTION NO. 94 SUMMARY**

School	Portable Number	Portables on Site	PM Inspection Schedule		Proposed Round 95 Inspection Date	Comments from Round 94 Inspection
			Round 94 Inspection Date	ARCADIS Inspector		
	RM 308		13-Aug-15	S.Parliament	6-Oct-15	N.S.M.O.M.O.
	RM 309		13-Aug-15	S.Parliament	6-Oct-15	N.S.M.O.M.O.
	RM 310		13-Aug-15	S.Parliament	6-Oct-15	N.S.M.O.M.O.
Irma Coulson P.S.	HB 009	10	23-Jul-15	S.Parliament	15-Sep-15	N.S.M.O.M.O.
	HB 081		23-Jul-15	S.Parliament	15-Sep-15	N.S.M.O.M.O.
	HB 142		23-Jul-15	S.Parliament	15-Sep-15	N.S.M.O.M.O.
	HB 146		23-Jul-15	S.Parliament	15-Sep-15	N.S.M.O.M.O.
	HB 150		23-Jul-15	S.Parliament	15-Sep-15	N.S.M.O.M.O.
	HBL 242		23-Jul-15	S.Parliament	15-Sep-15	N.S.M.O.M.O.
	HBL 243		23-Jul-15	S.Parliament	15-Sep-15	Exterior caulking missing at first window. Screw holes observed in metal cladding and corner flashing at left elevation. Downspout detached at left elevation.
	HBL 244		23-Jul-15	S.Parliament	15-Sep-15	N.S.M.O.M.O.
	HBL 245		23-Jul-15	S.Parliament	15-Sep-15	N.S.M.O.M.O.
	HBL 246		23-Jul-15	S.Parliament	15-Sep-15	N.S.M.O.M.O.
Martin Street P.S.	HB 152	2	31-Aug-15	C. Jagarnauth	12-Oct-15	N.S.M.O.M.O.
	HB 015		31-Aug-15	C. Jagarnauth	12-Oct-15	Screw holes observed at front.
Milton District H.S.	HB 001	3	31-Aug-15	C. Jagarnauth	24-Sept-15	Skirting damaged at right, left and rear elevations.
	HB 093		31-Aug-15	C. Jagarnauth	24-Sept-15	N.S.M.O.M.O.
	HB 154		31-Aug-15	C. Jagarnauth	24-Sept-15	Eavestrough damaged at rear.
P.L. Robertson P.S.	HB 004	7	31-Aug-15	C. Jagarnauth	12-Oct-15	N.S.M.O.M.O.
	HB 016		31-Aug-15	C. Jagarnauth	12-Oct-15	N.S.M.O.M.O.
	HB 021		31-Aug-15	C. Jagarnauth	12-Oct-15	N.S.M.O.M.O.
	HB 022		31-Aug-15	C. Jagarnauth	12-Oct-15	N.S.M.O.M.O.
	HB 027		31-Aug-15	C. Jagarnauth	12-Oct-15	N.S.M.O.M.O.
	HB 030		31-Aug-15	C. Jagarnauth	12-Oct-15	Hole (~1") observed in metal cladding at right elevation.
	HB 039		31-Aug-15	C. Jagarnauth	12-Oct-15	Exterior caulking degraded at air-exchanger vent.
Park P.S.	HB 048	1	27-Jul-15	S.Parliament	22-Sep-15	N.S.M.O.M.O.
Robert Baldwin P.S.	HB 122	4	10-Aug-15	S.Parliament	29-Sep-15	Screw holes observed in metal cladding at front elevation.
	HB 174		10-Aug-15	S.Parliament	29-Sep-15	Tear (2") observed in center flashing at left elevation.
	HBL 079		10-Aug-15	S.Parliament	29-Sep-15	N.S.M.O.M.O.
	HBL 248 (1072)		10-Aug-15	S.Parliament	29-Sep-15	N.S.M.O.M.O.
Robert Little P.S.	HB 208	2	27-Jul-15	D.Kellyman	22-Sep-15	N.S.M.O.M.O.
	HBL 10		27-Jul-15	D.Kellyman	22-Sep-15	N.S.M.O.M.O.
Sam Sherratt P.S.	HB 082	9	05-Sep-15	S.Parliament	1-Oct-15	Exterior caulking degraded at conduit.
	HB 083		05-Sep-15	S.Parliament	1-Oct-15	N.S.M.O.M.O.
	HBL 087		05-Sep-15	S.Parliament	1-Oct-15	N.S.M.O.M.O.
	HBL 099		05-Sep-15	S.Parliament	1-Oct-15	N.S.M.O.M.O.
	HBL 223		05-Sep-15	S.Parliament	1-Oct-15	N.S.M.O.M.O.
	HBL 227		05-Sep-15	S.Parliament	1-Oct-15	N.S.M.O.M.O.
	HB 041		05-Sep-15	S.Parliament	1-Oct-15	Screw holes observed in metal cladding at right elevation.
	HB 195		05-Sep-15	S.Parliament	1-Oct-15	Exterior caulking degraded at front door. Screw holes observed in both corner flashings at left elevation. Center flashing damaged and/or torn off leaving sharp edges.
	HB 066		05-Sep-15	S.Parliament	1-Oct-15	Exterior caulking degraded at conduit. Section of metal cladding (5"x4') missing around conduit support.

**TABLE 1
PORTABLE CLASSROOM PREVENTATIVE MAINTENANCE INSPECTION NO. 94 SUMMARY**

School	Portable Number	Portables on Site	PM Inspection Schedule		Proposed Round 95 Inspection Date	Comments from Round 94 Inspection
			Round 94 Inspection Date	ARCADIS Inspector		
Silver Creek P.S.	HB 029	2	27-Jul-15	D.Kellyman	22-Sep-15	<i>N.S.M.O.M.O.</i>
	HB 033		27-Jul-15	D.Kellyman	22-Sep-15	<i>N.S.M.O.M.O.</i>
Tiger Jeet Singh P.S.	HB 063	11	26-Aug-15	D.Kellyman	24-Sept-15	<i>Exterior caulking degraded at door and air-exchanger vent.</i>
	HB 095		26-Aug-15	D.Kellyman	24-Sept-15	<i>N.S.M.O.M.O.</i>
	HB 109		26-Aug-15	D.Kellyman	24-Sept-15	<i>Exterior caulking degraded at windows and door (new).</i>
	HB 116		26-Aug-15	D.Kellyman	24-Sept-15	<i>Exterior caulking missing at gable-louvre at right elevation.</i>
	HB 126		26-Aug-15	D.Kellyman	24-Sept-15	<i>N.S.M.O.M.O.</i>
	HB 187		26-Aug-15	D.Kellyman	24-Sept-15	<i>N.S.M.O.M.O.</i>
	HBL 013		26-Aug-15	D.Kellyman	24-Sept-15	<i>Exterior caulking degraded at window.</i>
	HBL 014		26-Aug-15	D.Kellyman	24-Sept-15	<i>N.S.M.O.M.O.</i>
	HBL 015		26-Aug-15	D.Kellyman	24-Sept-15	<i>N.S.M.O.M.O.</i>
	HBL 098		26-Aug-15	D.Kellyman	24-Sept-15	<i>N.S.M.O.M.O.</i>
	HBL 213		26-Aug-15	D.Kellyman	24-Sept-15	<i>N.S.M.O.M.O.</i>
W.I. Dick P.S.	HB 002	3	31-Aug-15	C. Jagarnauth	12-Oct-15	<i>Caulking missing around 1" hole observed at rear wall.</i>
	HB 007		31-Aug-15	C. Jagarnauth	12-Oct-15	<i>Vinyl floor tiles (~5) damaged throughout. Front downspout damaged.</i>
	HB 183		31-Aug-15	C. Jagarnauth	12-Oct-15	<i>Hole (1") observed at front wall.</i>
Total Portables:		155				

NOTE:

Scheduled inspection date subject to change due to availability of manpower and the facility.

N.S.M.O.M.O. = No Suspect Mold or Moisture Observed

**TABLE 1
PORTABLE CLASSROOM PREVENTATIVE MAINTENANCE INSPECTION NO. 94 SUMMARY**

School	Portable Number	Portables on Site	PM Inspection Schedule		Proposed Round 95 Inspection Date	Comments from Round 94 Inspection
			Round 94 Inspection Date	ARCADIS Inspector		
Abbey Park H.S.	HB 164	3	12-Aug-15	J. Jones	15-Oct-15	<i>N.S.M.O.M.O.</i>
	HB 108		12-Aug-15	J. Jones	15-Oct-15	<i>N.S.M.O.M.O.</i>
	HB 163		12-Aug-15	J. Jones	15-Oct-15	<i>N.S.M.O.M.O.</i>
E.J. James P.S.	HB 061	5	17-Jul-15	S.Parliament	8-Sept-15	<i>N.S.M.O.M.O.</i>
	HB 079		17-Jul-15	S.Parliament	8-Sept-15	<i>Screw holes observed in metal cladding at front elevation.</i>
	HB 111		17-Jul-15	S.Parliament	8-Sept-15	<i>N.S.M.O.M.O.</i>
	HB 121		17-Jul-15	S.Parliament	8-Sept-15	<i>N.S.M.O.M.O.</i>
	HBL 009		17-Jul-15	S.Parliament	8-Sept-15	<i>N.S.M.O.M.O.</i>
Heritage Glen P.S.	HBL 216	4	05-Sep-15	S.Parliament	15-Oct-15	<i>Portable not present on site at the time of inspection. Portable to be inspected at new location during next round of inspections.</i>
	HBL 217		05-Sep-15	S.Parliament	15-Oct-15	<i>Portable not present on site at the time of inspection. Portable to be inspected at new location during next round of inspections.</i>
	HBL 218		05-Sep-15	S.Parliament	15-Oct-15	<i>Portable not present on site at the time of inspection. Portable to be inspected at new location during next round of inspections.</i>
	HBL 241		05-Sep-15	S.Parliament	15-Oct-15	<i>Portable not present on site at the time of inspection. Portable to be inspected at new location during next round of inspections.</i>
Iroquois Ridge H.S.	HB 070	2	16-Jul-15	S.Parliament	7-Sept-15	<i>Wooden skirting damaged at front elevation.</i>
	HB 209		16-Jul-15	S.Parliament	7-Sept-15	<i>N.S.M.O.M.O.</i>
James W. Hill P.S.	HB 080	3	16-Jul-15	S.Parliament	10-Sept-15	<i>N.S.M.O.M.O.</i>
	HB 099		16-Jul-15	S.Parliament	10-Sept-15	<i>N.S.M.O.M.O.</i>
	HB 176		16-Jul-15	S.Parliament	10-Sept-15	<i>N.S.M.O.M.O.</i>
Joshua Creek P.S.	HB 011	5	16-Jul-15	S.Parliament	7-Sept-15	<i>N.S.M.O.M.O.</i>
	HB 077		16-Jul-15	S.Parliament	7-Sept-15	<i>N.S.M.O.M.O.</i>
	HB 085		16-Jul-15	S.Parliament	7-Sept-15	<i>Screw holes observed in metal cladding at left and front elevations (existing). Exterior caulking degraded at conduit.</i>
	HB 199		16-Jul-15	S.Parliament	7-Sept-15	<i>N.S.M.O.M.O.</i>
	HB 200		16-Jul-15	S.Parliament	7-Sept-15	<i>Portable not present on site at the time of inspection. Portable to be inspected at new location during next round of inspections.</i>
Munn's P.S.	HB 106	2	14-May-15	C. Jagarnauth	14-Sept-15	<i>Front stairwell missing from the portable. Screw holes observed at the front elevation. Skirting missing at the right elevation. Front window only has one pane. Portable not joint securely at the centre.</i>
	HB 177		14-May-15	C. Jagarnauth	14-Sept-15	<i>N.S.M.O.M.O.</i>
Oakville Trafalgar H.S. (Portable Relocatable)	RM 190	7	17-Jul-15	S.Parliament	8-Sept-15	<i>N.S.M.O.M.O.</i>
	RM 191		17-Jul-15	S.Parliament	8-Sept-15	<i>N.S.M.O.M.O.</i>
	RM 192		17-Jul-15	S.Parliament	8-Sept-15	<i>N.S.M.O.M.O.</i>
	RM 193		17-Jul-15	S.Parliament	8-Sept-15	<i>N.S.M.O.M.O.</i>
	RM 194		17-Jul-15	S.Parliament	8-Sept-15	<i>N.S.M.O.M.O.</i>
	RM 198		17-Jul-15	S.Parliament	8-Sept-15	<i>N.S.M.O.M.O.</i>
	RM 199		17-Jul-15	S.Parliament	8-Sept-15	<i>N.S.M.O.M.O.</i>
Pilgrim Wood P.S.	HBL 110	2	27-Aug-15	C. Jagarnauth	15-Oct-15	<i>N.S.M.O.M.O.</i>
	HBL 224		27-Aug-15	C. Jagarnauth	15-Oct-15	<i>N.S.M.O.M.O.</i>
Post's Corners P.S.	HB 065	1	16-Jul-15	S.Parliament	10-Sept-15	<i>Exterior caulking degraded at first window. Hole (1") observed in metal cladding at rear elevation.</i>
Sheridan P.S.	HBL 226	1	16-Jul-15	S.Parliament	10-Sept-15	<i>N.S.M.O.M.O.</i>

**TABLE 1
PORTABLE CLASSROOM PREVENTATIVE MAINTENANCE INSPECTION NO. 94 SUMMARY**

School	Portable Number	Portables on Site	PM Inspection Schedule		Proposed Round 95 Inspection Date	Comments from Round 94 Inspection
			Round 94 Inspection Date	ARCADIS Inspector		
River Oaks P.S.	HB 088	3	27-Aug-15	C. Jagarnauth	14-Oct-15	<i>Skirting missing at left elevation.</i>
	HB 196		05-Sep-15	S. Parliament	14-Oct-15	<i>N.S.M.O.M.O.</i>
	HB 202		05-Sep-15	S. Parliament	14-Oct-15	<i>Portable not present on site at the time of inspection. Portable to be inspected at new location during next round of inspections.</i>
Total Portables:		38				

NOTE:

Scheduled inspection date subject to change due to availability of manpower and the facility.

N.S.M.O.M.O.= No Suspect Mould or Moisture Observed

**TABLE 1
PORTABLE CLASSROOM PREVENTATIVE MAINTENANCE INSPECTION NO. 94 SUMMARY**

School	Portable Number	Portables on Site	PM Inspection Schedule		Proposed Round 95 Inspection Date	Comments from Round 94 Inspection
			Round 94 Inspection Date	ARCADIS Inspector		
Alexander's P.S.	HB 008	5	25-Aug-15	J. Jones	19-Oct-15	<i>N.S.M.O.M.O.</i>
	HB 024		25-Aug-15	J. Jones	19-Oct-15	<i>N.S.M.O.M.O.</i>
	HB 028		25-Aug-15	J. Jones	19-Oct-15	<i>N.S.M.O.M.O.</i>
	HB 032		25-Aug-15	J. Jones	19-Oct-15	<i>N.S.M.O.M.O.</i>
	HB 051		25-Aug-15	J. Jones	19-Oct-15	<i>N.S.M.O.M.O.</i>
Charles R. Beaudoin P.S.	HBL 100	4	01-Sep-15	C. Jagarnauth	13-Oct-15	<i>N.S.M.O.M.O.</i>
	HBL 101		01-Sep-15	C. Jagarnauth	13-Oct-15	<i>N.S.M.O.M.O.</i>
	HBL 102		01-Sep-15	C. Jagarnauth	13-Oct-15	<i>N.S.M.O.M.O.</i>
	HBL 206		01-Sep-15	C. Jagarnauth	13-Oct-15	<i>N.S.M.O.M.O.</i>
J.W. Singleton Education Centre	HB 003	4	21-Aug-15	D.Kellyman	16-Sept-15	<i>N.S.M.O.M.O.</i>
	HB 117		21-Aug-15	D.Kellyman	16-Sept-15	<i>Exterior caulking missing at air-conditioning unit wiring.</i>
	HB 118		21-Aug-15	D.Kellyman	16-Sept-15	<i>N.S.M.O.M.O.</i>
	HB 119		21-Aug-15	D.Kellyman	16-Sept-15	<i>N.S.M.O.M.O.</i>
John T. Tuck P.S.	HB 064	7	11-Aug-15	J. Jones	7-Oct-15	<i>Exterior caulking missing at door.</i>
	HB 156		11-Aug-15	J. Jones	7-Oct-15	<i>N.S.M.O.M.O.</i>
	HB 157		11-Aug-15	J. Jones	7-Oct-15	<i>N.S.M.O.M.O.</i>
	HB 173		11-Aug-15	J. Jones	7-Oct-15	<i>N.S.M.O.M.O.</i>
	HBL 219		11-Aug-15	J. Jones	7-Oct-15	<i>N.S.M.O.M.O.</i>
	HBL 220		11-Aug-15	J. Jones	7-Oct-15	<i>N.S.M.O.M.O.</i>
	HBL 221		11-Aug-15	J. Jones	7-Oct-15	<i>N.S.M.O.M.O.</i>
John W. Boich P.S.	HBL 247	3	12-Aug-15	J. Jones	19-Oct-15	<i>N.S.M.O.M.O.</i>
	HB 108		12-Aug-15	J. Jones	19-Oct-15	<i>N.S.M.O.M.O.</i>
	HB 109		12-Aug-15	J. Jones	19-Oct-15	<i>N.S.M.O.M.O.</i>
L.B. Pearson H.S.	RM 179 A/B	12	21-Aug-15	D.Kellyman	16-Sept-15	<i>N.S.M.O.M.O.</i>
	RM 180		21-Aug-15	J. Jones	16-Sept-15	<i>Minor amounts of suspect mould observed on gypsum board wall and on vinyl floor tile (new).</i>
	RM 181		21-Aug-15	D.Kellyman	16-Sept-15	<i>N.S.M.O.M.O.</i>
	RM 182		21-Aug-15	J.Jones	16-Sept-15	<i>Moisture and suspect mould observed on a gypsum board wall (new).</i>
	RM 183		21-Aug-15	J.Jones	16-Sept-15	<i>Minor amounts of suspect mould observed on vinyl floor tile (new).</i>
	RM 184		21-Aug-15	D.Kellyman	16-Sept-15	<i>Black staining observed on wood sheathing in ceiling space at C-2 (new).</i>
	RM 185		21-Aug-15	D.Kellyman	16-Sept-15	<i>N.S.M.O.M.O.</i>
	RM 186		21-Aug-15	J.Jones	16-Sept-15	<i>N.S.M.O.M.O.</i>
	RM 187		21-Aug-15	D.Kellyman	16-Sept-15	<i>N.S.M.O.M.O.</i>
	RM 188		21-Aug-15	D.Kellyman	16-Sept-15	<i>N.S.M.O.M.O.</i>
	RM 189		21-Aug-15	D.Kellyman	16-Sept-15	<i>N.S.M.O.M.O.</i>
	RM 190 A/B		21-Aug-15	D.Kellyman	16-Sept-15	<i>N.S.M.O.M.O.</i>

**TABLE 1
PORTABLE CLASSROOM PREVENTATIVE MAINTENANCE INSPECTION NO. 94 SUMMARY**

School	Portable Number	Portables on Site	PM Inspection Schedule		Proposed Round 95 Inspection Date	Comments from Round 94 Inspection
			Round 94 Inspection Date	ARCADIS Inspector		
M.M. Robinson H.S.	HB 010	3	21-Aug-15	D.Kellyman	16-Sept-15	<i>N.S.M.O.M.O.</i>
	HB 151		21-Aug-15	D.Kellyman	16-Sept-15	<i>N.S.M.O.M.O.</i>
	HB 161		21-Aug-15	D.Kellyman	16-Sept-15	<i>N.S.M.O.M.O.</i>
Pineland P.S.	HB 006	6	13-Aug-15	J. Jones	8-Oct-15	<i>N.S.M.O.M.O.</i>
	HB 067		13-Aug-15	J. Jones	8-Oct-15	<i>N.S.M.O.M.O.</i>
	HB 069		13-Aug-15	J. Jones	8-Oct-15	<i>N.S.M.O.M.O.</i>
	HB 094		13-Aug-15	J. Jones	8-Oct-15	<i>N.S.M.O.M.O.</i>
	HB 096		13-Aug-15	J. Jones	8-Oct-15	<i>N.S.M.O.M.O.</i>
	HB 128		13-Aug-15	J. Jones	8-Oct-15	<i>N.S.M.O.M.O.</i>
Sir E. MacMillan P.S.	HB 017	6	13-Aug-15	J. Jones	8-Oct-15	<i>Exterior caulking degraded at both windows.</i>
	HB 018		13-Aug-15	J. Jones	8-Oct-15	<i>N.S.M.O.M.O.</i>
	HB 019		13-Aug-15	J. Jones	8-Oct-15	<i>N.S.M.O.M.O.</i>
	HB 020		13-Aug-15	J. Jones	8-Oct-15	<i>N.S.M.O.M.O.</i>
	HB 025		13-Aug-15	J. Jones	8-Oct-15	<i>N.S.M.O.M.O.</i>
	HB 165		13-Aug-15	J. Jones	8-Oct-15	<i>N.S.M.O.M.O.</i>
Total Portables:		50				

NOTE:

Scheduled inspection date subject to change due to availability of manpower and the facility.

N.S.M.O.M.O.= No Suspect Mold or Moisture Observed

**TABLE 1
PORTABLE CLASSROOM PREVENTATIVE MAINTENANCE INSPECTION NO. 94 SUMMARY**

School	Portable Number	Portables on Site	PM Inspection Schedule		Proposed Round 95 Inspection Date	Comments from Round 94 Inspection
			Round 94 Inspection Date	ARCADIS Inspector		
Captain R. Wilson P.S.	HB 014	1	12-Aug-15	J. Jones	15-Oct-15	N.S.M.O.M.O.
Emily Carr P.S.	HB 084	6	23-Jul-15	D.Kellyman	21-Sept-15	N.S.M.O.M.O.
	HB 106		23-Jul-15	D.Kellyman	21-Sept-15	Portable not present on site at the time of inspection. Portable to be inspected at new location during next round of inspections.
	HBL 001		23-Jul-15	D.Kellyman	21-Sept-15	N.S.M.O.M.O.
	HBL 002		23-Jul-15	D.Kellyman	21-Sept-15	N.S.M.O.M.O.
	HBL 008		23-Jul-15	D.Kellyman	21-Sept-15	N.S.M.O.M.O.
	HBL 085		23-Jul-15	D.Kellyman	21-Sept-15	Portable not present on site at the time of inspection. Portable to be inspected at new location during next round of inspections.
Forest Trail P.S.	HB 044	9	22-Jul-15	S. Parliament	10-Sept-15	N.S.M.O.M.O.
	HB 047		22-Jul-15	S. Parliament	10-Sept-15	N.S.M.O.M.O.
	HB 049		22-Jul-15	S. Parliament	10-Sept-15	N.S.M.O.M.O.
	HB 050		22-Jul-15	S. Parliament	10-Sept-15	N.S.M.O.M.O.
	HB 052		22-Jul-15	S. Parliament	10-Sept-15	N.S.M.O.M.O.
	HB 054		22-Jul-15	S. Parliament	10-Sept-15	N.S.M.O.M.O.
	HB 058		22-Jul-15	S. Parliament	10-Sept-15	N.S.M.O.M.O.
	HB 076		22-Jul-15	S. Parliament	10-Sept-15	N.S.M.O.M.O.
	HB 101		22-Jul-15	S. Parliament	10-Sept-15	N.S.M.O.M.O.
Gladys Speers P.S.	HB 104	1	14-May-15	S. Parliament	14-Oct-15	N.S.M.O.M.O.
Palmero P.S.	HB 086	5	23-Jul-15	D.Kellyman	21-Sep-15	N.S.M.O.M.O.
	HB 087		23-Jul-15	D.Kellyman	21-Sep-15	N.S.M.O.M.O.
	HB 167		23-Jul-15	D.Kellyman	21-Sep-15	N.S.M.O.M.O.
	HB 168		23-Jul-15	D.Kellyman	21-Sep-15	N.S.M.O.M.O.
	HB 170		23-Jul-15	D.Kellyman	21-Sep-15	N.S.M.O.M.O.
Pine Grove P.S.	HB 043	10	18-Jul-15	S. Parliament	9-Sept-15	Small tear observed in metal cladding at left elevation.
	HB 097		18-Jul-15	S. Parliament	9-Sept-15	Hole (1") observed in metal cladding at rear elevation.
	HB 123		18-Jul-15	S. Parliament	9-Sept-15	N.S.M.O.M.O.
	HB 130		18-Jul-15	S. Parliament	9-Sept-15	Eavestrough at front and rear elevations detached and/or damaged.
	HB 131		18-Jul-15	S. Parliament	9-Sept-15	N.S.M.O.M.O.
	HB 158		18-Jul-15	S. Parliament	9-Sept-15	Eavestrough (2') damaged at front elevation. Exterior caulking degraded and/or missing at conduit.
	HB 159		18-Jul-15	S. Parliament	9-Sept-15	N.S.M.O.M.O.
	HB 171		18-Jul-15	S. Parliament	9-Sept-15	N.S.M.O.M.O.
	HB 175		18-Jul-15	S. Parliament	9-Sept-15	N.S.M.O.M.O.
	HBL 006		18-Jul-15	S. Parliament	9-Sept-15	N.S.M.O.M.O.
Sunningdale P.S.	HB 059	10	27-Aug-15	C. Jagarnauth	14-Oct-15	Portable not present on site at the time of inspection. Portable to be inspected at new location during next round of inspections.
	HB 072		27-Aug-15	C. Jagarnauth	14-Oct-15	N.S.M.O.M.O.
	HB 092		27-Aug-15	C. Jagarnauth	14-Oct-15	Portable not present on site at the time of inspection. Portable to be inspected at new location during next round of inspections.
	HB 120		27-Aug-15	C. Jagarnauth	14-Oct-15	Portable not present on site at the time of inspection. Portable to be inspected at new location during next round of inspections.
	HB 132		27-Aug-15	C. Jagarnauth	14-Oct-15	N.S.M.O.M.O.
	HB 137		27-Aug-15	C. Jagarnauth	14-Oct-15	Portable not present on site at the time of inspection. Portable to be inspected at new location during next round of inspections.
	HB 145		27-Aug-15	C. Jagarnauth	14-Oct-15	N.S.M.O.M.O.

**TABLE 1
PORTABLE CLASSROOM PREVENTATIVE MAINTENANCE INSPECTION NO. 94 SUMMARY**

School	Portable Number	Portables on Site	PM Inspection Schedule		Proposed Round 95 Inspection Date	Comments from Round 94 Inspection
			Round 94 Inspection Date	ARCADIS Inspector		
	HB 172		14-May-15	C. Jagarnauth	14-Oct-15	<i>Portable not present on site at the time of inspection. Portable to be inspected at new location during next round of inspections.</i>
	HB 179		27-Aug-15	C. Jagarnauth	14-Oct-15	<i>N.S.M.O.M.O.</i>
	HB 207		27-Aug-15	C. Jagarnauth	14-Oct-15	<i>Portable not present on site at the time of inspection. Portable to be inspected at new location during next round of inspections.</i>
W.H. Morden P.S.	HB 055	5	18/Jul/2015	S. Parliament	9-Sept-15	<i>N.S.M.O.M.O.</i>
	HB 138		18/Jul/2015	S. Parliament	9-Sept-15	<i>N.S.M.O.M.O.</i>
	HBL 007		18/Jul/2015	S. Parliament	9-Sept-15	<i>N.S.M.O.M.O.</i>
	HBL 249 (1147)		18/Jul/2015	S. Parliament	9-Sept-15	<i>N.S.M.O.M.O.</i>
	HBL 250 (931)		18/Jul/2015	S. Parliament	9-Sept-15	<i>N.S.M.O.M.O.</i>
West Oak P.S.	RM 1	8	22-Jul-15	S. Parliament	10-Sept-15	<i>N.S.M.O.M.O.</i>
	RM 2		22-Jul-15	S. Parliament	10-Sept-15	<i>N.S.M.O.M.O.</i>
	RM 3		22-Jul-15	S. Parliament	10-Sept-15	<i>N.S.M.O.M.O.</i>
	RM 4		22-Jul-15	S. Parliament	10-Sept-15	<i>N.S.M.O.M.O.</i>
	RM 5		22-Jul-15	S. Parliament	10-Sept-15	<i>N.S.M.O.M.O.</i>
	RM 6		22-Jul-15	S. Parliament	10-Sept-15	<i>Exterior caulking degraded at window both windows.</i>
	Work Room		22-Jul-15	S. Parliament	10-Sept-15	<i>N.S.M.O.M.O.</i>
	HB 107		22-Jul-15	S. Parliament	10-Sept-15	<i>N.S.M.O.M.O.</i>
White Oaks Centre for Science and Technology (North Campus)	HB 060	5	20/Jul/2015	S. Parliament	22-Oct-15	<i>N.S.M.O.M.O.</i>
	HBL 092		20/Jul/2015	S. Parliament	22-Oct-15	<i>N.S.M.O.M.O.</i>
	HBL 093		20/Jul/2015	S. Parliament	22-Oct-15	<i>N.S.M.O.M.O.</i>
	HBL 094		20/Jul/2015	S. Parliament	22-Oct-15	<i>N.S.M.O.M.O.</i>
	HBL 095		20/Jul/2015	S. Parliament	22-Oct-15	<i>Wooden skirting damaged at rear and left elevations.</i>
White Oaks School Admin. (South Campus)	HB 023	12	20/Jul/2015	S. Parliament	22-Oct-15	<i>N.S.M.O.M.O.</i>
	HB 042		20/Jul/2015	S. Parliament	22-Oct-15	<i>Screw holes observed in corner flashing at left elevation.</i>
	HB 078		20/Jul/2015	S. Parliament	22-Oct-15	<i>N.S.M.O.M.O.</i>
	HB 112		20/Jul/2015	S. Parliament	22-Oct-15	<i>N.S.M.O.M.O.</i>
	HB 153		20/Jul/2015	S. Parliament	22-Oct-15	<i>N.S.M.O.M.O.</i>
	HB 201		20/Jul/2015	S. Parliament	22-Oct-15	<i>N.S.M.O.M.O.</i>
	HB 205		20/Jul/2015	S. Parliament	22-Oct-15	<i>N.S.M.O.M.O.</i>
	HBL 016		20/Jul/2015	S. Parliament	22-Oct-15	<i>N.S.M.O.M.O.</i>
	HBL 017		20/Jul/2015	S. Parliament	22-Oct-15	<i>N.S.M.O.M.O.</i>
	HBL 018		20/Jul/2015	S. Parliament	22-Oct-15	<i>N.S.M.O.M.O.</i>
	HBL 096		20/Jul/2015	S. Parliament	22-Oct-15	<i>N.S.M.O.M.O.</i>
	HBL 097		20/Jul/2015	S. Parliament	22-Oct-15	<i>N.S.M.O.M.O.</i>
Total Portables:		72				

NOTE:
Scheduled inspection date subject to change due to availability of manpower and the facility.
N.S.M.O.M.O.= No Suspect Mould or Moisture Observed

**TABLE 1
PORTABLE CLASSROOM PREVENTATIVE MAINTENANCE INSPECTION NO. 94 SUMMARY**

School	Portable Number	Portables on Site	PM Inspection Schedule		Proposed Round 95 Inspection Date	Comments from Round 94 Inspection
			Round 94 Inspection Date	ARCADIS Inspector		
Alton Village P.S.	HBL 234	9	01-Sep-15	C. Jagarnauth	13-Oct-15	<i>N.S.M.O.M.O.</i>
	HBL 235		1-Sept-15	C. Jagarnauth	13-Oct-15	<i>N.S.M.O.M.O.</i>
	HBL 236		1-Sept-15	C. Jagarnauth	13-Oct-15	<i>N.S.M.O.M.O.</i>
	HBL 237		1-Sept-15	C. Jagarnauth	13-Oct-15	<i>N.S.M.O.M.O.</i>
	HBL 238		1-Sept-15	C. Jagarnauth	13-Oct-15	<i>Downspout detached at front walls.</i>
	HBL 239		1-Sept-15	C. Jagarnauth	13-Oct-15	<i>N.S.M.O.M.O.</i>
	HBL 225		1-Sept-15	C. Jagarnauth	13-Oct-15	<i>Screw holes observed at front and rear elevations</i>
	HB 068		1-Sept-15	C. Jagarnauth	13-Oct-15	<i>N.S.M.O.M.O.</i>
	HB 037		1-Sept-15	C. Jagarnauth	13-Oct-15	<i>N.S.M.O.M.O.</i>
Dr. Charles Best P.S.	HB 210	2	13-Aug-15	J. Jones	8-Oct-15	<i>N.S.M.O.M.O.</i>
	HBL 211		13-Aug-15	J. Jones	8-Oct-15	<i>N.S.M.O.M.O.</i>
Florence Meares P.S.	HB 139	1	01-Sep-15	C. Jagarnauth	13-Oct-15	<i>N.S.M.O.M.O.</i>
Kilbride P.S.	HB 074	1	01-Sep-15	C. Jagarnauth	13-Oct-15	<i>Hole (1") observed at the right wall.</i>
Orchard Park P.S.	HB 040	4	12-Aug-15	J. Jones	19-Oct-15	<i>N.S.M.O.M.O.</i>
	HB 147		12-Aug-15	J. Jones	19-Oct-15	<i>N.S.M.O.M.O.</i>
	HB 166		12-Aug-15	J. Jones	19-Oct-15	<i>N.S.M.O.M.O.</i>
	HB 140		12-Aug-15	J. Jones	19-Oct-15	<i>N.S.M.O.M.O.</i>
Pauline Johnson P.S.	HBL 32	2	13-Aug-15	J. Jones	8-Oct-15	<i>N.S.M.O.M.O.</i>
	HB 102		13-Aug-15	J. Jones	8-Oct-15	<i>N.S.M.O.M.O.</i>
Tom Thompson P.S.	HB 012	10	11-Aug-15	J. Jones	7-Oct-15	<i>N.S.M.O.M.O.</i>
	HB 031		11-Aug-15	J. Jones	7-Oct-15	<i>N.S.M.O.M.O.</i>
	HB 053		11-Aug-15	J. Jones	7-Oct-15	<i>N.S.M.O.M.O.</i>
	HB 098		11-Aug-15	J. Jones	7-Oct-15	<i>Screw holes observed in metal cladding near front banister. Metal cladding heavily rusted and damaged below door at front elevation.</i>
	HB 105		11-Aug-15	J. Jones	7-Oct-15	<i>N.S.M.O.M.O.</i>
	HB 124		11-Aug-15	J. Jones	7-Oct-15	<i>N.S.M.O.M.O.</i>
	HB 141		11-Aug-15	J. Jones	7-Oct-15	<i>N.S.M.O.M.O.</i>
	HB 148		11-Aug-15	J. Jones	7-Oct-15	<i>N.S.M.O.M.O.</i>
	HB 169		11-Aug-15	J. Jones	7-Oct-15	<i>N.S.M.O.M.O.</i>
	HB 206		11-Aug-15	J. Jones	7-Oct-15	<i>Edge flashing missing at front elevation.</i>
Total Portables:		29				

NOTE:

Scheduled inspection date subject to change due to availability of manpower and the facility.

N.S.M.O.M.O. = No Suspect Mold or Moisture Observed