

PORTABLE CLASSROOM PREVENTATIVE MAINTENANCE INSPECTION NO. 95 SUMMARY

School	Portable Number	No. of Portables	PM Inspection Schedule		Comments from Round 95 Inspection
			Round 95 Inspection date	ARCADIS Inspector	
Anne J. MacArthur P.S.	HB 026	11	25-Sept-15	J. Jones	<i>Screw holes at right elevation. Two holes at the front elevation.</i>
	HB 071		25-Sept-15	J. Jones	<i>Screw holes at front and left elevations.</i>
	HB 127		25-Sept-15	J. Jones	<i>Screw holes at right elevation.</i>
	HBL 202		25-Sept-15	J. Jones	<i>Screw holes observed at right elevation.</i>
	HBL 203		25-Sept-15	J. Jones	<i>N.S.M.O.M.O.</i>
	HBL 204		25-Sept-15	J. Jones	<i>N.S.M.O.M.O.</i>
	HBL 205		25-Sept-15	J. Jones	<i>N.S.M.O.M.O.</i>
	HBL 214		25-Sept-15	J. Jones	<i>N.S.M.O.M.O.</i>
	HBL 215		25-Sept-15	J. Jones	<i>N.S.M.O.M.O.</i>
	HBL 232		25-Sept-15	J. Jones	<i>N.S.M.O.M.O.</i>
	HBL 233		25-Sept-15	J. Jones	<i>N.S.M.O.M.O.</i>
Brookville P.S.	HBL 201	1	22-Oct-15	S.Parliament	<i>Exterior caulking degraded at both windows.</i>
Bruce Trail P.S.	HB 046	13	26-Sep-15	S.Parliament	<i>N.S.M.O.M.O.</i>
	HB 062		26-Sep-15	S.Parliament	<i>Gable louvre damaged at right elevation. Screw holes observed in metal cladding at right elevation.</i>
	HB 075		26-Sep-15	S.Parliament	<i>N.S.M.O.M.O.</i>
	HB 103		26-Sep-15	S.Parliament	<i>N.S.M.O.M.O.</i>
	HB 110		26-Sep-15	S.Parliament	<i>Vinyl floor tiles (~10) damaged throughout.</i>
	HB 114		26-Sep-15	S.Parliament	<i>Screw holes observed in metal cladding at front elevation.</i>
	HB 115		26-Sep-15	S.Parliament	<i>N.S.M.O.M.O.</i>
	HB 149		26-Sep-15	S.Parliament	<i>Caulking degraded at air-conditioner wiring. Downspout detached at rear elevation.</i>
	HBL 105		26-Sep-15	S.Parliament	<i>Stained ceiling tiles (~2) observed.</i>
	HBL 228		26-Sep-15	S.Parliament	<i>N.S.M.O.M.O.</i>
	HBL 229		26-Sep-15	S.Parliament	<i>N.S.M.O.M.O.</i>
	HBL 230		26-Sep-15	S.Parliament	<i>N.S.M.O.M.O.</i>
	HBL 231		26-Sep-15	S.Parliament	<i>N.S.M.O.M.O.</i>
Chris Hadfield P.S.	RM A1	12	22-Oct-15	S.Parliament	<i>N.S.M.O.M.O.</i>
	RM A2		22-Oct-15	S.Parliament	<i>N.S.M.O.M.O.</i>
	RM A3		22-Oct-15	S.Parliament	<i>N.S.M.O.M.O.</i>
	RM A4		22-Oct-15	S.Parliament	<i>N.S.M.O.M.O.</i>
	RM A5		22-Oct-15	S.Parliament	<i>N.S.M.O.M.O.</i>
	RM A6		22-Oct-15	S.Parliament	<i>N.S.M.O.M.O.</i>
	RM A7		22-Oct-15	S.Parliament	<i>N.S.M.O.M.O.</i>
	RM A8		22-Oct-15	S.Parliament	<i>N.S.M.O.M.O.</i>
	RM A9		22-Oct-15	S.Parliament	<i>N.S.M.O.M.O.</i>
	RM A10		22-Oct-15	S.Parliament	<i>N.S.M.O.M.O.</i>

PORTABLE CLASSROOM PREVENTATIVE MAINTENANCE INSPECTION NO. 95 SUMMARY

School	Portable Number	No. of Portables	PM Inspection Schedule		Comments from Round 95 Inspection
			Round 95 Inspection date	ARCADIS Inspector	
	RM A11		22-Oct-15	S.Parliament	<i>N.S.M.O.M.O.</i>
	HBL 106		22-Oct-15	S.Parliament	<i>N.S.M.O.M.O.</i>
Craig Kielburger S.S.	HB 038	21	20-Oct-15	S.Parliament	<i>N.S.M.O.M.O.</i>
	HB 045		20-Oct-15	S.Parliament	<i>N.S.M.O.M.O.</i>
	HB 056		20-Oct-15	S.Parliament	<i>N.S.M.O.M.O.</i>
	HB 057		20-Oct-15	S.Parliament	<i>N.S.M.O.M.O.</i>
	HB 073		20-Oct-15	S.Parliament	<i>N.S.M.O.M.O.</i>
	HB 090		20-Oct-15	S.Parliament	<i>Exterior caulking degraded at conduit.</i>
	HB 091		20-Oct-15	S.Parliament	<i>N.S.M.O.M.O.</i>
	HB 100		20-Oct-15	S.Parliament	<i>Exterior caulking degraded at conduit.</i>
	HB 133		19-Oct-15	S.Parliament	<i>N.S.M.O.M.O.</i>
	HB 134		19-Oct-15	S.Parliament	<i>Screw holes observed in metal cladding at front and rear elevations. Exterior caulking degraded at conduits.</i>
	HB 135		20-Oct-15	S.Parliament	<i>Vinyl floor tiles (~6) damaged. Section of metal cladding (6"x2') missing at left elevation.</i>
	HB 143		19-Oct-15	S.Parliament	<i>N.S.M.O.M.O.</i>
	HB 203		20-Oct-15	S.Parliament	<i>N.S.M.O.M.O.</i>
	HBL 005		20-Oct-15	S.Parliament	<i>N.S.M.O.M.O.</i>
	HBL 080		20-Oct-15	S.Parliament	<i>N.S.M.O.M.O.</i>
	HBL 084		20-Oct-15	S.Parliament	<i>N.S.M.O.M.O.</i>
	HB 113		19-Oct-15	S.Parliament	<i>N.S.M.O.M.O.</i>
	HB 125		19-Oct-15	S.Parliament	<i>N.S.M.O.M.O.</i>
	HB 180		19-Oct-15	S.Parliament	<i>N.S.M.O.M.O.</i>
	HB 189		19-Oct-15	S.Parliament	<i>N.S.M.O.M.O.</i>
	HBL 086		19-Oct-15	S.Parliament	<i>N.S.M.O.M.O.</i>
Escarpment View P.S.	HBL 103	12	30-Sep-15	R. Farnsworth	<i>N.S.M.O.M.O.</i>
	HB 005		30-Sep-15	R. Farnsworth	<i>N.S.M.O.M.O.</i>
	HB 089		30-Sep-15	R. Farnsworth	<i>N.S.M.O.M.O.</i>
	HB 144		30-Sep-15	R. Farnsworth	<i>N.S.M.O.M.O.</i>
	HBL 081		30-Sep-15	R. Farnsworth	<i>N.S.M.O.M.O.</i>
	HBL 082		30-Sep-15	R. Farnsworth	<i>N.S.M.O.M.O.</i>
	HBL 083		30-Sep-15	R. Farnsworth	<i>N.S.M.O.M.O.</i>
	HBL 088		30-Sep-15	R. Farnsworth	<i>N.S.M.O.M.O.</i>
	HBL 090		30-Sep-15	R. Farnsworth	<i>N.S.M.O.M.O.</i>
	HBL 091		30-Sep-15	R. Farnsworth	<i>N.S.M.O.M.O.</i>
	HBL 104		30-Sep-15	R. Farnsworth	<i>N.S.M.O.M.O.</i>
	HBL 089		30-Sep-15	R. Farnsworth	<i>N.S.M.O.M.O.</i>

PORTABLE CLASSROOM PREVENTATIVE MAINTENANCE INSPECTION NO. 95 SUMMARY

School	Portable Number	No. of Portables	PM Inspection Schedule		Comments from Round 95 Inspection
			Round 95 Inspection date	ARCADIS Inspector	
Gardiner P.S.	HBL 207	1	21-Sep-15	D.Kellyman	<i>N.S.M.O.M.O.</i>
Glen Williams P.S.	HB 178	2	21-Sep-15	D.Kellyman	<i>N.S.M.O.M.O.</i>
	HB 184		21-Sep-15	D.Kellyman	<i>Eavestrough (5') damaged at front elevation.</i>
Hawthorne Village P.S.	HB 013	22	29-Sep-15	S.Parliament	<i>N.S.M.O.M.O.</i>
	HB 034		29-Sep-15	S.Parliament	<i>N.S.M.O.M.O.</i>
	HB 035		29-Sep-15	S.Parliament	<i>N.S.M.O.M.O.</i>
	HB 036		29-Sep-15	S.Parliament	<i>N.S.M.O.M.O.</i>
	HB 136		29-Sep-15	S.Parliament	<i>Corner flashing damaged at front elevation.</i>
	HB 155		29-Sep-15	S.Parliament	<i>N.S.M.O.M.O.</i>
	HB 162		29-Sep-15	S.Parliament	<i>Metal cladding detached at left elevation.</i>
	RM 101		01-Oct-15	S.Parliament	<i>N.S.M.O.M.O.</i>
	RM 102		01-Oct-15	S.Parliament	<i>N.S.M.O.M.O.</i>
	RM 103		01-Oct-15	S.Parliament	<i>N.S.M.O.M.O.</i>
	RM 104		01-Oct-15	S.Parliament	<i>N.S.M.O.M.O.</i>
	RM 105		01-Oct-15	S.Parliament	<i>N.S.M.O.M.O.</i>
	RM 301		01-Oct-15	S.Parliament	<i>N.S.M.O.M.O.</i>
	RM 302		01-Oct-15	S.Parliament	<i>N.S.M.O.M.O.</i>
	RM 303		01-Oct-15	S.Parliament	<i>N.S.M.O.M.O.</i>
	RM 304		01-Oct-15	S.Parliament	<i>N.S.M.O.M.O.</i>
	RM 305		01-Oct-15	S.Parliament	<i>N.S.M.O.M.O.</i>
	RM 306		01-Oct-15	S.Parliament	<i>N.S.M.O.M.O.</i>
	RM 307		01-Oct-15	S.Parliament	<i>N.S.M.O.M.O.</i>
	RM 308		01-Oct-15	S.Parliament	<i>N.S.M.O.M.O.</i>
RM 309		01-Oct-15	S.Parliament	<i>N.S.M.O.M.O.</i>	
RM 310		01-Oct-15	S.Parliament	<i>N.S.M.O.M.O.</i>	
Irma Coulson P.S.	HB 009	10	25-Sep-15	D.Kellyman	<i>N.S.M.O.M.O.</i>
	HB 081		25-Sep-15	D.Kellyman	<i>N.S.M.O.M.O.</i>
	HB 142		25-Sep-15	D.Kellyman	<i>N.S.M.O.M.O.</i>
	HB 146		25-Sep-15	D.Kellyman	<i>N.S.M.O.M.O.</i>
	HB 150		25-Sep-15	D.Kellyman	<i>N.S.M.O.M.O.</i>
	HBL 242		25-Sep-15	D.Kellyman	<i>Exterior caulking degraded at window. Screw holes observed in metal cladding at left elevation.</i>
	HBL 243		25-Sep-15	D.Kellyman	<i>N.S.M.O.M.O.</i>
	HBL 244		25-Sep-15	D.Kellyman	<i>N.S.M.O.M.O.</i>
	HBL 245		25-Sep-15	D.Kellyman	<i>N.S.M.O.M.O.</i>
	HBL 246		25-Sep-15	D.Kellyman	<i>N.S.M.O.M.O.</i>

PORTABLE CLASSROOM PREVENTATIVE MAINTENANCE INSPECTION NO. 95 SUMMARY

School	Portable Number	No. of Portables	PM Inspection Schedule		Comments from Round 95 Inspection
			Round 95 Inspection date	ARCADIS Inspector	
Martin Street P.S.	HB 152	2	29-Sep-15	R. Farnsworth	<i>N.S.M.O.M.O.</i>
	HB 015		29-Sep-15	R. Farnsworth	<i>Screw holes observed at front.</i>
Milton District H.S.	HB 001	3	29-Sep-15	R. Farnsworth	<i>N.S.M.O.M.O.</i>
	HB 093		29-Sep-15	R. Farnsworth	<i>N.S.M.O.M.O.</i>
	HB 154		29-Sep-15	R. Farnsworth	<i>N.S.M.O.M.O.</i>
P.L. Robertson P.S.	HB 004	7	02-Oct-15	D.Kellyman	<i>N.S.M.O.M.O.</i>
	HB 016		02-Oct-15	D.Kellyman	<i>N.S.M.O.M.O.</i>
	HB 021		02-Oct-15	D.Kellyman	<i>N.S.M.O.M.O.</i>
	HB 022		02-Oct-15	D.Kellyman	<i>N.S.M.O.M.O.</i>
	HB 027		02-Oct-15	D.Kellyman	<i>N.S.M.O.M.O.</i>
	HB 030		02-Oct-15	D.Kellyman	<i>Hole (~1") observed in metal cladding at right elevation.</i>
	HB 039		02-Oct-15	D.Kellyman	<i>ScExterior caulking degraded at air-exchanger vent.</i>
	Park P.S.		HB 048	1	21-Sep-15
Robert Baldwin P.S.	HB 122	4	20-Oct-15	S.Parliament	<i>N.S.M.O.M.O.</i>
	HB 174		20-Oct-15	S.Parliament	<i>N.S.M.O.M.O.</i>
	HBL 079		20-Oct-15	S.Parliament	<i>N.S.M.O.M.O.</i>
	HBL 248 (1072)		20-Oct-15	S.Parliament	<i>N.S.M.O.M.O.</i>
Robert Little P.S.	HB 208	2	21-Sep-15	D.Kellyman	<i>N.S.M.O.M.O.</i>
	HBL 10		21-Sep-15	D.Kellyman	<i>N.S.M.O.M.O.</i>
Sam Sherratt P.S.	HBL 087	9	25-Sep-15	J.Jones	<i>N.S.M.O.M.O.</i>
	HB 127		25-Sep-15	J. Jones	<i>Screw holes observed at rear and left elevations.</i>
	HB 082		25-Sep-15	J. Jones	<i>N.S.M.O.M.O.</i>
	HB 195		25-Sep-15	J. Jones	<i>N.S.M.O.M.O.</i>
	HB 083		25-Sep-15	J. Jones	<i>N.S.M.O.M.O.</i>
	HB 041		25-Sep-15	J. Jones	<i>N.S.M.O.M.O.</i>
	HBL 099		25-Sep-15	J. Jones	<i>N.S.M.O.M.O.</i>
	HBL 227		25-Sep-15	J. Jones	<i>N.S.M.O.M.O.</i>
	HB 066		25-Sep-15	J. Jones	<i>N.S.M.O.M.O.</i>
	Silver Creek P.S.		HB 029	2	21-Sep-15
HB 033		21-Sep-15	D.Kellyman		<i>N.S.M.O.M.O.</i>
Tiger Jeet Singh P.S.	HB 063	11	29-Sep-15	R. Farnsworth	<i>N.S.M.O.M.O.</i>
	HB 095		29-Sep-15	R. Farnsworth	<i>N.S.M.O.M.O.</i>
	HB 109		29-Sep-15	R. Farnsworth	<i>N.S.M.O.M.O.</i>
	HB 116		29-Sep-15	R. Farnsworth	<i>Exterior caulking missing at gable louvre at right elevation.</i>
	HB 126		29-Sep-15	R. Farnsworth	<i>N.S.M.O.M.O.</i>
	HB 187		29-Sep-15	R. Farnsworth	<i>N.S.M.O.M.O.</i>

PORTABLE CLASSROOM PREVENTATIVE MAINTENANCE INSPECTION NO. 95 SUMMARY

School	Portable Number	No. of Portables	PM Inspection Schedule		Comments from Round 95 Inspection
			Round 95 Inspection date	ARCADIS Inspector	
	HBL 013		29-Sep-15	R. Farnsworth	<i>N.S.M.O.M.O.</i>
	HBL 014		29-Sep-15	R. Farnsworth	<i>N.S.M.O.M.O.</i>
	HBL 015		29-Sep-15	R. Farnsworth	<i>N.S.M.O.M.O.</i>
	HBL 098		29-Sep-15	R. Farnsworth	<i>N.S.M.O.M.O.</i>
	HBL 213		29-Sep-15	R. Farnsworth	<i>N.S.M.O.M.O.</i>
W.I. Dick P.S.	HB 002	3	26-Sep-15	S.Parliament	<i>N.S.M.O.M.O.</i>
	HB 007		26-Sep-15	S.Parliament	<i>Downspout damaged at front elevation.</i>
	HB 183		26-Sep-15	S.Parliament	<i>N.S.M.O.M.O.</i>
Total Portables		149			
NOTE:					
Scheduled inspection date subject to change due to availability of manpower and the facility.					
N.S.M.O.M.O.=	No Suspect Mould or Moisture Observed				

PORTABLE CLASSROOM PREVENTATIVE MAINTENANCE INSPECTION NO. 95 SUMMARY

School	Portable Number	No. of Portables	PM Inspection Schedule		Comments from Round 95 Inspection
			Round 95 Inspection date	ARCADIS Inspector	
Abbey Park H.S.	HB 164	3	07-Oct-15	D.Kellyman	<i>N.S.M.O.M.O.</i>
	HB 108		07-Oct-15	D.Kellyman	<i>N.S.M.O.M.O.</i>
	HB 163		07-Oct-15	D.Kellyman	<i>N.S.M.O.M.O.</i>
E.J. James P.S.	HB 061	6	08-Oct-15	S.Parliament	<i>N.S.M.O.M.O.</i>
	HB 079		08-Oct-15	S.Parliament	<i>N.S.M.O.M.O.</i>
	HB 111		08-Oct-15	S.Parliament	<i>N.S.M.O.M.O.</i>
	HB 121		08-Oct-15	S.Parliament	<i>N.S.M.O.M.O.</i>
	HBL 009		08-Oct-15	S.Parliament	<i>N.S.M.O.M.O.</i>
	HBL085		08-Oct-15	S.Parliament	<i>Screw holes observed in metal cladding and centre flashing at right and rear elevation.</i>
Iroquois Ridge H.S.	HB 070	3	08-Oct-15	S.Parliament	<i>N.S.M.O.M.O.</i>
	HB 209		08-Oct-15	S.Parliament	<i>N.S.M.O.M.O.</i>
	HB 202		08-Oct-15	S.Parliament	<i>Hole ("2) and screw holes observed in metal cladding at right elevation. Exterior caulking missing at conduit. Exterior caulking missing at gable louvre at left elevation. Metal cladding insufficient/improperly sealed at right elevation.</i>
James W. Hill P.S.	HB 080	3	07-Oct-15	S.Parliament	<i>Hole (1") observed in metal cladding at rear elevation.</i>
	HB 099		07-Oct-15	S.Parliament	<i>Corner flashing detached and/or loose at rear right elevation.</i>
	HB 176		07-Oct-15	S.Parliament	<i>Wooden fascia (1') damaged at left elevation.</i>
Joshua Creek P.S.	HB 011	4	07-Oct-15	S.Parliament	<i>N.S.M.O.M.O.</i>
	HB 077		07-Oct-15	S.Parliament	<i>Exterior caulking degraded at conduit.</i>
	HB 085		07-Oct-15	S.Parliament	<i>N.S.M.O.M.O.</i>
	HB 199		07-Oct-15	S.Parliament	<i>N.S.M.O.M.O.</i>
Munn's P.S.	HB 166	2	06-Oct-15	S.Parliament	<i>Vinyl floor tiles (~6) damaged along center seam.</i>
	HB 177		06-Oct-15	S.Parliament	<i>N.S.M.O.M.O.</i>
Oakville Trafalgar H.S. (Portable)	RM 190	7	08-Oct-15	S.Parliament	<i>Baseboard (2') detached underneath second window.</i>
	RM 191		08-Oct-15	S.Parliament	<i>N.S.M.O.M.O.</i>
	RM 192		08-Oct-15	S.Parliament	<i>Exterior caulking degraded at second window.</i>
	RM 193		08-Oct-15	S.Parliament	<i>Exterior caulking degraded at top of second window.</i>
	RM 194		08-Oct-15	S.Parliament	<i>Interior caulking degraded and/or missing at second window,</i>
	RM 198		08-Oct-15	S.Parliament	<i>N.S.M.O.M.O.</i>
Pilgrim Wood P.S.	HBL 110	2	06-Oct-15	S. Parliament	<i>N.S.M.O.M.O.</i>
	HBL 224		06-Oct-15	S. Parliament	<i>N.S.M.O.M.O.</i>
Post's Corners P.S.	HB 065	1	07-Oct-15	S.Parliament	<i>N.S.M.O.M.O.</i>
Sheridan P.S.	HBL 226	1	07-Oct-15	S.Parliament	<i>N.S.M.O.M.O.</i>
River Oaks P.S.	HB 196	3	24-Sep-15	J. Jones	<i>N.S.M.O.M.O.</i>
	HB 202		24-Sep-15	J. Jones	<i>N.S.M.O.M.O.</i>
	HB 088		24-Sep-15	J. Jones	<i>Exterior caulking missing at conduit. Downspout missing at right elevation. Screw holes observed at right and rear elevations.</i>
Total Portables		35			
NOTE:					
Scheduled inspection date subject to change due to availability of manpower and the facility.					
N.S.M.O.M.O.= No Suspect Mould or Moisture Observed					

PORTABLE CLASSROOM PREVENTATIVE MAINTENANCE INSPECTION NO. 95 SUMMARY

School	Portable Number	No. of Portables	PM Inspection Schedule		Comments from Round 95 Inspection
			Round 95 Inspection date	ARCADIS Inspector	
Alexander's P.S.	HB 008	5	05-Oct-15	S.Parliament	<i>N.S.M.O.M.O.</i>
	HB 024		05-Oct-15	S.Parliament	<i>Exterior caulking degraded at air-exchanger vent.</i>
	HB 028		05-Oct-15	S.Parliament	<i>N.S.M.O.M.O.</i>
	HB 032		05-Oct-15	S.Parliament	<i>N.S.M.O.M.O.</i>
	HB 051		05-Oct-15	S.Parliament	<i>N.S.M.O.M.O.</i>
Charles R. Beaudoin P.S.	HBL 100	4	16-Oct-15	S.Parliament	<i>N.S.M.O.M.O.</i>
	HBL 101		16-Oct-15	S.Parliament	<i>N.S.M.O.M.O.</i>
	HBL 102		16-Oct-15	S.Parliament	<i>N.S.M.O.M.O.</i>
	HBL 247		16-Oct-15	S.Parliament	<i>N.S.M.O.M.O.</i>
Dr. Frank Hayden	HB 059	5	19-Oct-15	D.Kellyman	<i>Portable under construction at the time of inspection. Portable to be inspected at during next round of inspections.</i>
	HB120		19-Oct-15	D.Kellyman	<i>Portable under construction at the time of inspection. Portable to be inspected at during next round of inspections.</i>
	HB 137		19-Oct-15	D.Kellyman	<i>Portable under construction at the time of inspection. Portable to be inspected at during next round of inspections.</i>
	HB 172		19-Oct-15	D.Kellyman	<i>Portable under construction at the time of inspection. Portable to be inspected at during next round of inspections.</i>
	HB 207		19-Oct-15	D.Kellyman	<i>Portable under construction at the time of inspection. Portable to be inspected at during next round of inspections.</i>
J.W. Singleton Education Centre	HB 003	4	23-Sep-15	J. Jones	<i>N.S.M.O.M.O.</i>
	HB 117		23-Sep-15	J.Jones	<i>N.S.M.O.M.O.</i>
	HB 118		23-Sep-15	J.Jones	<i>N.S.M.O.M.O.</i>
	HB 119		23-Sep-15	J.Jones	<i>N.S.M.O.M.O.</i>
John T. Tuck P.S.	HB 064	7	16-Oct-15	S.Parliament	<i>N.S.M.O.M.O.</i>
	HB 156		16-Oct-15	S.Parliament	<i>N.S.M.O.M.O.</i>
	HB 157		16-Oct-15	S.Parliament	<i>N.S.M.O.M.O.</i>
	HB 173		16-Oct-15	S.Parliament	<i>N.S.M.O.M.O.</i>
	HBL 219		16-Oct-15	S.Parliament	<i>N.S.M.O.M.O.</i>
	HBL 220		16-Oct-15	S.Parliament	<i>N.S.M.O.M.O.</i>
	HBL 221		16-Oct-15	S.Parliament	<i>N.S.M.O.M.O.</i>
	HBL 216		16-Oct-15	S.Parliament	<i>N.S.M.O.M.O.</i>
John W. Boich P.S.	HB 108	4	05-Oct-15	S.Parliament	<i>N.S.M.O.M.O.</i>
	HBL 109		05-Oct-15	S.Parliament	<i>N.S.M.O.M.O.</i>
	HBL 247		05-Oct-15	S.Parliament	<i>N.S.M.O.M.O.</i>
	HBL 218		05-Oct-15	S.Parliament	<i>Screw holes observed in metal cladding and corner flashing at right elevation.</i>
L.B. Pearson H.S.	RM 179A	12	2-Oct-15	J. Jones	<i>N.S.M.O.M.O.</i>
	RM 180		2-Oct-15	J. Jones	<i>N.S.M.O.M.O.</i>
	RM 181		2-Oct-15	J. Jones	<i>N.S.M.O.M.O.</i>
	RM 182		2-Oct-15	J. Jones	<i>N.S.M.O.M.O.</i>
	RM 183		2-Oct-15	J. Jones	<i>N.S.M.O.M.O.</i>
	RM 184		2-Oct-15	J. Jones	<i>N.S.M.O.M.O.</i>

PORTABLE CLASSROOM PREVENTATIVE MAINTENANCE INSPECTION NO. 95 SUMMARY

School	Portable Number	No. of Portables	PM Inspection Schedule		Comments from Round 95 Inspection
			Round 95 Inspection date	ARCADIS Inspector	
	RM 185		2-Oct-15	J. Jones	<i>N.S.M.O.M.O.</i>
	RM 186		2-Oct-15	J. Jones	<i>N.S.M.O.M.O.</i>
	RM 187		2-Oct-15	J. Jones	<i>N.S.M.O.M.O.</i>
	RM 188		2-Oct-15	J. Jones	<i>N.S.M.O.M.O.</i>
	RM 189		2-Oct-15	J. Jones	<i>N.S.M.O.M.O.</i>
	RM 190A/B		2-Oct-15	J. Jones	<i>N.S.M.O.M.O.</i>
M.M. Robinson H.S.	HB 010	2	23-Sept-15	J. Jones	<i>N.S.M.O.M.O.</i>
	HB 151		23-Sept-15	J. Jones	<i>Screw holes observed at front elevation.</i>
Pineland P.S.	HB 069	6	01-Oct-15	J. Jones	<i>N.S.M.O.M.O.</i>
	HB 128		01-Oct-15	J. Jones	<i>N.S.M.O.M.O.</i>
	HB 096		01-Oct-15	J. Jones	<i>N.S.M.O.M.O.</i>
	HB 006		01-Oct-15	J. Jones	<i>Screw holes observed at front and right walls.</i>
	HB 067		01-Oct-15	J. Jones	<i>N.S.M.O.M.O.</i>
	HB 094		01-Oct-15	J. Jones	<i>N.S.M.O.M.O.</i>
Sir E. MacMillan P.S.	HB 017	6	02-Oct-15	J. Jones	<i>Exterior caulking degraded at both windows.</i>
	HB 018		02-Oct-15	J. Jones	<i>N.S.M.O.M.O.</i>
	HB 019		02-Oct-15	J. Jones	<i>N.S.M.O.M.O.</i>
	HB 020		02-Oct-15	J. Jones	<i>Hole (1") in exterior cladding at right wall.</i>
	HB 025		02-Oct-15	J. Jones	<i>N.S.M.O.M.O.</i>
	HB 165		02-Oct-15	J. Jones	<i>N.S.M.O.M.O.</i>
Total Portables		55			
NOTE:					
Scheduled inspection date subject to change due to availability of manpower and the facility.					
N.S.M.O.M.O.=	No Suspect Mould or Moisture Observed				

PORTABLE CLASSROOM PREVENTATIVE MAINTENANCE INSPECTION NO. 95 SUMMARY

School	Portable Number	No. of Portables	PM Inspection Schedule		Comments from Round 95 Inspection
			Round 95 Inspection date	ARCADIS Inspector	
Captain R. Wilson P.S.	HB 014	1	06-Oct-15	S. Parliament	<i>N.S.M.O.M.O.</i>
Emily Carr P.S.	HB 084	5	06-Oct-15	S. Parliament	<i>N.S.M.O.M.O.</i>
	HBL 085		06-Oct-15	S. Parliament	<i>N.S.M.O.M.O.</i>
	HBL 001		06-Oct-15	S. Parliament	<i>Screw holes observed in metal cladding at left elevation.</i>
	HBL 002		06-Oct-15	S. Parliament	<i>Screw holes observed in metal cladding and corner flashing at right elevation.</i>
	HBL 008		06-Oct-15	S. Parliament	<i>N.S.M.O.M.O.</i>
Forest Trail P.S.	HB 044	9	11-Oct-15	S. Parliament	<i>N.S.M.O.M.O.</i>
	HB 047		11-Oct-15	S. Parliament	<i>N.S.M.O.M.O.</i>
	HB 049		11-Oct-15	S. Parliament	<i>N.S.M.O.M.O.</i>
	HB 050		11-Oct-15	S. Parliament	<i>N.S.M.O.M.O.</i>
	HB 052		11-Oct-15	S. Parliament	<i>N.S.M.O.M.O.</i>
	HB 054		11-Oct-15	S. Parliament	<i>N.S.M.O.M.O.</i>
	HB 058		11-Oct-15	S. Parliament	<i>N.S.M.O.M.O.</i>
	HB 076		11-Oct-15	S. Parliament	<i>N.S.M.O.M.O.</i>
	HB 101		11-Oct-15	S. Parliament	<i>N.S.M.O.M.O.</i>
Gladys Speers P.S.	HB 104	1	07-Oct-15	D.Kellyman	<i>N.S.M.O.M.O.</i>
Palmero P.S.	HB 086	5	07-Oct-15	D.Kellyman	<i>N.S.M.O.M.O.</i>
	HB 087		07-Oct-15	D.Kellyman	<i>Exterior caulking degraded at front door and conduits.</i>
	HB 167		07-Oct-15	D.Kellyman	<i>N.S.M.O.M.O.</i>
	HB 168		07-Oct-15	D.Kellyman	<i>N.S.M.O.M.O.</i>
	HB 170		07-Oct-15	D.Kellyman	<i>N.S.M.O.M.O.</i>
Pine Grove P.S.	HB 043	10	12-Oct-15	S. Parliament	<i>N.S.M.O.M.O.</i>
	HB 097		12-Oct-15	S. Parliament	<i>N.S.M.O.M.O.</i>
	HB 123		12-Oct-15	S. Parliament	<i>N.S.M.O.M.O.</i>
	HB 130		12-Oct-15	S. Parliament	<i>Eavestrough at front and rear elevations detached and/or damaged.</i>
	HB 131		12-Oct-15	S. Parliament	<i>N.S.M.O.M.O.</i>
	HB 158		12-Oct-15	S. Parliament	<i>N.S.M.O.M.O.</i>
	HB 159		12-Oct-15	S. Parliament	<i>N.S.M.O.M.O.</i>
	HB 171		12-Oct-15	S. Parliament	<i>N.S.M.O.M.O.</i>
	HB 175		12-Oct-15	S. Parliament	<i>Section (3"x3") of metal cladding missing at right elevation.</i>
	HBL 006		12-Oct-15	S. Parliament	<i>N.S.M.O.M.O.</i>
Sunningdale P.S.	HB 072	4	07-Oct-15	D.Kellyman	<i>N.S.M.O.M.O.</i>
	HB 132		07-Oct-15	D.Kellyman	<i>Exterior caulking degraded at window.</i>
	HB 145		07-Oct-15	D.Kellyman	<i>N.S.M.O.M.O.</i>
	HB 179		07-Oct-15	D.Kellyman	<i>Exterior caulking degraded/ missing at left elevation. Screw holes observed in metal cladding at right elevation and left elevation. Hole (~1") observed in metal cladding at right elevation.</i>
W.H. Morden P.S.	HB 055	6	12/Oct/2015	S. Parliament	<i>N.S.M.O.M.O.</i>
	HB 138		12/Oct/2015	S. Parliament	<i>N.S.M.O.M.O.</i>

PORTABLE CLASSROOM PREVENTATIVE MAINTENANCE INSPECTION NO. 95 SUMMARY

School	Portable Number	No. of Portables	PM Inspection Schedule		Comments from Round 95 Inspection
			Round 95 Inspection date	ARCADIS Inspector	
	HBL 007		12/Oct/2015	S. Parliament	<i>N.S.M.O.M.O.</i>
	HBL 249 (1147)		12/Oct/2015	S. Parliament	<i>N.S.M.O.M.O.</i>
	HBL 250 (931)		12/Oct/2015	S. Parliament	<i>N.S.M.O.M.O.</i>
	HB 199		12/Oct/2015	S. Parliament	<i>Exterior caulking degraded at both windows. Downspout missing at rear elevation</i>
West Oak P.S.	RM 1	8	11/Oct/2015	S. Parliament	<i>N.S.M.O.M.O.</i>
	RM 2		11/Oct/2015	S. Parliament	<i>N.S.M.O.M.O.</i>
	RM 3		11/Oct/2015	S. Parliament	<i>N.S.M.O.M.O.</i>
	RM 4		11/Oct/2015	S. Parliament	<i>N.S.M.O.M.O.</i>
	RM 5		11/Oct/2015	S. Parliament	<i>N.S.M.O.M.O.</i>
	RM 6		11/Oct/2015	S. Parliament	<i>N.S.M.O.M.O.</i>
	Work Room		11/Oct/2015	S. Parliament	<i>N.S.M.O.M.O.</i>
	HB 107		11/Oct/2015	S. Parliament	<i>N.S.M.O.M.O.</i>
White Oaks Centre for Science and Technology (North Campus)	HB 060	5	6/Oct/2015	S. Parliament	<i>Hole in skirting at front elevation. Eavestrough damaged at rear elevation.</i>
	HBL 092		6/Oct/2015	S. Parliament	<i>N.S.M.O.M.O.</i>
	HBL 093		6/Oct/2015	S. Parliament	<i>N.S.M.O.M.O.</i>
	HBL 094		6/Oct/2015	S. Parliament	<i>N.S.M.O.M.O.</i>
	HBL 095		6/Oct/2015	S. Parliament	<i>N.S.M.O.M.O.</i>
White Oaks School Admin. (South Campus)	HB 023	11	24/Sep/2014	J. Jones	<i>N.S.M.O.M.O.</i>
	HB 042		24/Sep/2014	J. Jones	<i>N.S.M.O.M.O.</i>
	HBL 01		24/Sep/2014	J. Jones	<i>N.S.M.O.M.O.</i>
	HB 078		24/Sep/2014	J. Jones	<i>N.S.M.O.M.O.</i>
	HB 112		24/Sep/2014	J. Jones	<i>N.S.M.O.M.O.</i>
	HB 153		24/Sep/2014	J. Jones	<i>N.S.M.O.M.O.</i>
	HB 201		24/Sep/2014	J. Jones	<i>Missing ceiling tile observed near front door.</i>
	HB 205		24/Sep/2014	J. Jones	<i>N.S.M.O.M.O.</i>
	HBL 017		24/Sep/2014	J. Jones	<i>N.S.M.O.M.O.</i>
	HBL 096		24/Sep/2014	J. Jones	<i>N.S.M.O.M.O.</i>
	HBL 097		24/Sep/2014	J. Jones	<i>N.S.M.O.M.O.</i>
Total Portables		50			
NOTE:					
Scheduled inspection date subject to change due to availability of manpower and the facility.					
N.S.M.O.M.O.=	No Suspect Mould or Moisture Observed				

PORTABLE CLASSROOM PREVENTATIVE MAINTENANCE INSPECTION NO. 95 SUMMARY

School	Portable Number	No. of Portables	PM Inspection Schedule		Comments from Round 95 Inspection
			Round 95 Inspection date	ARCADIS Inspector	
Alton Village P.S.	HBL 234	9	05-Oct-15	D.Kellyman	<i>N.S.M.O.M.O.</i>
	HBL 235		05-Oct-15	D.Kellyman	<i>N.S.M.O.M.O.</i>
	HBL 236		05-Oct-15	D.Kellyman	<i>N.S.M.O.M.O.</i>
	HBL 237		05-Oct-15	D.Kellyman	<i>N.S.M.O.M.O.</i>
	HBL 238		05-Oct-15	D.Kellyman	<i>Downspout detached at front walls.</i>
	HBL 239		05-Oct-15	D.Kellyman	<i>N.S.M.O.M.O.</i>
	HBL 225		05-Oct-15	D.Kellyman	<i>Screw holes observed at front and rear elevations</i>
	HB 068		05-Oct-15	D.Kellyman	<i>N.S.M.O.M.O.</i>
	HB 037		05-Oct-15	D.Kellyman	<i>N.S.M.O.M.O.</i>
Dr. Charles Best P.S.	HB 210	2	23-Sep-15	J. Jones	<i>N.S.M.O.M.O.</i>
	HBL 211		23-Sep-15	J. Jones	<i>N.S.M.O.M.O.</i>
Florence Meares P.S.	HB 139	1	05-Oct-15	D.Kellyman	<i>N.S.M.O.M.O.</i>
Kilbride P.S.	HB 074	1	05-Oct-15	D.Kellyman	<i>Hole (1") observed at the right wall.</i>
Orchard Park P.S.	HB 040	4	05-Oct-15	S.Parliament	<i>N.S.M.O.M.O.</i>
	HB 147		05-Oct-15	S.Parliament	<i>N.S.M.O.M.O.</i>
	HB 166		05-Oct-15	S.Parliament	<i>N.S.M.O.M.O.</i>
	HB 140		05-Oct-15	S.Parliament	<i>N.S.M.O.M.O.</i>
Pauline Johnson P.S.	HBL 222	2	01-Oct-15	J. Jones	<i>N.S.M.O.M.O.</i>
	HB 102		01-Oct-15	J. Jones	<i>N.S.M.O.M.O.</i>
Tom Thompson P.S.	HB 102	10	24-Sep-15	J. Jones	<i>N.S.M.O.M.O.</i>
	HB 031		24-Sep-15	J. Jones	<i>N.S.M.O.M.O.</i>
	HB 053		24-Sep-15	J. Jones	<i>N.S.M.O.M.O.</i>
	HB 098		24-Sep-15	J. Jones	<i>Screw holes observed in metal cladding near front banister. Metal cladding heavily rusted and damaged below door at front elevation.</i>
	HB 105		24-Sep-15	J. Jones	<i>N.S.M.O.M.O.</i>
	HB 124		24-Sep-15	J. Jones	<i>N.S.M.O.M.O.</i>
	HB 141		24-Sep-15	J. Jones	<i>N.S.M.O.M.O.</i>
	HB 148		24-Sep-15	J. Jones	<i>N.S.M.O.M.O.</i>
	HB 169		24-Sep-15	J. Jones	<i>N.S.M.O.M.O.</i>
	HB 206		24-Sep-15	J. Jones	<i>Edge flashing missing at front elevation.</i>
Total Portables		29			
NOTE:					
Scheduled inspection date subject to change due to availability of manpower and the facility.					
N.S.M.O.M.O.=	No Suspect Mould or Moisture Observed				