

PORTABLE CLASSROOM PRENTATIVE MAINTENANCE INSPECTION NO. 96 SUMMARY

School	Portable Number	Portables on Site	PM Inspection Schedule		Proposed Round 97 Inspection Date	Comments from Round 96 Inspection
			Round 96 Inspection Date	DCS Inspector		
Anne J. MacArthur P.S.	HB 026	10	20-Nov-15	D.Kellyman	29-Jan-16	<i>N.S.M.O.M.O.</i>
	HB 071		20-Nov-15	D.Kellyman	29-Jan-16	<i>N.S.M.O.M.O.</i>
	HBL 202		20-Nov-15	D.Kellyman	29-Jan-16	<i>N.S.M.O.M.O.</i>
	HBL 203		20-Nov-15	D.Kellyman	29-Jan-16	<i>N.S.M.O.M.O.</i>
	HBL 204		20-Nov-15	D.Kellyman	29-Jan-16	<i>N.S.M.O.M.O.</i>
	HBL 205		20-Nov-15	D.Kellyman	29-Jan-16	<i>N.S.M.O.M.O.</i>
	HBL 214		20-Nov-15	D.Kellyman	29-Jan-16	<i>Exterior caulking degraded at windows.</i>
	HBL 215		20-Nov-15	D.Kellyman	29-Jan-16	<i>N.S.M.O.M.O.</i>
	HBL 232		20-Nov-15	D.Kellyman	29-Jan-16	<i>N.S.M.O.M.O.</i>
	HBL 233		20-Nov-15	D.Kellyman	29-Jan-16	<i>N.S.M.O.M.O.</i>
Brookville P.S.	HBL 201	1	07-Jan-16	S.Parliament	18-Feb-16	<i>N.S.M.O.M.O.</i>
Bruce Trail P.S.	HB 046	12	27-Nov-15	D.Kellyman	29-Jan-16	<i>N.S.M.O.M.O.</i>
	HB 062		27-Nov-15	D.Kellyman	29-Jan-16	<i>N.S.M.O.M.O.</i>
	HB 075		27-Nov-15	D.Kellyman	29-Jan-16	<i>N.S.M.O.M.O.</i>
	HB 103		27-Nov-15	D.Kellyman	29-Jan-16	<i>N.S.M.O.M.O.</i>
	HB 110		27-Nov-15	D.Kellyman	29-Jan-16	<i>Exterior caulking degraded at door. Stained ceiling tiles (~2) observed.</i>
	HB 114		27-Nov-15	D.Kellyman	29-Jan-16	<i>N.S.M.O.M.O.</i>
	HB 115		27-Nov-15	D.Kellyman	29-Jan-16	<i>N.S.M.O.M.O.</i>
	HB 149		27-Nov-15	D.Kellyman	29-Jan-16	<i>Fascia (1') damaged at right elevation.</i>
	HBL 105		27-Nov-15	D.Kellyman	29-Jan-16	<i>N.S.M.O.M.O.</i>
	HBL 228		27-Nov-15	D.Kellyman	29-Jan-16	<i>N.S.M.O.M.O.</i>
	HBL 229		27-Nov-15	D.Kellyman	29-Jan-16	<i>N.S.M.O.M.O.</i>
HBL 230		27-Nov-15	D.Kellyman	29-Jan-16	<i>N.S.M.O.M.O.</i>	
Chris Hadfield P.S.	RM A1	12	07-Jan-16	S.Parliament	18-Feb-16	<i>N.S.M.O.M.O.</i>
	RM A2		07-Jan-16	S.Parliament	18-Feb-16	<i>N.S.M.O.M.O.</i>
	RM A3		07-Jan-16	S.Parliament	18-Feb-16	<i>N.S.M.O.M.O.</i>
	RM A4		07-Jan-16	S.Parliament	18-Feb-16	<i>N.S.M.O.M.O.</i>
	RM A5		07-Jan-16	S.Parliament	18-Feb-16	<i>N.S.M.O.M.O.</i>
	RM A6		07-Jan-16	S.Parliament	18-Feb-16	<i>N.S.M.O.M.O.</i>
	RM A7		07-Jan-16	S.Parliament	18-Feb-16	<i>N.S.M.O.M.O.</i>
	RM A8		07-Jan-16	S.Parliament	18-Feb-16	<i>N.S.M.O.M.O.</i>
	RM A9		07-Jan-16	S.Parliament	18-Feb-16	<i>N.S.M.O.M.O.</i>
	RM A10		07-Jan-16	S.Parliament	18-Feb-16	<i>N.S.M.O.M.O.</i>
	RM A11		07-Jan-16	S.Parliament	18-Feb-16	<i>N.S.M.O.M.O.</i>
HBL 106		07-Jan-16	S.Parliament	18-Feb-16	<i>N.S.M.O.M.O.</i>	
Craig Kielburger S.S.	HB 038	18	09-Jan-16	S.Parliament	25-Feb-16	<i>Edge flashing damaged at front elevation leaving sharp edge.</i>
	HB 045		09-Jan-16	S.Parliament	25-Feb-16	<i>N.S.M.O.M.O.</i>
	HB 056		09-Jan-16	S.Parliament	25-Feb-16	<i>N.S.M.O.M.O.</i>
	HB 057		09-Jan-16	S.Parliament	25-Feb-16	<i>N.S.M.O.M.O.</i>
	HB 073		09-Jan-16	S.Parliament	25-Feb-16	<i>Stained ceiling tile (~1) observed, moist insulation in ceiling space above vapour-barrier.</i>
	HB 090		09-Jan-16	S.Parliament	25-Feb-16	<i>N.S.M.O.M.O.</i>

PORTABLE CLASSROOM PRENTATIVE MAINTENANCE INSPECTION NO. 96 SUMMARY

School	Portable Number	Portables on Site	PM Inspection Schedule		Proposed Round 97 Inspection Date	Comments from Round 96 Inspection
			Round 96 Inspection Date	DCS Inspector		
	HB 091		09-Jan-16	S.Parliament	25-Feb-16	<i>N.S.M.O.M.O.</i>
	HB 100		11-Jan-16	S.Parliament	25-Feb-16	<i>N.S.M.O.M.O.</i>
	HB 133		09-Jan-16	S.Parliament	25-Feb-16	<i>N.S.M.O.M.O.</i>
	HB 134		11-Jan-16	S.Parliament	25-Feb-16	<i>N.S.M.O.M.O.</i>
	HB 135		11-Jan-16	S.Parliament	25-Feb-16	<i>N.S.M.O.M.O.</i>
	HB 143		09-Jan-16	S.Parliament	25-Feb-16	<i>N.S.M.O.M.O.</i>
	HB 203		09-Jan-16	S.Parliament	25-Feb-16	<i>Holes (1/4") observed underneath air-conditioner unit.</i>
	HBL 005		11-Jan-16	S.Parliament	25-Feb-16	<i>N.S.M.O.M.O.</i>
	HBL 080		01-Sep-15	S.Parliament	25-Feb-16	<i>N.S.M.O.M.O.</i>
	HBL 084		01-Sep-15	S.Parliament	25-Feb-16	<i>N.S.M.O.M.O.</i>
	HB 113		11-Jan-16	S.Parliament	25-Feb-16	<i>Exterior caulking degraded and/or missing at air-conditioner, front window and conduits. Screw holes observed in metal cladding at front elevation. Stained ceiling tile observed.</i>
	HB 125		11-Jan-16	S.Parliament	25-Feb-16	<i>Exterior caulking degraded at air-exchanger unit.</i>
Escarpment View P.S.	HB 005	12	12-Jan-16	S.Parliament	01-Feb-16	<i>N.S.M.O.M.O.</i>
	HB 089		12-Jan-16	S.Parliament	01-Feb-16	<i>N.S.M.O.M.O.</i>
	HB 144		12-Jan-16	S.Parliament	01-Feb-16	<i>Screw holes observed in metal cladding at right elevation.</i>
	HBL 081		12-Jan-16	S.Parliament	01-Feb-16	<i>N.S.M.O.M.O.</i>
	HBL 082		12-Jan-16	S.Parliament	01-Feb-16	<i>N.S.M.O.M.O.</i>
	HBL 083		12-Jan-16	S.Parliament	01-Feb-16	<i>N.S.M.O.M.O.</i>
	HBL 088		12-Jan-16	S.Parliament	01-Feb-16	<i>N.S.M.O.M.O.</i>
	HBL 089		12-Jan-16	S.Parliament	01-Feb-16	<i>N.S.M.O.M.O.</i>
	HBL 090		12-Jan-16	S.Parliament	01-Feb-16	<i>N.S.M.O.M.O.</i>
	HBL 091		12-Jan-16	S.Parliament	01-Feb-16	<i>N.S.M.O.M.O.</i>
	HBL 103		12-Jan-16	S.Parliament	01-Feb-16	<i>Gouge (2") observed in metal cladding at front elevation.</i>
	HBL 104		12-Jan-16	S.Parliament	01-Feb-16	<i>N.S.M.O.M.O.</i>
E.W. Foster P.S.	HB 086	5	23-Dec-15	D. Kellyman	29-Feb-16	<i>Screw holes observed in metal cladding at right elevation.</i>
	HB 129		23-Dec-15	D. Kellyman	29-Feb-16	<i>N.S.M.O.M.O.</i>
	HB 160		23-Dec-15	D. Kellyman	29-Feb-16	<i>N.S.M.O.M.O.</i>
	HB 180		23-Dec-15	D. Kellyman	29-Feb-16	<i>N.S.M.O.M.O.</i>
	HB 189		23-Dec-15	D. Kellyman	29-Feb-16	<i>Exterior caulking missing at downspout.</i>
Gardiner P.S.	HBL 207	2	23-Nov-15	S.Parliament	01-Feb-16	<i>N.S.M.O.M.O.</i>
	HBL 212		23-Nov-15	S.Parliament	01-Feb-16	<i>Hole (1.5") observed in metal cladding at right elevation. Screw holes observed in front corner flashing at right elevation. Exterior caulking degraded at front windows.</i>
Glen Williams P.S.	HB 178	2	23-Nov-15	S.Parliament	1-Feb-16	<i>N.S.M.O.M.O.</i>
	HB 184		23-Nov-15	S.Parliament	1-Feb-16	<i>Skirting (3') damaged at front elevation.</i>
Hawthorne Village P.S.	HB 013	22	24-Nov-15	D.Kellyman	3-Feb-16	<i>N.S.M.O.M.O.</i>
	HB 034		24-Nov-15	D.Kellyman	3-Feb-16	<i>N.S.M.O.M.O.</i>
	HB 035		24-Nov-15	D.Kellyman	3-Feb-16	<i>N.S.M.O.M.O.</i>
	HB 036		24-Nov-15	D.Kellyman	3-Feb-16	<i>N.S.M.O.M.O.</i>
	HB 136		24-Nov-15	D.Kellyman	3-Feb-16	<i>N.S.M.O.M.O.</i>
	HB 155		24-Nov-15	D.Kellyman	3-Feb-16	<i>N.S.M.O.M.O.</i>
	HB 162		24-Nov-15	D.Kellyman	3-Feb-16	<i>N.S.M.O.M.O.</i>

PORTABLE CLASSROOM PRENTATIVE MAINTENANCE INSPECTION NO. 96 SUMMARY

School	Portable Number	Portables on Site	PM Inspection Schedule		Proposed Round 97 Inspection Date	Comments from Round 96 Inspection
			Round 96 Inspection Date	DCS Inspector		
	RM 101		23-Nov-15	D.Kellyman	3-Feb-16	<i>N.S.M.O.M.O.</i>
	RM 102		23-Nov-15	D.Kellyman	3-Feb-16	<i>N.S.M.O.M.O.</i>
	RM 103		23-Nov-15	D.Kellyman	3-Feb-16	<i>N.S.M.O.M.O.</i>
	RM 104		23-Nov-15	D.Kellyman	3-Feb-16	<i>N.S.M.O.M.O.</i>
	RM 105		23-Nov-15	D.Kellyman	3-Feb-16	<i>N.S.M.O.M.O.</i>
	RM 301		23-Nov-15	D.Kellyman	3-Feb-16	<i>N.S.M.O.M.O.</i>
	RM 302		23-Nov-15	D.Kellyman	3-Feb-16	<i>N.S.M.O.M.O.</i>
	RM 303		23-Nov-15	D.Kellyman	3-Feb-16	<i>N.S.M.O.M.O.</i>
	RM 304		23-Nov-15	D.Kellyman	3-Feb-16	<i>N.S.M.O.M.O.</i>
	RM 305		23-Nov-15	D.Kellyman	3-Feb-16	<i>N.S.M.O.M.O.</i>
	RM 306		23-Nov-15	D.Kellyman	3-Feb-16	<i>N.S.M.O.M.O.</i>
	RM 307		23-Nov-15	D.Kellyman	3-Feb-16	<i>N.S.M.O.M.O.</i>
	RM 308		23-Nov-15	D.Kellyman	3-Feb-16	<i>N.S.M.O.M.O.</i>
	RM 309		23-Nov-15	D.Kellyman	3-Feb-16	<i>N.S.M.O.M.O.</i>
	RM 310		23-Nov-15	D.Kellyman	3-Feb-16	<i>N.S.M.O.M.O.</i>
Irma Coulson P.S.	HB 009	13	23-Dec-15	D.Kellyman	29-Feb-16	<i>N.S.M.O.M.O.</i>
	HB 081		23-Dec-15	D.Kellyman	29-Feb-16	<i>N.S.M.O.M.O.</i>
	HB 142		23-Dec-15	D.Kellyman	29-Feb-16	<i>N.S.M.O.M.O.</i>
	HB 146		23-Dec-15	D.Kellyman	29-Feb-16	<i>N.S.M.O.M.O.</i>
	HB 150		23-Dec-15	D.Kellyman	29-Feb-16	<i>N.S.M.O.M.O.</i>
	HBL 242		23-Dec-15	D.Kellyman	29-Feb-16	<i>Exterior caulking degraded at window. Screw holes observed in metal cladding at left elevation.</i>
	HBL 243		23-Dec-15	D.Kellyman	29-Feb-16	<i>Screw holes observed in corner flashing at left elevation. Downspout detached at left elevation.</i>
	HBL 244		23-Dec-15	D.Kellyman	29-Feb-16	<i>N.S.M.O.M.O.</i>
	HBL 245		23-Dec-15	D.Kellyman	29-Feb-16	<i>N.S.M.O.M.O.</i>
	HBL 246		23-Dec-15	D.Kellyman	29-Feb-16	<i>Screw holes observed in metal cladding at right elevation.</i>
	HB 204		23-Dec-15	D.Kellyman	29-Feb-16	<i>Exterior caulking missing at windows, door, and air-exchanger vent.</i>
	HBL 111		23-Dec-15	D.Kellyman	29-Feb-16	<i>N.S.M.O.M.O.</i>
	HB 196		23-Dec-15	D.Kellyman	29-Feb-16	<i>Exterior caulking degraded at air-exchanger vent.</i>
Martin Street P.S.	HB 152	2	07-Jan-16	S.Parliament	29-Feb-16	<i>N.S.M.O.M.O.</i>
	HB 015		07-Jan-16	S.Parliament	29-Feb-16	<i>N.S.M.O.M.O.</i>
Milton District H.S.	HB 001	3	12-Jan-16	S.Parliament	1-Feb-16	<i>N.S.M.O.M.O.</i>
	HB 093		12-Jan-16	S.Parliament	1-Feb-16	<i>Exterior caulking missing at front door. Hole (2") observed in metal cladding at rear elevation. Hole (1.5") observed in metal cladding at left elevation.</i>
	HB 154		12-Jan-16	S.Parliament	1-Feb-16	<i>Hole (4") observed in drywall at west wall.</i>
P.L. Robertson P.S.	HB 004	7	01-Dec-15	S. Parliament	9-Feb-16	<i>N.S.M.O.M.O.</i>
	HB 016		01-Dec-15	S. Parliament	9-Feb-16	<i>Caulking degraded at door and second window.</i>
	HB 021		01-Dec-15	S. Parliament	9-Feb-16	<i>N.S.M.O.M.O.</i>
	HB 022		01-Dec-15	S. Parliament	9-Feb-16	<i>N.S.M.O.M.O.</i>
	HB 027		01-Dec-15	S. Parliament	9-Feb-16	<i>Hole (1") observed in drywall at west wall.</i>
	HB 030		01-Dec-15	S. Parliament	9-Feb-16	<i>N.S.M.O.M.O.</i>
	HB 039		01-Dec-15	S. Parliament	9-Feb-16	<i>N.S.M.O.M.O.</i>
Park P.S.	HB 048	1	23-Nov-15	S.Parliament	2-Feb-16	<i>N.S.M.O.M.O.</i>
Robert Baldwin P.S.	HB 122	4	15-Jan-16	S.Parliament	2-Feb-16	<i>N.S.M.O.M.O.</i>

PORTABLE CLASSROOM PRENTATIVE MAINTENANCE INSPECTION NO. 96 SUMMARY

School	Portable Number	Portables on Site	PM Inspection Schedule		Proposed Round 97 Inspection Date	Comments from Round 96 Inspection
			Round 96 Inspection Date	DCS Inspector		
	HB 174		15-Jan-16	S.Parliament	2-Feb-16	N.S.M.O.M.O.
	HBL 079		15-Jan-16	S.Parliament	2-Feb-16	N.S.M.O.M.O.
	HBL 248 (1072)		15-Jan-16	S.Parliament	2-Feb-16	N.S.M.O.M.O.
Robert Little P.S.	HB 208	2	23-Nov-15	S.Parliament	2-Feb-16	N.S.M.O.M.O.
	HBL 10		23-Nov-15	S.Parliament	2-Feb-16	Downspout damaged at rear elevation.
Sam Sherratt P.S.	HB 082	10	11-Jan-16	S.Parliament	25-Feb-16	Stained ceiling tile observed.
	HB 083		11-Jan-16	S.Parliament	25-Feb-16	N.S.M.O.M.O.
	HBL 087		11-Jan-16	S.Parliament	25-Feb-16	N.S.M.O.M.O.
	HBL 099		11-Jan-16	S.Parliament	25-Feb-16	N.S.M.O.M.O.
	HBL 223		11-Jan-16	S.Parliament	25-Feb-16	N.S.M.O.M.O.
	HBL 227		11-Jan-16	S.Parliament	25-Feb-16	N.S.M.O.M.O.
	HB 041		11-Jan-16	S.Parliament	25-Feb-16	Exterior caulking missing at rear elevation conduit.
	HB 195		11-Jan-16	S.Parliament	25-Feb-16	Screw holes observed in metal cladding at front elevation.
	HB 066		11-Jan-16	S.Parliament	25-Feb-16	Section of metal cladding (5"x4') missing around conduit support.
	HB 127		11-Jan-16	S.Parliament	25-Feb-16	Screw holes observed in rear right corner flashing and center flashing at left elevation.
Silver Creek P.S.	HB 029	2	23-Nov-15	S.Parliament	25-Feb-16	N.S.M.O.M.O.
	HB 033		23-Nov-15	S.Parliament	25-Feb-16	N.S.M.O.M.O.
Tiger Jeet Singh P.S.	HB 063	11	15-Jan-16	S.Parliament	25-Feb-16	N.S.M.O.M.O.
	HB 095		15-Jan-16	S.Parliament	25-Feb-16	N.S.M.O.M.O.
	HB 109		15-Jan-16	S.Parliament	25-Feb-16	Large nest/ debris observed above ceiling space at north wall center seam. Stained ceiling tiles (~2) observed (new). Water pooling on vapour barrier and wet insulation observed in ceiling space at C-2.
	HB 116		15-Jan-16	S.Parliament	25-Feb-16	N.S.M.O.M.O.
	HB 126		15-Jan-16	S.Parliament	25-Feb-16	N.S.M.O.M.O.
	HB 187		15-Jan-16	S.Parliament	25-Feb-16	N.S.M.O.M.O.
	HBL 098		15-Jan-16	S.Parliament	25-Feb-16	Screw holes observed in metal cladding at front elevation. Downspout damaged at front elevation.
	HBL 013		15-Jan-16	S.Parliament	25-Feb-16	N.S.M.O.M.O.
	HBL 014		15-Jan-16	S.Parliament	25-Feb-16	N.S.M.O.M.O.
	HBL 015		15-Jan-16	S.Parliament	25-Feb-16	N.S.M.O.M.O.
	HBL 213		15-Jan-16	S.Parliament	25-Feb-16	N.S.M.O.M.O.
W.I. Dick P.S.	HB 002	3	27-Nov-15	D.Kellyman	25-Feb-16	N.S.M.O.M.O.
	HB 007		27-Nov-15	D.Kellyman	25-Feb-16	N.S.M.O.M.O.
	HB 183		27-Nov-15	D.Kellyman	25-Feb-16	N.S.M.O.M.O.
Total Number of Portables		154				

Notes:	
Scheduled inspection date subject to change due to availability of manpower and the facility.	
N.S.M.O.M.O. =	No Suspect Mould Or Moisture Observed

PORTABLE CLASSROOM PREVENTATIVE MAINTENANCE INPECTION NO. 96 SUMMARY

School	Portable Number	Portables on Site	PM Inspection Schedule		Proposed Round 97 Inspection Date	Comments from Round 96 Inspection
			Round 96 Inspection Date	DCS Inspector		
Abbey Park H.S.	HB 164	3	01-Jan-16	S.Parliament	11-Feb-16	<i>N.S.M.O.M.O.</i>
	HB 108		01-Jan-16	S.Parliament	11-Feb-16	<i>N.S.M.O.M.O.</i>
	HB 163		01-Jan-16	S.Parliament	11-Feb-16	<i>N.S.M.O.M.O.</i>
E.J. James P.S.	HB 061	6	05-Jan-16	S.Parliament	23-Feb-16	<i>Exterior caulking missing at left elevation conduit.</i>
	HB 079		05-Jan-16	S.Parliament	23-Feb-16	<i>N.S.M.O.M.O.</i>
	HB 111		05-Jan-16	S.Parliament	23-Feb-16	<i>N.S.M.O.M.O.</i>
	HB 121		05-Jan-16	S.Parliament	23-Feb-16	<i>N.S.M.O.M.O.</i>
	HBL 009		05-Jan-16	S.Parliament	23-Feb-16	<i>N.S.M.O.M.O.</i>
	HBL085		05-Jan-16	S.Parliament	23-Feb-16	<i>Baseboard (10') missing along west wall.</i>
Iroquois Ridge H.S.	HB 070	3	05-Jan-16	S.Parliament	23-Feb-16	<i>N.S.M.O.M.O.</i>
	HB 209		05-Jan-16	S.Parliament	23-Feb-16	<i>N.S.M.O.M.O.</i>
	HB 202		05-Jan-16	S.Parliament	23-Feb-16	<i>Stained ceiling tile observed.</i>
James W. Hill P.S.	HB 080	3	28-Dec-15	D.Kellyman	22-Feb-16	<i>N.S.M.O.M.O.</i>
	HB 099		28-Dec-15	D.Kellyman	22-Feb-16	<i>N.S.M.O.M.O.</i>
	HB 176		28-Dec-15	D.Kellyman	22-Feb-16	<i>Wooden fascia (1') damaged at left elevation.</i>
Joshua Creek P.S.	HB 011	3	28-Dec-15	D.Kellyman	22-Feb-16	<i>N.S.M.O.M.O.</i>
	HB 077		28-Dec-15	D.Kellyman	22-Feb-16	<i>Exterior caulking degraded at door.</i>
	HB 085		28-Dec-15	D.Kellyman	22-Feb-16	<i>N.S.M.O.M.O.</i>
Munn's P.S.	HB 106	2	04-Jan-16	S.Parliament	16-Feb-16	<i>Exterior caulking missing at front door.</i>
	HB 177		04-Jan-16	S.Parliament	16-Feb-16	<i>N.S.M.O.M.O.</i>
Oakville Trafalgar H.S. (Portable)	RM 190	7	05-Jan-16	S.Parliament	23-Feb-16	<i>N.S.M.O.M.O.</i>
	RM 191		05-Jan-16	S.Parliament	23-Feb-16	<i>N.S.M.O.M.O.</i>
	RM 192		05-Jan-16	S.Parliament	23-Feb-16	<i>N.S.M.O.M.O.</i>
	RM 193		05-Jan-16	S.Parliament	23-Feb-16	<i>N.S.M.O.M.O.</i>
	RM 194		05-Jan-16	S.Parliament	23-Feb-16	<i>N.S.M.O.M.O.</i>
	RM 198		05-Jan-16	S.Parliament	23-Feb-16	<i>N.S.M.O.M.O.</i>
	RM 199		05-Jan-16	S.Parliament	23-Feb-16	<i>N.S.M.O.M.O.</i>
Pilgrim Wood P.S.	HBL 110	2	04-Jan-16	S.Parliament	16-Feb-16	<i>N.S.M.O.M.O.</i>
	HBL 224		04-Jan-16	S.Parliament	16-Feb-16	<i>N.S.M.O.M.O.</i>
Post's Corners P.S.	HB 065	1	28-Dec-15	D.Kellyman	22-Feb-16	<i>N.S.M.O.M.O.</i>
Sheridan P.S.	HBL 226	1	28-Dec-15	D.Kellyman	22-Feb-16	<i>N.S.M.O.M.O.</i>
Total Number of Portables		31				

Notes:	
Scheduled inspection date subject to change due to availability of manpower and the facility.	
N.S.M.O.M.O. =	No Suspect Mould Or Moisture Observed

PORTABLE CLASSROOM PREVENTATIVE MAINTENANCE INSPECTION NO. 96 SUMMARY

School	Portable Number	Portables on Site	PM Inspection Schedule		Proposed Round 97 Inspection Date	Comments from Round 96 Inspection
			Round 96 Inspection Date	DCS Inspector		
Alexander's P.S.	HB 008	5	30-Nov-15	J. Jones	17-Feb-16	<i>N.S.M.O.M.O.</i>
	HB 024		30-Nov-15	J. Jones	17-Feb-16	<i>N.S.M.O.M.O.</i>
	HB 028		30-Nov-15	J. Jones	17-Feb-16	<i>N.S.M.O.M.O.</i>
	HB 032		30-Nov-15	J. Jones	17-Feb-16	<i>N.S.M.O.M.O.</i>
	HB 051		30-Nov-15	J. Jones	17-Feb-16	<i>N.S.M.O.M.O.</i>
Charles R. Beaudoin P.S.	HBL 100	4	29-Dec-15	D.Kellyman	03-Feb-16	<i>N.S.M.O.M.O.</i>
	HBL 101		29-Dec-15	D.Kellyman	03-Feb-16	<i>N.S.M.O.M.O.</i>
	HBL 102		29-Dec-15	D.Kellyman	03-Feb-16	<i>N.S.M.O.M.O.</i>
	HBL 247		29-Dec-15	D.Kellyman	03-Feb-16	<i>N.S.M.O.M.O.</i>
Dr. Frank Hayden	HB 059	6	01-Dec-15	S. Parliament	9-Feb-16	<i>Exterior caulking degraded at front door. Stained ceiling tiles (2) observed.</i>
	HB 120		01-Dec-15	S. Parliament	9-Feb-16	<i>N.S.M.O.M.O.</i>
	HB 137		01-Dec-15	S. Parliament	9-Feb-16	<i>N.S.M.O.M.O.</i>
	HB 172		01-Dec-15	S. Parliament	9-Feb-16	<i>N.S.M.O.M.O.</i>
	HB 207		01-Dec-15	S. Parliament	9-Feb-16	<i>Screw holes observed in metal cladding at right elevation. Vapour barrier damaged at ceiling tile at C-3.</i>
	HB 092		01-Dec-15	S. Parliament	9-Feb-16	<i>Hole (3") observed at right elevation for air-conditioner wiring. Exterior caulking missing at front door.</i>
J.W. Singleton Education Centre	HB 003	4	09-Dec-15	J. Jones	29-Feb-16	<i>N.S.M.O.M.O.</i>
	HB 117		09-Dec-15	J. Jones	29-Feb-16	<i>N.S.M.O.M.O.</i>
	HB 118		09-Dec-15	J. Jones	29-Feb-16	<i>N.S.M.O.M.O.</i>
	HB 119		09-Dec-15	J. Jones	29-Feb-16	<i>N.S.M.O.M.O.</i>
John T. Tuck P.S.	HB 064	8	29-Dec-15	D.Kellyman	29-Feb-16	<i>N.S.M.O.M.O.</i>
	HB 156		29-Dec-15	D.Kellyman	29-Feb-16	<i>N.S.M.O.M.O.</i>
	HB 157		29-Dec-15	D.Kellyman	29-Feb-16	<i>N.S.M.O.M.O.</i>
	HB 173		29-Dec-15	D.Kellyman	29-Feb-16	<i>N.S.M.O.M.O.</i>
	HBL 219		29-Dec-15	D.Kellyman	29-Feb-16	<i>N.S.M.O.M.O.</i>
	HBL 220		29-Dec-15	D.Kellyman	29-Feb-16	<i>N.S.M.O.M.O.</i>
	HBL 221		29-Dec-15	D.Kellyman	29-Feb-16	<i>N.S.M.O.M.O.</i>
	HBL 216		29-Dec-15	D.Kellyman	29-Feb-16	<i>Exterior caulking degraded at windows and conduit.</i>
John W. Boich P.S.	HBL 217	5	30-Nov-15	J. Jones	17-Feb-16	<i>N.S.M.O.M.O.</i>
	HBL 218		30-Nov-15	J. Jones	17-Feb-16	<i>N.S.M.O.M.O.</i>
	HBL 247		30-Nov-15	J. Jones	17-Feb-16	<i>N.S.M.O.M.O.</i>
	HBL 108		30-Nov-15	J. Jones	17-Feb-16	<i>N.S.M.O.M.O.</i>
	HBL 109		30-Nov-15	J. Jones	17-Feb-16	<i>N.S.M.O.M.O.</i>
L.B. Pearson H.S.	RM 179 A	12	09-Dec-15	J. Jones	29-Feb-16	<i>N.S.M.O.M.O.</i>
	RM 180		09-Dec-15	J. Jones	29-Feb-16	<i>N.S.M.O.M.O.</i>
	RM 181		09-Dec-15	J. Jones	29-Feb-16	<i>N.S.M.O.M.O.</i>
	RM 182		09-Dec-15	J. Jones	29-Feb-16	<i>N.S.M.O.M.O.</i>
	RM 183		09-Dec-15	J. Jones	29-Feb-16	<i>N.S.M.O.M.O.</i>
	RM 184		09-Dec-15	J. Jones	29-Feb-16	<i>Stained ceiling tile observed.</i>
	RM 185		09-Dec-15	J. Jones	29-Feb-16	<i>N.S.M.O.M.O.</i>
	RM 186		09-Dec-15	J. Jones	29-Feb-16	<i>N.S.M.O.M.O.</i>
	RM 187		09-Dec-15	J. Jones	29-Feb-16	<i>N.S.M.O.M.O.</i>
	RM 188		09-Dec-15	J. Jones	29-Feb-16	<i>N.S.M.O.M.O.</i>
	RM 189		09-Dec-15	J. Jones	29-Feb-16	<i>N.S.M.O.M.O.</i>
	RM 190 A/B		09-Dec-15	J. Jones	29-Feb-16	<i>N.S.M.O.M.O.</i>
M.M. Robinson H.S.	HB 010	3	15-Jan-16	S.Parliament	29-Feb-16	<i>N.S.M.O.M.O.</i>

PORTABLE CLASSROOM PREVENTATIVE MAINTENANCE INSPECTION NO. 96 SUMMARY

School	Portable Number	Portables on Site	PM Inspection Schedule		Proposed Round 97 Inspection Date	Comments from Round 96 Inspection
			Round 96 Inspection Date	DCS Inspector		
	HB 161		15-Jan-16	S.Parliament	29-Feb-16	<i>N.S.M.O.M.O.</i>
	HB 151		15-Jan-16	S.Parliament	29-Feb-16	<i>N.S.M.O.M.O.</i>
Pineland P.S.	HB 006	6	26-Nov-15	J. Jones	8-Feb-16	<i>N.S.M.O.M.O.</i>
	HB 067		26-Nov-15	J. Jones	8-Feb-16	<i>N.S.M.O.M.O.</i>
	HB 069		26-Nov-15	J. Jones	8-Feb-16	<i>N.S.M.O.M.O.</i>
	HB 094		26-Nov-15	J. Jones	8-Feb-16	<i>N.S.M.O.M.O.</i>
	HB 096		26-Nov-15	J. Jones	8-Feb-16	<i>N.S.M.O.M.O.</i>
	HB 128		26-Nov-15	J. Jones	8-Feb-16	<i>N.S.M.O.M.O.</i>
Sir E. MacMillan P.S.	HB 017	6	25-Nov-15	J. Jones	8-Feb-16	<i>N.S.M.O.M.O.</i>
	HB 018		25-Nov-15	J. Jones	8-Feb-16	<i>N.S.M.O.M.O.</i>
	HB 019		25-Nov-15	J. Jones	8-Feb-16	<i>N.S.M.O.M.O.</i>
	HB 020		25-Nov-15	J. Jones	8-Feb-16	<i>N.S.M.O.M.O.</i>
	HB 025		25-Nov-15	J. Jones	8-Feb-16	<i>Wood siding damaged.</i>
	HB 165		25-Nov-15	J. Jones	8-Feb-16	<i>N.S.M.O.M.O.</i>
Total Number of Portables		59				

Notes:	
Scheduled inspection date subject to change due to availability of manpower and the facility.	
N.S.M.O.M.O. =	No Suspect Mould Or Moisture Observed

PORTABLE CLASSROOM PREVENTATIVE MAINTENANCE INSPECTION NO. 96 SUMMARY

School	Portable Number	Portables on Site	PM Inspection Schedule		Proposed Round 97 Inspection Date	Comments from Round 96 Inspection
			Round 96 Inspection Date	DCS Inspector		
Captain R. Wilson P.S.	HB 014	1	04-Jan-16	S. Parliament	16-Feb-16	<i>N.S.M.O.M.O.</i>
Emily Carr P.S.	HB 084	4	04-Jan-16	S. Parliament	16-Feb-16	<i>N.S.M.O.M.O.</i>
	HBL 001		04-Jan-16	S. Parliament	16-Feb-16	<i>N.S.M.O.M.O.</i>
	HBL 002		04-Jan-16	S. Parliament	16-Feb-16	<i>N.S.M.O.M.O.</i>
Forest Trail P.S.	HBL 008	9	04-Jan-16	S. Parliament	16-Feb-16	<i>N.S.M.O.M.O.</i>
	HB 044		27-Nov-15	S. Parliament	02-Feb-16	<i>N.S.M.O.M.O.</i>
	HB 047		27-Nov-15	S. Parliament	02-Feb-16	<i>N.S.M.O.M.O.</i>
	HB 049		27-Nov-15	S. Parliament	02-Feb-16	<i>Exterior caulking degraded at conduit and wiring at left elevation. Screw holes observed in metal cladding at left elevation.</i>
	HB 050		27-Nov-15	S. Parliament	02-Feb-16	<i>N.S.M.O.M.O.</i>
	HB 052		27-Nov-15	S. Parliament	02-Feb-16	<i>Exterior caulking degraded and/or missing at air-exchanger vent.</i>
	HB 054		27-Nov-15	S. Parliament	02-Feb-16	<i>N.S.M.O.M.O.</i>
	HB 058		27-Nov-15	S. Parliament	02-Feb-16	<i>N.S.M.O.M.O.</i>
	HB 076		27-Nov-15	S. Parliament	02-Feb-16	<i>N.S.M.O.M.O.</i>
Gladys Speers P.S.	HB 101	1	27-Nov-15	S. Parliament	02-Feb-16	<i>Baseboard (5') missing along south and east walls.</i>
	HB 104		01-Jan-16	S. Parliament	11-Feb-16	<i>N.S.M.O.M.O.</i>
Palmero P.S.	HB 086	5	01-Jan-16	S.Parliament	11-Feb-16	<i>Screw holes observed in metal cladding at right elevation. Exterior caulking degraded at right elevation conduit. Downspout at front elevation damaged.</i>
	HB 087		01-Jan-16	S.Parliament	11-Feb-16	<i>Exterior caulking degraded at front door.</i>
	HB 167		01-Jan-16	S.Parliament	11-Feb-16	<i>Left corner flashing damaged at rear elevation.</i>
	HB 168		01-Jan-16	S.Parliament	11-Feb-16	<i>N.S.M.O.M.O.</i>
	HB 170		01-Jan-16	S.Parliament	11-Feb-16	<i>N.S.M.O.M.O.</i>
Pine Grove P.S.	HB 043	10	21-Dec-15	D.Kellyman	2-Feb-15	<i>N.S.M.O.M.O.</i>
	HB 097		21-Dec-15	D.Kellyman	2-Feb-15	<i>N.S.M.O.M.O.</i>
	HB 123		21-Dec-15	D.Kellyman	2-Feb-15	<i>N.S.M.O.M.O.</i>
	HB 130		21-Dec-15	D.Kellyman	2-Feb-15	<i>N.S.M.O.M.O.</i>
	HB 131		21-Dec-15	D.Kellyman	2-Feb-15	<i>N.S.M.O.M.O.</i>
	HB 158		21-Dec-15	D.Kellyman	2-Feb-15	<i>N.S.M.O.M.O.</i>
	HB 159		21-Dec-15	D.Kellyman	2-Feb-15	<i>N.S.M.O.M.O.</i>
	HB 171		21-Dec-15	D.Kellyman	2-Feb-15	<i>N.S.M.O.M.O.</i>
	HB 175		21-Dec-15	D.Kellyman	2-Feb-15	<i>Section (3"x3") of fascia missing at right elevation.</i>
	HBL 006		21-Dec-15	D.Kellyman	2-Feb-15	<i>N.S.M.O.M.O.</i>
Sunningdale P.S.	HB 072	4	01-Jan-16	S.Parliament	11-Feb-15	<i>N.S.M.O.M.O.</i>
	HB 132		01-Jan-16	S.Parliament	11-Feb-15	<i>N.S.M.O.M.O.</i>
	HB 145		01-Jan-16	S.Parliament	11-Feb-15	<i>N.S.M.O.M.O.</i>
	HB 179		01-Jan-16	S.Parliament	11-Feb-15	<i>Exterior caulking degraded and/or missing at conduit at left elevation. Hole (2") observed in metal cladding at left elevation. Screw holes observed in metal cladding and corner flashing at right elevation.</i>
W.H. Morden P.S.	HB 055	6	21-Dec-15	D.Kellyman	1-Feb-15	<i>N.S.M.O.M.O.</i>
	HB 138		21-Dec-15	D.Kellyman	1-Feb-15	<i>N.S.M.O.M.O.</i>
	HBL 007		21-Dec-15	D.Kellyman	1-Feb-15	<i>N.S.M.O.M.O.</i>
	HBL 249 (1147)		21-Dec-15	D.Kellyman	1-Feb-15	<i>N.S.M.O.M.O.</i>
	HBL 250 (931)		21-Dec-15	D.Kellyman	1-Feb-15	<i>N.S.M.O.M.O.</i>
	HB 199		21-Dec-15	D.Kellyman	1-Feb-15	<i>N.S.M.O.M.O.</i>
West Oak P.S.	RM 1	9	27-Nov-15	S. Parliament	3-Feb-16	<i>N.S.M.O.M.O.</i>
	RM 2		27-Nov-15	S. Parliament	3-Feb-16	<i>N.S.M.O.M.O.</i>
	RM 3		27-Nov-15	S. Parliament	3-Feb-16	<i>N.S.M.O.M.O.</i>
	RM 4		27-Nov-15	S. Parliament	3-Feb-16	<i>N.S.M.O.M.O.</i>

PORTABLE CLASSROOM PREVENTATIVE MAINTENANCE INSPECTION NO. 96 SUMMARY

School	Portable Number	Portables on Site	PM Inspection Schedule		Proposed Round 97 Inspection Date	Comments from Round 96 Inspection
			Round 96 Inspection Date	DCS Inspector		
	RM 5		27-Nov-15	S. Parliament	3-Feb-16	<i>N.S.M.O.M.O.</i>
	RM 6		27-Nov-15	S. Parliament	3-Feb-16	<i>N.S.M.O.M.O.</i>
	Work Room		27-Nov-15	S. Parliament	3-Feb-16	<i>N.S.M.O.M.O.</i>
	HB 107		27-Nov-15	S. Parliament	3-Feb-16	<i>N.S.M.O.M.O.</i>
	HB 088		27-Nov-15	S. Parliament	3-Feb-16	<i>Screw holes observed in metal cladding at front elevation. Downspout damaged at rear elevation.</i>
White Oaks Centre for Science and Technology (North Campus)	HB 060	5	04-Jan-16	S. Parliament	16-Feb-16	<i>N.S.M.O.M.O.</i>
	HBL 092		04-Jan-16	S. Parliament	16-Feb-16	<i>N.S.M.O.M.O.</i>
	HBL 093		04-Jan-16	S. Parliament	16-Feb-16	<i>N.S.M.O.M.O.</i>
	HBL 094		04-Jan-16	S. Parliament	16-Feb-16	<i>N.S.M.O.M.O.</i>
	HBL 095		04-Jan-16	S. Parliament	16-Feb-16	<i>N.S.M.O.M.O.</i>
White Oaks School Admin. (South Campus)	HB 023	12	25-Nov-15	J. Jones	05-Feb-16	<i>N.S.M.O.M.O.</i>
	HB 042		25-Nov-15	J. Jones	05-Feb-16	<i>N.S.M.O.M.O.</i>
	HBL 016		25-Nov-15	J. Jones	05-Feb-16	<i>N.S.M.O.M.O.</i>
	HB 078		25-Nov-15	J. Jones	05-Feb-16	<i>N.S.M.O.M.O.</i>
	HB 112		25-Nov-15	J. Jones	05-Feb-16	<i>N.S.M.O.M.O.</i>
	HB 153		25-Nov-15	J. Jones	05-Feb-16	<i>N.S.M.O.M.O.</i>
	HBL 018		25-Nov-15	J. Jones	05-Feb-16	<i>N.S.M.O.M.O.</i>
	HB 201		25-Nov-15	J. Jones	05-Feb-16	<i>Missing ceiling tile observed near front door.</i>
	HB 205		25-Nov-15	J. Jones	05-Feb-16	<i>N.S.M.O.M.O.</i>
	HBL 017		25-Nov-15	J. Jones	05-Feb-16	<i>N.S.M.O.M.O.</i>
	HBL 096		25-Nov-15	J. Jones	05-Feb-16	<i>N.S.M.O.M.O.</i>
	HBL 097		25-Nov-15	J. Jones	05-Feb-16	<i>N.S.M.O.M.O.</i>
Total Number of Portables		66				

Notes:	
Scheduled inspection date subject to change due to availability of manpower and the facility.	
N.S.M.O.M.O. =	No Suspect Mould Or Moisture Observed

PORTABLE CLASSROOM PREVENTATIVE MAINTENANCE INSPECTION NO. 96 SUMMARY

School	Portable Number	Portables on Site	PM Inspection Schedule		Proposed Round 97 Inspection Date	Comments from Round 96 Inspection
			Round 96 Inspection Date	DCS Inspector		
Alton Village P.S.	HBL 234	10	28-Dec-15	S.Parliament	10-Feb-16	<i>N.S.M.O.M.O.</i>
	HBL 235		28-Dec-15	S.Parliament	10-Feb-16	<i>N.S.M.O.M.O.</i>
	HBL 236		28-Dec-15	S.Parliament	10-Feb-16	<i>N.S.M.O.M.O.</i>
	HBL 237		28-Dec-15	S.Parliament	10-Feb-16	<i>Screw holes observed in metal cladding at front elevation beside door.</i>
	HBL 238		28-Dec-15	S.Parliament	10-Feb-16	<i>N.S.M.O.M.O.</i>
	HBL 239		28-Dec-15	S.Parliament	10-Feb-16	<i>Screw holes observed at left elevation. Exterior caulking degraded at windows.</i>
	HBL 225		28-Dec-15	S.Parliament	10-Feb-16	<i>Screw holes observed at left elevation.</i>
	HB 068		28-Dec-15	S.Parliament	10-Feb-16	<i>Eavestrough missing at front and rear elevation. Exterior caulking degraded and/or missing at first window. Downspout missing at front elevation. Screw holes observed in metal cladding at front elevation.</i>
	HB 037		28-Dec-15	S.Parliament	10-Feb-16	<i>Screw holes observed in metal cladding at right elevation.</i>
	HBL 35		28-Dec-15	S.Parliament	10-Feb-16	<i>N.S.M.O.M.O.</i>
Dr. Charles Best P.S.	HB 210	2	22-Nov-15	S.Parliament	4-Feb-16	<i>End cap missing on rear eavestrough.</i>
	HBL 211		22-Nov-15	S.Parliament	4-Feb-16	<i>N.S.M.O.M.O.</i>
Florence Meares P.S.	HB 139	1	28-Dec-15	S.Parliament	10-Feb-16	<i>Hole (2") observed in metal cladding at right elevation</i>
Kilbride P.S.	HB 074	1	28-Dec-15	S.Parliament	10-Feb-16	<i>N.S.M.O.M.O.</i>
Orchard Park P.S.	HB 040	4	30-Nov-15	J. Jones	17-Feb-16	<i>N.S.M.O.M.O.</i>
	HB 147		30-Nov-15	J. Jones	17-Feb-16	<i>N.S.M.O.M.O.</i>
	HB 166		30-Nov-15	J. Jones	17-Feb-16	<i>N.S.M.O.M.O.</i>
	HB 140		30-Nov-15	J. Jones	17-Feb-16	<i>N.S.M.O.M.O.</i>
Pauline Johnson P.S.	HBL 222	2	26-Nov-15	J. Jones	8-Feb-16	<i>N.S.M.O.M.O.</i>
	HB 102		26-Nov-15	J. Jones	8-Feb-16	<i>N.S.M.O.M.O.</i>
Tom Thompson P.S.	HB 012	10	22-Nov-15	S.Parliament	4-Feb-16	<i>N.S.M.O.M.O.</i>
	HB 031		22-Nov-15	S.Parliament	4-Feb-16	<i>Exterior caulking missing at conduit at rear elevation.</i>
	HB 053		22-Nov-15	S.Parliament	4-Feb-16	<i>Downspout detached at rear elevation.</i>
	HB 098		22-Nov-15	S.Parliament	4-Feb-16	<i>Exterior caulking degraded at right elevation. Screw holes observed in metal cladding at right elevation. Vapour barrier missing and/or damaged at ceiling tile C-3.</i>
	HB 105		22-Nov-15	S.Parliament	4-Feb-16	<i>N.S.M.O.M.O.</i>
	HB 124		22-Nov-15	S.Parliament	4-Feb-16	<i>N.S.M.O.M.O.</i>
	HB 141		22-Nov-15	S.Parliament	4-Feb-16	<i>Hole (2") observed in metal cladding at front elevation.</i>
	HB 148		22-Nov-15	S.Parliament	4-Feb-16	<i>N.S.M.O.M.O.</i>
	HB 169		22-Nov-15	S.Parliament	4-Feb-16	<i>Corner flashing damaged at right elevation.</i>
	HB 206		22-Nov-15	S.Parliament	4-Feb-16	<i>Downspout missing at rear elevation.</i>
Total Number of Portables		30				

Notes:	
Scheduled inspection date subject to change due to availability of manpower and the facility.	
N.S.M.O.M.O. =	No Suspect Mould Or Moisture Observed