

PORTABLE CLASSROOM PREVENTATIVE MAINTENANCE INSPECTION NO. 97 SUMMARY

School	Portable Number	Portables on Site	PM Inspection Schedule		Proposed Round 98 Inspection Date	Comments from Round 97 Inspection
			Round 97 Inspection Date	ARCADIS Inspector		
Anne J. MacArthur P.S.	HB 026	10	16-Feb-16	D.Kellyman	10-Apr-16	<i>N.S.M.O.M.O.</i>
	HB 071		16-Feb-16	D. Kellyman	10-Apr-16	<i>Exterior caulking degraded at windows and door.</i>
	HBL 202		16-Feb-16	D. Kellyman	10-Apr-16	<i>N.S.M.O.M.O.</i>
	HBL 203		16-Feb-16	D. Kellyman	10-Apr-16	<i>N.S.M.O.M.O.</i>
	HBL 204		16-Feb-16	D. Kellyman	10-Apr-16	<i>Exterior caulking degraded at windows.</i>
	HBL 205		16-Feb-16	D. Kellyman	10-Apr-16	<i>N.S.M.O.M.O.</i>
	HBL 214		16-Feb-16	D. Kellyman	10-Apr-16	<i>N.S.M.O.M.O.</i>
	HBL 215		16-Feb-16	D. Kellyman	10-Apr-16	<i>N.S.M.O.M.O.</i>
	HBL 232		16-Feb-16	D. Kellyman	10-Apr-16	<i>N.S.M.O.M.O.</i>
	HBL 233		16-Feb-16	D. Kellyman	10-Apr-16	<i>N.S.M.O.M.O.</i>
Brookville P.S.	HBL 201	1	09-Mar-16	S.Parliament	6-May-16	<i>N.S.M.O.M.O.</i>
Bruce Trail P.S.	HB 046	13	16-Feb-16	S.Parliament	7-Apr-16	<i>N.S.M.O.M.O.</i>
	HB 062		16-Feb-16	S.Parliament	7-Apr-16	<i>N.S.M.O.M.O.</i>
	HB 075		16-Feb-16	S.Parliament	7-Apr-16	<i>Exterior caulking degraded at both windows. Vinyl floor tiles (~4) damaged throughout.</i>
	HB 103		16-Feb-16	S.Parliament	7-Apr-16	<i>N.S.M.O.M.O.</i>
	HB 110		16-Feb-16	S.Parliament	7-Apr-16	<i>N.S.M.O.M.O.</i>
	HB 114		16-Feb-16	S.Parliament	7-Apr-16	<i>N.S.M.O.M.O.</i>
	HB 115		16-Feb-16	S.Parliament	7-Apr-16	<i>N.S.M.O.M.O.</i>
	HB 149		16-Feb-16	S.Parliament	7-Apr-16	<i>Downspout damaged at rear elevation.</i>
	HBL 105		16-Feb-16	S.Parliament	7-Apr-16	<i>N.S.M.O.M.O.</i>
	HBL 228		16-Feb-16	S.Parliament	7-Apr-16	<i>N.S.M.O.M.O.</i>
	HBL 229		16-Feb-16	S.Parliament	7-Apr-16	<i>N.S.M.O.M.O.</i>
	HBL 230		16-Feb-16	S.Parliament	7-Apr-16	<i>N.S.M.O.M.O.</i>
	HBL 231		16-Feb-16	S.Parliament	7-Apr-16	<i>N.S.M.O.M.O.</i>
Chris Hadfield P.S.	RM A1	12	09-Mar-16	S.Parliament	6-May-16	<i>N.S.M.O.M.O.</i>
	RM A2		09-Mar-16	S.Parliament	6-May-16	<i>N.S.M.O.M.O.</i>
	RM A3		09-Mar-16	S.Parliament	6-May-16	<i>N.S.M.O.M.O.</i>
	RM A4		09-Mar-16	S.Parliament	6-May-16	<i>N.S.M.O.M.O.</i>
	RM A5		09-Mar-16	S.Parliament	6-May-16	<i>N.S.M.O.M.O.</i>
	RM A6		09-Mar-16	S.Parliament	6-May-16	<i>N.S.M.O.M.O.</i>
	RM A7		09-Mar-16	S.Parliament	6-May-16	<i>N.S.M.O.M.O.</i>
	RM A8		09-Mar-16	S.Parliament	6-May-16	<i>N.S.M.O.M.O.</i>
	RM A9		09-Mar-16	S.Parliament	6-May-16	<i>N.S.M.O.M.O.</i>
	RM A10		09-Mar-16	S.Parliament	6-May-16	<i>N.S.M.O.M.O.</i>
	RM A11		09-Mar-16	S.Parliament	6-May-16	<i>N.S.M.O.M.O.</i>
	HBL 106		09-Mar-16	S.Parliament	6-May-16	<i>N.S.M.O.M.O.</i>
Craig Kielburger S.S.	HB 038	18	07-Mar-16	C. Jagarnauth	12-May-16	<i>Edge flashing damaged at front elevation leaving sharp edge.</i>
	HB 045		07-Mar-16	C. Jagarnauth	12-May-16	<i>N.S.M.O.M.O.</i>
	HB 056		07-Mar-16	C. Jagarnauth	12-May-16	<i>N.S.M.O.M.O.</i>
	HB 057		07-Mar-16	C. Jagarnauth	12-May-16	<i>N.S.M.O.M.O.</i>
	HB 073		07-Mar-16	C. Jagarnauth	12-May-16	<i>N.S.M.O.M.O.</i>
	HB 090		07-Mar-16	C. Jagarnauth	12-May-16	<i>N.S.M.O.M.O.</i>
	HB 091		07-Mar-16	C. Jagarnauth	12-May-16	<i>N.S.M.O.M.O.</i>
	HB 100		07-Mar-16	C. Jagarnauth	12-May-16	<i>N.S.M.O.M.O.</i>
	HB 133		07-Mar-16	C. Jagarnauth	12-May-16	<i>N.S.M.O.M.O.</i>
	HB 134		07-Mar-16	C. Jagarnauth	12-May-16	<i>N.S.M.O.M.O.</i>

PORTABLE CLASSROOM PREVENTATIVE MAINTENANCE INSPECTION NO. 97 SUMMARY

School	Portable Number	Portables on Site	PM Inspection Schedule		Proposed Round 98 Inspection Date	Comments from Round 97 Inspection
			Round 97 Inspection Date	ARCADIS Inspector		
	HB 135		07-Mar-16	C. Jagarnauth	12-May-16	<i>N.S.M.O.M.O.</i>
	HB 143		07-Mar-16	C. Jagarnauth	12-May-16	<i>N.S.M.O.M.O.</i>
	HB 203		07-Mar-16	C. Jagarnauth	12-May-16	<i>Holes (1/4") observed underneath air-conditioner unit.</i>
	HBL 005		07-Mar-16	C. Jagarnauth	12-May-16	<i>N.S.M.O.M.O.</i>
	HBL 080		07-Mar-16	C. Jagarnauth	12-May-16	<i>N.S.M.O.M.O.</i>
	HBL 084		07-Mar-16	C. Jagarnauth	12-May-16	<i>N.S.M.O.M.O.</i>
	HB 113		07-Mar-16	C. Jagarnauth	12-May-16	<i>N.S.M.O.M.O.</i>
	HB 125		07-Mar-16	C. Jagarnauth	12-May-16	<i>N.S.M.O.M.O.</i>
Escarpment View P.S.	HBL 103	12	17-Feb-16	S.Parliament	12-Apr-16	<i>N.S.M.O.M.O.</i>
	HB 005		17-Feb-16	S.Parliament	12-Apr-16	<i>Vinyl floor tile and subfloor damaged by door.</i>
	HB 089		17-Feb-16	S.Parliament	12-Apr-16	<i>Kick plate at front door detached.</i>
	HB 144		17-Feb-16	S.Parliament	12-Apr-16	<i>Screw holes observed in metal cladding and center flashing at right elevation.</i>
	HBL 081		17-Feb-16	S.Parliament	12-Apr-16	<i>N.S.M.O.M.O.</i>
	HBL 082		17-Feb-16	S.Parliament	12-Apr-16	<i>N.S.M.O.M.O.</i>
	HBL 083		17-Feb-16	S.Parliament	12-Apr-16	<i>N.S.M.O.M.O.</i>
	HBL 088		17-Feb-16	S.Parliament	12-Apr-16	<i>N.S.M.O.M.O.</i>
	HBL 090		17-Feb-16	S.Parliament	12-Apr-16	<i>N.S.M.O.M.O.</i>
	HBL 091		17-Feb-16	S.Parliament	12-Apr-16	<i>N.S.M.O.M.O.</i>
	HBL 104		17-Feb-16	S.Parliament	12-Apr-16	<i>N.S.M.O.M.O.</i>
	HBL 089		17-Feb-16	S.Parliament	12-Apr-16	<i>N.S.M.O.M.O.</i>
E.W. Foster P.S.	HB 086	5	26-Feb-16	D.Kellyman	14-May-16	<i>Screw holes observed in metal cladding at right elevation.</i>
	HB 129		26-Feb-16	D.Kellyman	14-May-16	<i>N.S.M.O.M.O.</i>
	HB 160		26-Feb-16	D.Kellyman	14-May-16	<i>N.S.M.O.M.O.</i>
	HB 180		26-Feb-16	D.Kellyman	14-May-16	<i>N.S.M.O.M.O.</i>
	HB 189		26-Feb-16	D.Kellyman	14-May-16	<i>Exterior caulking missing at downspout.</i>
Gardiner P.S.	HBL 207	2	24-Feb-16	D.Kellyman	6-Apr-16	<i>N.S.M.O.M.O.</i>
	HBL 212		24-Feb-16	D.Kellyman	6-Apr-16	<i>Hole (1.5") observed in metal cladding at right elevation. Screw holes observed in front corner flashing at right elevation. Exterior caulking degraded at front windows.</i>
Glen Williams P.S.	HB 178	2	24-Feb-16	D.Kellyman	6-Apr-16	<i>N.S.M.O.M.O.</i>
	HB 184		24-Feb-16	D.Kellyman	6-Apr-16	<i>N.S.M.O.M.O.</i>
Hawthorne Village P.S.	HB 013	22	29-Feb-16	S.Parliament	19-Apr-16	<i>N.S.M.O.M.O.</i>
	HB 034		29-Feb-16	S.Parliament	19-Apr-16	<i>N.S.M.O.M.O.</i>
	HB 035		29-Feb-16	S.Parliament	19-Apr-16	<i>N.S.M.O.M.O.</i>
	HB 036		29-Feb-16	S.Parliament	19-Apr-16	<i>N.S.M.O.M.O.</i>
	HB 136		29-Feb-16	S.Parliament	19-Apr-16	<i>Roof edge flashing missing at left elevation. Skirting damaged at left elevation. Stained ceiling tile (1) observed at C-2 (new).</i>
	HB 155		29-Feb-16	S.Parliament	19-Apr-16	<i>N.S.M.O.M.O.</i>
	HB 162		29-Feb-16	S.Parliament	19-Apr-16	<i>N.S.M.O.M.O.</i>
	RM 101		29-Feb-16	S.Parliament	19-Apr-16	<i>N.S.M.O.M.O.</i>
	RM 102		29-Feb-16	S.Parliament	19-Apr-16	<i>Stained ceiling tiles (~3) observed (new).</i>
	RM 103		29-Feb-16	S.Parliament	19-Apr-16	<i>Stained ceiling tiles (~2) observed (new).</i>
	RM 104		29-Feb-16	S.Parliament	19-Apr-16	<i>N.S.M.O.M.O.</i>
	RM 105		29-Feb-16	S.Parliament	20-Apr-16	<i>N.S.M.O.M.O.</i>
	RM 301		29-Feb-16	S.Parliament	20-Apr-16	<i>N.S.M.O.M.O.</i>
	RM 302		29-Feb-16	S.Parliament	20-Apr-16	<i>N.S.M.O.M.O.</i>

PORTABLE CLASSROOM PREVENTATIVE MAINTENANCE INSPECTION NO. 97 SUMMARY

School	Portable Number	Portables on Site	PM Inspection Schedule		Proposed Round 98 Inspection Date	Comments from Round 97 Inspection
			Round 97 Inspection Date	ARCADIS Inspector		
	RM 303		29-Feb-16	S.Parliament	20-Apr-16	<i>N.S.M.O.M.O.</i>
	RM 304		29-Feb-16	S.Parliament	20-Apr-16	<i>N.S.M.O.M.O.</i>
	RM 305		29-Feb-16	S.Parliament	20-Apr-16	<i>N.S.M.O.M.O.</i>
	RM 306		29-Feb-16	S.Parliament	20-Apr-16	<i>N.S.M.O.M.O.</i>
	RM 307		29-Feb-16	S.Parliament	20-Apr-16	<i>N.S.M.O.M.O.</i>
	RM 308		29-Feb-16	S.Parliament	20-Apr-16	<i>N.S.M.O.M.O.</i>
	RM 309		29-Feb-16	S.Parliament	20-Apr-16	<i>N.S.M.O.M.O.</i>
	RM 310		29-Feb-16	S.Parliament	20-Apr-16	<i>N.S.M.O.M.O.</i>
Irma Coulson P.S.	HB 009	13	26-Feb-16	D.Kellyman	14-May-16	<i>N.S.M.O.M.O.</i>
	HB 081		26-Feb-16	D.Kellyman	14-May-16	<i>N.S.M.O.M.O.</i>
	HB 142		26-Feb-16	D.Kellyman	14-May-16	<i>N.S.M.O.M.O.</i>
	HB 146		26-Feb-16	D.Kellyman	14-May-16	<i>N.S.M.O.M.O.</i>
	HB 150		26-Feb-16	D.Kellyman	14-May-16	<i>N.S.M.O.M.O.</i>
	HBL 242		26-Feb-16	D.Kellyman	14-May-16	<i>Exterior caulking degraded at window. Screw holes observed in metal cladding at left elevation.</i>
	HBL 243		26-Feb-16	D.Kellyman	14-May-16	<i>Screw holes observed in corner flashing at left elevation. Downspout detached at left elevation.</i>
	HBL 244		26-Feb-16	D.Kellyman	14-May-16	<i>N.S.M.O.M.O.</i>
	HBL 245		26-Feb-16	D.Kellyman	14-May-16	<i>N.S.M.O.M.O.</i>
	HBL 246		26-Feb-16	D.Kellyman	14-May-16	<i>Screw holes observed in metal cladding at right elevation.</i>
	HB 204		26-Feb-16	D.Kellyman	14-May-16	<i>Exterior caulking missing at windows, door, and air-exchanger vent.</i>
	HBL 111		26-Feb-16	D.Kellyman	14-May-16	<i>N.S.M.O.M.O.</i>
	HB 196		26-Feb-16	D.Kellyman	14-May-16	<i>Exterior caulking degraded at air-exchanger vent.</i>
Martin Street P.S.	HB 152	2		S. Parliament		<i>Portable not present on site at the time of inspection. Portable to be inspected at new location during next round of inspections.</i>
	HB 015			S. Parliament		<i>Portable not present on site at the time of inspection. Portable to be inspected at new location during next round of inspections.</i>
Milton District H.S.	HB 001	3	17-Feb-16	S.Parliament	12-April-16	<i>N.S.M.O.M.O.</i>
	HB 093		17-Feb-16	S.Parliament	12-April-16	<i>N.S.M.O.M.O.</i>
	HB 154		17-Feb-16	S.Parliament	12-April-16	<i>N.S.M.O.M.O.</i>
P.L. Robertson P.S.	HB 004	7	08-Mar-16	C. Jagarnauth	26-April-16	<i>N.S.M.O.M.O.</i>
	HB 016		08-Mar-16	C. Jagarnauth	26-April-16	<i>Caulking degraded at door and windows.</i>
	HB 021		08-Mar-16	C. Jagarnauth	26-April-16	<i>N.S.M.O.M.O.</i>
	HB 022		08-Mar-16	C. Jagarnauth	26-April-16	<i>N.S.M.O.M.O.</i>
	HB 027		08-Mar-16	C. Jagarnauth	26-April-16	<i>Hole (1") observed in drywall at west wall.</i>
	HB 030		08-Mar-16	C. Jagarnauth	26-April-16	<i>N.S.M.O.M.O.</i>
	HB 039		08-Mar-16	C. Jagarnauth	26-April-16	<i>N.S.M.O.M.O.</i>
Park P.S.	HB 048	1	24-Feb-16	D.Kellyman	6-Apr-16	<i>N.S.M.O.M.O.</i>
Robert Baldwin P.S.	HB 208	2	24-Feb-16	D.Kellyman	11-Apr-16	<i>N.S.M.O.M.O.</i>
	HBL 10		24-Feb-16	D.Kellyman	11-Apr-16	<i>N.S.M.O.M.O.</i>
Robert Little P.S.	HB 208	2	24-Feb-16	D.Kellyman	6-Apr-16	<i>N.S.M.O.M.O.</i>
	HBL 10		24-Feb-16	D.Kellyman	6-Apr-16	<i>N.S.M.O.M.O.</i>
Sam Sherratt P.S.	HB 082	10	16-Feb-16	C. Jagarnauth	13-May-16	<i>N.S.M.O.M.O.</i>
	HB 083		16-Feb-16	C. Jagarnauth	13-May-16	<i>N.S.M.O.M.O.</i>
	HBL 087		16-Feb-16	C. Jagarnauth	13-May-16	<i>N.S.M.O.M.O.</i>
	HBL 099		16-Feb-16	C. Jagarnauth	13-May-16	<i>N.S.M.O.M.O.</i>
	HBL 223		16-Feb-16	C. Jagarnauth	13-May-16	<i>N.S.M.O.M.O.</i>
	HBL 227		16-Feb-16	C. Jagarnauth	13-May-16	<i>N.S.M.O.M.O.</i>
	HB 041		16-Feb-16	C. Jagarnauth	13-May-16	<i>Exterior caulking missing at rear elevation conduit.</i>
	HB 195		16-Feb-16	C. Jagarnauth	13-May-16	<i>Screw holes observed in metal cladding at front elevation.</i>

PORTABLE CLASSROOM PREVENTATIVE MAINTENANCE INSPECTION NO. 97 SUMMARY

School	Portable Number	Portables on Site	PM Inspection Schedule		Proposed Round 98 Inspection Date	Comments from Round 97 Inspection
			Round 97 Inspection Date	ARCADIS Inspector		
	HB 066		16-Feb-16	C. Jagarnauth	13-May-16	<i>Section of metal cladding (5'x4') missing around conduit support.</i>
	HB 127		16-Feb-16	C. Jagarnauth	13-May-16	<i>Screw holes observed in rear right corner flashing and center flashing at left elevation.</i>
Silver Creek P.S.	HB 029	2	24-Feb-16	D.Kellyman	6-Apr-16	<i>N.S.M.O.M.O.</i>
	HB 033		24-Feb-16	D.Kellyman	6-Apr-16	<i>N.S.M.O.M.O.</i>
Tiger Jeet Singh P.S.	HB 063	11	17-Feb-16	C. Jagarnauth	11-April-16	<i>N.S.M.O.M.O.</i>
	HB 095		17-Feb-16	C. Jagarnauth	11-April-16	<i>N.S.M.O.M.O.</i>
	HB 109		17-Feb-16	C. Jagarnauth	11-April-16	<i>Large nest/ debris observed above ceiling space at north wall center seam.</i>
	HB 116		17-Feb-16	C. Jagarnauth	11-April-16	<i>N.S.M.O.M.O.</i>
	HB 126		17-Feb-16	C. Jagarnauth	11-April-16	<i>N.S.M.O.M.O.</i>
	HB 187		17-Feb-16	C. Jagarnauth	11-April-16	<i>N.S.M.O.M.O.</i>
	HBL 098		17-Feb-16	C. Jagarnauth	11-April-16	<i>Screw holes observed in metal cladding at front elevation. Downspout damaged at front elevation.</i>
	HBL 013		17-Feb-16	C. Jagarnauth	11-April-16	<i>N.S.M.O.M.O.</i>
	HBL 014		17-Feb-16	C. Jagarnauth	11-April-16	<i>N.S.M.O.M.O.</i>
	HBL 015		17-Feb-16	C. Jagarnauth	11-April-16	<i>N.S.M.O.M.O.</i>
	HBL 213		17-Feb-16	C. Jagarnauth	11-April-16	<i>N.S.M.O.M.O.</i>
W.I. Dick P.S.	HB 002	3	16-Feb-16	S.Parliament	4-April-16	<i>Caulking missing around hole (1") observed at rear metal cladding.</i>
	HB 007		16-Feb-16	S.Parliament	4-April-16	<i>Vinyl floor tiles (~5) damaged throughout.</i>
	HB 183		16-Feb-16	S.Parliament	4-April-16	<i>Large pool of standing water observed underneath portable.</i>
<b>Total Number of Portables</b>		<b>153</b>				

Notes:	
Scheduled inspection date subject to change due to availability of manpower and the facility.	
<b>N.S.M.O.M.O. =</b>	<b>No Suspect Mould Or Moisture Observed</b>

PORTABLE CLASSROOM PREVENTATIVE MAINTENANCE INSPECTION NO. 97 SUMMARY

School	Portable Number	Portables on Site	PM Inspection Schedule		Proposed Round 98 Inspection Date	Comments from Round 97 Inspection
			Round 97 Inspection Date	ARCADIS Inspector		
Abbey Park H.S.	HB 164	3	15-Mar-16	S.Parliament	28-April-16	<i>N.S.M.O.M.O.</i>
	HB 108		15-Mar-16	S.Parliament	28-April-16	<i>Screw holes observed at front, rear and right elevations (existing).</i>
	HB 163		15-Mar-16	S.Parliament	28-April-16	<i>N.S.M.O.M.O.</i>
E.J. James P.S.	HB 061	6	14-Mar-16	S.Parliament	11-May-16	<i>Exterior caulking degraded at left elevation conduit.</i>
	HB 079		14-Mar-16	S.Parliament	11-May-16	<i>N.S.M.O.M.O.</i>
	HB 111		14-Mar-16	S.Parliament	11-May-16	<i>Water stain and dirt/debris observed on vapour barrier in ceiling space at C-2.</i>
	HB 121		14-Mar-16	S.Parliament	11-May-16	<i>N.S.M.O.M.O.</i>
	HBL 009		14-Mar-16	S.Parliament	11-May-16	<i>N.S.M.O.M.O.</i>
	HBL 85		14-Mar-16	S.Parliament	11-May-16	<i>Baseboard (5') missing.</i>
Iroquois Ridge H.S.	HB 070	3	14-Mar-16	S.Parliament	7-May-16	<i>Exterior caulking degraded at first window (existing). Hole (1") observed in metal cladding at rear wall caused by missing conduit (existing). Wooden skirting damaged at front elevation.</i>
	HB 209		14-Mar-16	S.Parliament	7-May-16	<i>N.S.M.O.M.O.</i>
	HB 202		14-Mar-16	S.Parliament	7-May-16	<i>Hole (2") and screw holes observed in metal cladding at right elevation. Exterior caulking missing at left elevation gable-louvre. Exterior caulking degraded at right elevation conduits. Siding open/missing at right elevation</i>
James W. Hill P.S.	HB 080	3	10-Mar-16	S.parliament	7-May-16	<i>N.S.M.O.M.O.</i>
	HB 099		10-Mar-16	S.Parliament	7-May-16	<i>Exterior caulking degraded at front door (existing).</i>
	HB 176		10-Mar-16	S.Parliament	7-May-16	<i>Vinyl floor tiles (~12) damaged throughout (existing). Baseboard (8') missing at corners (existing). Hole (1") observed in drywall. Wooden fascia damaged at left elevation. Large quantities of dirt/debris observed on vapour barrier in ceiling space at C-2.</i>
Joshua Creek P.S.	HB 085	3	10-Mar-16	S.Parliament	7-May-16	<i>Exterior caulking missing at left elevation conduit.</i>
	HB 011		10-Mar-16	S.Parliament	7-May-16	<i>N.S.M.O.M.O.</i>
	HB 077		10-Mar-16	S.Parliament	7-May-16	<i>Exterior caulking degraded at front door (existing). Tear (1") observed in metal cladding at front elevation (existing).</i>
Munn's P.S.	HB 106	2	07-Mar-16	S.Parliament	4-May-16	<i>Exterior caulking degraded at front door (existing). Screw holes observed in metal cladding at right elevation.</i>
	HB 177		07-Mar-16	S.Parliament	4-May-16	<i>Screw holes observed in metal cladding at right elevation (existing).</i>
Oakville Trafalgar H.S. (Portable Relocatable)	RM 190	7	14-Mar-16	S. Parliament	11-May-16	<i>N.S.M.O.M.O.</i>
	RM 191		14-Mar-16	S. Parliament	11-May-16	<i>N.S.M.O.M.O.</i>
	RM 192		14-Mar-16	S. Parliament	11-May-16	<i>N.S.M.O.M.O.</i>
	RM 193		14-Mar-16	S. Parliament	11-May-16	<i>N.S.M.O.M.O.</i>
	RM 194		14-Mar-16	S. Parliament	11-May-16	<i>N.S.M.O.M.O.</i>
	RM 198		14-Mar-16	S. Parliament	11-May-16	<i>N.S.M.O.M.O.</i>
Pilgrim Wood P.S.	HBL 110	2	07-Mar-16	S.Parliament	4-May-16	<i>N.S.M.O.M.O.</i>
	HBL 224		07-Mar-16	S.Parliament	4-May-16	<i>Screw holes observed in corner flashing and metal cladding at rear and right elevation.</i>
Post's Corners P.S.	HB 065	1	10-Mar-16	S.Parliament	7-May-16	<i>Screw holes observed in corner flashing and cladding at rear elevation (existing). Exterior caulking missing at front door (existing). Exterior caulking missing at rear elevation conduit (existing). Downspout missing at rear elevation.</i>
Sheridan P.S.	HBL 226	1	10-Mar-16	S.Parliament	7-May-16	<i>N.S.M.O.M.O.</i>
<b>Total Number of Portables</b>		<b>31</b>				

Notes:	
Scheduled inspection date subject to change due to availability of manpower and the facility.	
N.S.M.O.M.O. =	No Suspect Mould Or Moisture Observed

PORTABLE CLASSROOM PREVENTATIVE MAINTENANCE INSPECTION NO. 97 SUMMARY

School	Portable Number	Portables on Site	PM Inspection Schedule		Proposed Round 98 Inspection Date	Comments from Round 97 Inspection
			Round 97 Inspection Date	ARCADIS Inspector		
Alexander's P.S.	HB 008	6	05-Mar-16	S.Parliament	5-May-16	N.S.M.O.M.O.
	HB 024		05-Mar-16	S.Parliament	5-May-16	Screw holes observed in metal cladding and roof flashing at right elevation.
	HB 028		05-Mar-16	S.Parliament	5-May-16	N.S.M.O.M.O.
	HB 032		05-Mar-16	S.Parliament	5-May-16	Hole (1.5") in drywall (existing). Exterior caulking degraded at second window. Screw holes observed in metal cladding at front elevation. Edge flashing damaged leaving sharp edges at left elevation.
	HB 051		05-Mar-16	S.Parliament	5-May-16	N.S.M.O.M.O.
	HBL 241		05-Mar-16	S.Parliament	5-May-16	N.S.M.O.M.O.
Charles R. Beaudoin P.S.	HBL 100	4	11-Mar-16	J.Jones	13-May-16	N.S.M.O.M.O.
	HBL 101		11-Mar-16	J.Jones	13-May-16	N.S.M.O.M.O.
	HBL 102		11-Mar-16	J.Jones	13-May-16	N.S.M.O.M.O.
	HBL 247		11-Mar-16	J.Jones	13-May-16	N.S.M.O.M.O.
Dr. Frank Hayden	HB 059	6	17-Feb-16	C. Jagarnauth	26-April-16	Exterior caulking degraded at front door. Stained ceiling tiles (2) observed (new).
	HB 120		17-Feb-16	C. Jagarnauth	26-April-16	Exterior caulking degraded at front door (existing).
	HB 137		17-Feb-16	C. Jagarnauth	26-April-16	N.S.M.O.M.O.
	HB 172		17-Feb-16	C. Jagarnauth	26-April-16	Exterior caulking missing at front door (existing).
	HB 207		17-Feb-16	C. Jagarnauth	26-April-16	Screw holes observed in metal cladding at right elevation. Vapour barrier damaged at C-3.
	HB 092		17-Feb-16	C. Jagarnauth	26-April-16	Hole (3") observed at right elevation for air-conditioner wiring. Exterior caulking missing at front door.
J.W. Singleton Education Centre	HB 003	4	23-Mar-16	J.Jones	18-May-15	N.S.M.O.M.O.
	HB 117		23-Mar-16	J.Jones	18-May-15	N.S.M.O.M.O.
	HB 118		23-Mar-16	J.Jones	18-May-15	N.S.M.O.M.O.
	HB 119		23-Mar-16	J.Jones	18-May-15	N.S.M.O.M.O.
John T. Tuck P.S.	HB 064	8	11-Mar-16	J.Jones	13-April-15	Exterior caulking missing and/or degraded at door (existing).
	HB 156		11-Mar-16	J.Jones	13-April-15	Edge flashing missing at front and right elevations (existing).
	HB 157		11-Mar-16	J.Jones	13-April-15	N.S.M.O.M.O.
	HB 173		11-Mar-16	J.Jones	13-April-15	N.S.M.O.M.O.
	HBL 219		11-Mar-16	J.Jones	13-April-15	N.S.M.O.M.O.
	HBL 220		11-Mar-16	J.Jones	13-April-15	N.S.M.O.M.O.
	HBL 221		11-Mar-16	J.Jones	13-April-15	N.S.M.O.M.O.
	HBL 216		11-Mar-16	J.Jones	13-April-15	N.S.M.O.M.O.
John W. Boich P.S.	HBL 247	5	05-Mar-16	S. Parliament	5-May-16	N.S.M.O.M.O.
	HB 108		05-Mar-16	S. Parliament	5-May-16	N.S.M.O.M.O.
	HB 109		05-Mar-16	S. Parliament	5-May-16	N.S.M.O.M.O.
	HBL 217		05-Mar-16	S. Parliament	5-May-16	N.S.M.O.M.O.
	HBL 218		05-Mar-16	S. Parliament	5-May-16	N.S.M.O.M.O.
L.B. Pearson H.S.	RM 179 A	12	23-Mar-16	J.Jones	18-May-16	Room not accessible at time of inspection.
	RM 180		23-Mar-16	J.Jones	18-May-16	N.S.M.O.M.O.
	RM 181		23-Mar-16	J.Jones	18-May-16	N.S.M.O.M.O.
	RM 182		23-Mar-16	J.Jones	18-May-16	N.S.M.O.M.O.
	RM 183		23-Mar-16	J.Jones	18-May-16	N.S.M.O.M.O.
	RM 184		23-Mar-16	J.Jones	18-May-16	N.S.M.O.M.O.
	RM 185		23-Mar-16	J.Jones	18-May-16	N.S.M.O.M.O.
	RM 186		23-Mar-16	J.Jones	18-May-16	N.S.M.O.M.O.
	RM 187		23-Mar-16	J.Jones	18-May-16	N.S.M.O.M.O.
	RM 188		23-Mar-16	J.Jones	18-May-16	N.S.M.O.M.O.
	RM 189		23-Mar-16	J.Jones	18-May-16	N.S.M.O.M.O.
	RM 190 A/B		23-Mar-16	J.Jones	18-May-16	N.S.M.O.M.O.
M.M. Robinson H.S.	HB 010	3	23-Mar-16	J.Jones	18-May-16	N.S.M.O.M.O.
	HB 161		23-Mar-16	J.Jones	18-May-16	N.S.M.O.M.O.

PORTABLE CLASSROOM PREVENTATIVE MAINTENANCE INSPECTION NO. 97 SUMMARY

School	Portable Number	Portables on Site	PM Inspection Schedule		Proposed Round 98 Inspection Date	Comments from Round 97 Inspection
			Round 97 Inspection Date	ARCADIS Inspector		
	HB 151		23-Mar-16	J.Jones	18-May-16	<i>N.S.M.O.M.O.</i>
Pineland P.S.	HB 006	6	03-Mar-16	D.Kellyman	25-April-15	<i>N.S.M.O.M.O.</i>
	HB 067		03-Mar-16	D.Kellyman	25-April-16	<i>N.S.M.O.M.O.</i>
	HB 069		03-Mar-16	D.Kellyman	25-April-16	<i>N.S.M.O.M.O.</i>
	HB 094		03-Mar-16	D.Kellyman	25-April-16	<i>N.S.M.O.M.O.</i>
	HB 096		03-Mar-16	D.Kellyman	25-April-16	<i>N.S.M.O.M.O.</i>
	HB 128		03-Mar-16	D.Kellyman	25-April-16	<i>Exterior caulking degraded at door.</i>
Sir E. MacMillan P.S.	HB 017	6	03-Mar-16	D.Kellyman	25-April-16	<i>N.S.M.O.M.O.</i>
	HB 018		03-Mar-16	D.Kellyman	25-April-16	<i>N.S.M.O.M.O.</i>
	HB 019		03-Mar-16	D.Kellyman	25-April-16	<i>Exterior caulking degraded at air exchanger vent (new).</i>
	HB 020		03-Mar-16	D.Kellyman	25-April-16	<i>Hole (1") observed in metal cladding at right elevation.</i>
	HB 025		03-Mar-16	D.Kellyman	25-April-16	<i>Damaged wood siding observed.</i>
	HB 165		03-Mar-16	D.Kellyman	25-April-16	<i>Exterior caulking degraded at door.</i>
<b>Total Number of Portables</b>		<b>60</b>				

Notes:	
Scheduled inspection date subject to change due to availability of manpower and the facility.	
N.S.M.O.M.O. =	No Suspect Mould Or Moisture Observed

PORTABLE CLASSROOM PREVENTATIVE MAINTENANCE INSPECTION NO. 97 SUMMARY

School	Portable Number	Portables on Site	PM Inspection Schedule		Proposed Round 98 Inspection Date	Comments from Round 97 Inspection
			Round 97 Inspection Date	ARCADIS Inspector		
Captain R. Wilson P.S.	HB 014	1	07-Mar-16	S.Parliament	4-May-16	<i>N.S.M.O.M.O.</i>
Emily Carr P.S.	HB 084	4	07-Mar-16	S.Parliament	4-May-16	<i>N.S.M.O.M.O.</i>
	HBL 001		07-Mar-16	S.Parliament	4-May-16	<i>N.S.M.O.M.O.</i>
	HBL 002		07-Mar-16	S.Parliament	4-May-16	<i>Skirting ventilation cover missing at right elevation.</i>
	HBL 008		07-Mar-16	S.Parliament	4-May-16	<i>N.S.M.O.M.O.</i>
Forest Trail P.S.	HB 044	9	03-Mar-16	S.Parliament	14-April-16	<i>N.S.M.O.M.O.</i>
	HB 047		03-Mar-16	S.Parliament	14-April-16	<i>N.S.M.O.M.O.</i>
	HB 049		03-Mar-16	S.Parliament	14-April-16	<i>N.S.M.O.M.O.</i>
	HB 050		03-Mar-16	S.Parliament	14-April-16	<i>N.S.M.O.M.O.</i>
	HB 052		03-Mar-16	S.Parliament	14-April-16	<i>N.S.M.O.M.O.</i>
	HB 054		03-Mar-16	S.Parliament	14-April-16	<i>N.S.M.O.M.O.</i>
	HB 058		03-Mar-16	S.Parliament	14-April-16	<i>Stained ceiling tile (~1) observed along center seam (new). Water stains observed on vapour barrier above stained ceiling tile (new).</i>
	HB 076		03-Mar-16	S.Parliament	14-April-16	<i>N.S.M.O.M.O.</i>
	HB 101		03-Mar-16	S.Parliament	14-April-16	<i>Front railing detached/loose.</i>
Palmero P.S.	HB 086	5	15-Mar-16	S.Parliament	28-Apr-16	<i>Screw holes observed in metal cladding at right elevation. Exterior caulking degraded at right elevation conduit.</i>
	HB 087		15-Mar-16	S.Parliament	28-Apr-16	<i>N.S.M.O.M.O.</i>
	HB 167		15-Mar-16	S.Parliament	28-Apr-16	<i>Exterior caulking missing at front downspout and left elevation conduit. Corner flash and roof flashing damaged at rear elevation. Metal cladding at right elevation detached.</i>
	HB 168		15-Mar-16	S.Parliament	28-Apr-16	<i>Exterior caulking missing at front downspout. Baseboard (5') missing by door.</i>
	HB 170			S.Parliament	28-Apr-16	<i>N.S.M.O.M.O.</i>
Pine Grove P.S.	HB 043	10	16-Feb-16	J.Jones	18-Apr-16	<i>N.S.M.O.M.O.</i>
	HB 097		16-Feb-16	J.Jones	18-Apr-16	<i>N.S.M.O.M.O.</i>
	HB 123		16-Feb-16	J.Jones	18-Apr-16	<i>N.S.M.O.M.O.</i>
	HB 130		16-Feb-16	J.Jones	18-Apr-16	<i>N.S.M.O.M.O.</i>
	HB 131		16-Feb-16	J.Jones	18-Apr-16	<i>N.S.M.O.M.O.</i>
	HB 158		16-Feb-16	J.Jones	18-Apr-16	<i>N.S.M.O.M.O.</i>
	HB 159		16-Feb-16	J.Jones	18-Apr-16	<i>N.S.M.O.M.O.</i>
	HB 171		16-Feb-16	J.Jones	18-Apr-16	<i>N.S.M.O.M.O.</i>
	HB 175		16-Feb-16	J.Jones	18-Apr-16	<i>N.S.M.O.M.O.</i>
	HBL 006		16-Feb-16	J.Jones	18-Apr-16	<i>N.S.M.O.M.O.</i>
Sunningdale P.S.	HB 132	4	15-Mar-16	S.Parliament	28-April-16	<i>N.S.M.O.M.O.</i>
	HB145		15-Mar-16	S.Parliament	28-April-16	<i>N.S.M.O.M.O.</i>
	HB 072		15-Mar-16	S.Parliament	28-April-16	<i>N.S.M.O.M.O.</i>
	HB179		15-Mar-16	S.Parliament	28-April-16	<i>N.S.M.O.M.O.</i>
W.H. Morden P.S.	HB 055	6	29-Feb-16	J.Jones	18-Apr-16	<i>N.S.M.O.M.O.</i>
	HB 138		29-Feb-16	J.Jones	18-Apr-16	<i>N.S.M.O.M.O.</i>
	HBL 007		29-Feb-16	J.Jones	18-Apr-16	<i>N.S.M.O.M.O.</i>
	HBL 249 (1147)		29-Feb-16	J.Jones	18-Apr-16	<i>N.S.M.O.M.O.</i>
	HBL 250 (931)		29-Feb-16	J.Jones	18-Apr-16	<i>N.S.M.O.M.O.</i>
	HB 199		29-Feb-16	J.Jones	18-Apr-16	<i>N.S.M.O.M.O.</i>
West Oak P.S.	RM 1	9	03-Mar-16	S. Parliament	14-April-16	<i>N.S.M.O.M.O.</i>
	RM 2		03-Mar-16	S. Parliament	14-April-16	<i>N.S.M.O.M.O.</i>
	RM 3		03-Mar-16	S. Parliament	14-April-16	<i>N.S.M.O.M.O.</i>
	RM 4		03-Mar-16	S. Parliament	14-April-16	<i>N.S.M.O.M.O.</i>



PORTABLE CLASSROOM PREVENTATIVE MAINTENANCE INSPECTION NO. 97 SUMMARY

School	Portable Number	Portables on Site	PM Inspection Schedule		Proposed Round 98 Inspection Date	Comments from Round 97 Inspection
			Round 97 Inspection Date	ARCADIS Inspector		
	RM 5		03-Mar-16	S. Parliament	14-April-16	<i>N.S.M.O.M.O.</i>
	RM 6		03-Mar-16	S. Parliament	14-April-16	<i>N.S.M.O.M.O.</i>
	Work Room		03-Mar-16	S. Parliament	14-April-16	<i>N.S.M.O.M.O.</i>
	HB 107		03-Mar-16	S. Parliament	14-April-16	<i>N.S.M.O.M.O.</i>
	HB 088		03-Mar-16	S.Parliament	14-April-16	<i>N.S.M.O.M.O.</i>
White Oaks Centre for Science and Technology (North Campus)	HB 060	5	07-Mar-16	S.Parliament	04-May-16	<i>N.S.M.O.M.O.</i>
	HBL 092		07-Mar-16	S.Parliament	04-May-16	<i>N.S.M.O.M.O.</i>
	HBL 093		07-Mar-16	S.Parliament	04-May-16	<i>N.S.M.O.M.O.</i>
	HBL 094		07-Mar-16	S.Parliament	04-May-16	<i>Rear eavestrough detached.</i>
	HBL 095		07-Mar-16	S.Parliament	04-May-16	<i>Wooden skirting damaged at rear and left elevations.</i>
White Oaks School Admin. (South Campus)	HB 023	12	18-Feb-16	D.Kellyman	05-Apr-16	<i>N.S.M.O.M.O.</i>
	HB 042		18-Feb-16	D.Kellyman	05-Apr-16	<i>N.S.M.O.M.O.</i>
	HBL 016		18-Feb-16	D.Kellyman	05-Apr-16	<i>N.S.M.O.M.O.</i>
	HB 078		18-Feb-16	D.Kellyman	05-Apr-16	<i>N.S.M.O.M.O.</i>
	HB 112		18-Feb-16	D.Kellyman	05-Apr-16	<i>N.S.M.O.M.O.</i>
	HB 153		18-Feb-16	D.Kellyman	05-Apr-16	<i>N.S.M.O.M.O.</i>
	HBL 018		18-Feb-16	D.Kellyman	05-Apr-16	<i>N.S.M.O.M.O.</i>
	HB 201		18-Feb-16	D.Kellyman	05-Apr-16	<i>Missing ceiling tile observed near front door.</i>
	HB 205		18-Feb-16	D.Kellyman	05-Apr-16	<i>N.S.M.O.M.O.</i>
	HBL 017		18-Feb-16	D.Kellyman	05-Apr-16	<i>N.S.M.O.M.O.</i>
	HBL 096		18-Feb-16	D.Kellyman	05-Apr-16	<i>N.S.M.O.M.O.</i>
	HBL 097		18-Feb-16	D.Kellyman	05-Apr-16	<i>N.S.M.O.M.O.</i>
<b>Total Number of Portables</b>		<b>65</b>				

Notes:	
Scheduled inspection date subject to change due to availability of manpower and the facility.	
<b>N.S.M.O.M.O. =</b>	<b>No Suspect Mould Or Moisture Observed</b>

PORTABLE CLASSROOM PREVENTATIVE MAINTENANCE INSPECTION NO. 97 SUMMARY

School	Portable Number	Portables on Site	PM Inspection Schedule		Proposed Round 98 Inspection Date	Comments from Round 97 Inspection
			Round 97 Inspection Date	ARCADIS Inspector		

PORTABLE CLASSROOM PREVENTATIVE MAINTENANCE INSPECTION NO. 97 SUMMARY

School	Portable Number	Portables on Site	PM Inspection Schedule		Proposed Round 98 Inspection Date	Comments from Round 97 Inspection
			Round 97 Inspection Date	ARCADIS Inspector		

PORTABLE CLASSROOM PREVENTATIVE MAINTENANCE INSPECTION NO. 97 SUMMARY

School	Portable Number	Portables on Site	PM Inspection Schedule		Proposed Round 98 Inspection Date	Comments from Round 97 Inspection
			Round 97 Inspection Date	ARCADIS Inspector		
Alton Village P.S.	HBL 234	9	04-Mar-16	S. Parliament	27-April-16	<i>N.S.M.O.M.O.</i>
	HBL 235		04-Mar-16	S. Parliament	27-April-16	<i>N.S.M.O.M.O.</i>
	HBL 236		04-Mar-16	S. Parliament	27-April-16	<i>N.S.M.O.M.O.</i>
	HBL 237		04-Mar-16	S. Parliament	27-April-16	<i>Screw holes observed in metal cladding at front elevation.</i>
	HBL 238		04-Mar-16	S. Parliament	27-April-16	<i>N.S.M.O.M.O.</i>
	HBL 239		04-Mar-16	S. Parliament	27-April-16	<i>Exterior caulking degraded at front windows. Screw holes observed in metal cladding and center flashing at left elevation. Ice damming occurring at left elevation downspout.</i>
	HBL 225		04-Mar-16	S. Parliament	27-April-16	<i>Screw holes observed at front and rear elevations</i>
	HB 068		04-Mar-16	S. Parliament	27-April-16	<i>Exterior caulking missing and/or degraded at front door and first window. Eavestrough missing at rear and front elevation. Downspout detached at rear elevation.</i>
	HB 037		04-Mar-16	S. Parliament		<i>N.S.M.O.M.O.</i>
Dr. Charles Best P.S.	HB 210	2	22-Mar-16	J.Jones	21-April-16	<i>N.S.M.O.M.O.</i>
	HBL 211		22-Mar-16	J.Jones	21-April-16	<i>N.S.M.O.M.O.</i>
Florence Meares P.S.	HB 139	1	04-Mar-16	S.Parliament	27-April-16	<i>N.S.M.O.M.O.</i>
Kilbride P.S.	HB 074	1	04-Mar-16	S.Parliament	27-April-16	<i>N.S.M.O.M.O.</i>
Orchard Park P.S.	HB 040	4	05-Mar-16	S.Parliament	5-May-16	<i>N.S.M.O.M.O.</i>
	HB 147		05-Mar-16	S.Parliament	5-May-16	<i>Large quantities of rodent droppings and debris observed in ceiling space at C-3 and C-4.</i>
	HB 166		05-Mar-16	S.Parliament	5-May-16	<i>N.S.M.O.M.O.</i>
	HB 140		05-Mar-16	S.Parliament	5-May-16	<i>N.S.M.O.M.O.</i>
Pauline Johnson P.S.	HBL 222	2	03-Mar-16	D.Kellyman	25-April-16	<i>N.S.M.O.M.O.</i>
	HB 102		03-Mar-16	D.Kellyman	25-April-16	<i>N.S.M.O.M.O.</i>
Tom Thompson P.S.	HB 012	10	22-Mar-16	J.Jones	21-April-16	<i>N.S.M.O.M.O.</i>
	HB 031		22-Mar-16	J.Jones	21-April-16	<i>N.S.M.O.M.O.</i>
	HB 053		22-Mar-16	J.Jones	21-April-16	<i>N.S.M.O.M.O.</i>
	HB 098		22-Mar-16	J.Jones	21-April-16	<i>N.S.M.O.M.O.</i>
	HB 105		22-Mar-16	J.Jones	21-April-16	<i>N.S.M.O.M.O.</i>
	HB 124		22-Mar-16	J.Jones	21-April-16	<i>N.S.M.O.M.O.</i>
	HB 141		22-Mar-16	J.Jones	21-April-16	<i>N.S.M.O.M.O.</i>
	HB 148		22-Mar-16	J.Jones	21-April-16	<i>N.S.M.O.M.O.</i>
	HB 169		22-Mar-16	J.Jones	21-April-16	<i>N.S.M.O.M.O.</i>
	HB 206		22-Mar-16	J.Jones	21-April-16	<i>N.S.M.O.M.O.</i>
<b>Total Number of Portables</b>		<b>29</b>				

Notes:	
Scheduled inspection date subject to change due to availability of manpower and the facility.	
N.S.M.O.M.O. =	No Suspect Mould Or Moisture Observed